

# Quad-Core Intel® Xeon® Processor 5300 Series

Specification Update

---

*July 2009*

Order Number: 315338-018

**Notice:** The Quad-Core Intel® Xeon® Processor 5300 Series may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. Intel products are not intended for use in medical, life saving, life sustaining, critical control or safety systems, or in nuclear facility applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. See [http://www.intel.com/products/processor\\_number](http://www.intel.com/products/processor_number) for details.

The Quad-Core Intel® Xeon® Processor 5300 Series may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature may be obtained by calling 1-800-548-4725 or by visiting Intel's website at <http://www.intel.com>.

Intel, Intel Core, Celeron, Pentium, Intel Xeon, Intel SpeedStep and the Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

\*Other names and brands may be claimed as the property of others.

Copyright ©2006- 2009, Intel Corporation. All Rights Reserved.



## Contents

---

<b>Revision History</b> .....	4
<b>Preface</b> .....	5
<b>Summary Tables of Changes</b> .....	7
<b>Identification Information</b> .....	16
<b>Errata</b> .....	18
<b>Specification Changes</b> .....	52
<b>Specification Clarifications</b> .....	53
<b>Documentation Changes</b> .....	54



# Revision History

---

Revision	Version	Description	Date
-001	1.0	Initial Release	November 2006
-002	1.0	Deleted AJ83 and AJ87. Added AJ86 through AJ89.	December 2006
-003	1.0	Updated AJ67. Added AJ90 through AJ93.	January 2006
-004	1.0	Updated AJ46. Added AJ94 through AJ100. Deleted AJ82 and AJ84.	March 2007
-005	1.0	Added AJ101 through AJ103.	April 2007
-006	1.0	Added AJ104 and Specification Clarification AJ1	April 2007 Out of Cycle
-007	1.0	Updated AJ14, AJ25 and AJ26	May 2007
-008	1.0	Added AJ105 and AJ106	June 2007
-009	1.0	Added AJ107 and AJ108	July 2007
-010	1.0	Added AJ109 through AJ111 Added G-0 Information	August 2007
-011	1.0	Added AJ112 through AJ117, Updated AJ108	October 2007
-012	1.0	Added AJ118	November 2007
-013	1.0	Added AJ119. Updated AJ8 Added L5318 Information	December 2007
-014	1.0	Added AJ120	January 2008
-015	1.0	Added AJ121 Updated AJ10 and AJ51	February 2008
-016	1.0	Added AJ122 through AJ123	April 2008
-017	1.0	Update errata AJ56 and AJ61	March 2009
-018	1.0	Added errata AJ124 and AJ125 Added Specification Change AJ1	July 2009



# Preface

This document is an update to the specifications contained in the [Affected Documents](#) table below. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. Information types defined in [Nomenclature](#) are consolidated into the specification update and are no longer published in other documents. This document may also contain information that was not previously published.

## Affected Documents

Document Title	Document Number/ Location
<i>Quad-Core Intel® Xeon® Processor 5300 Series Datasheet</i>	315569

**Note:** Contact your Intel representative for the latest revision and document number of this document.

## Related Documents


Document Title	Document Number/ Location
<i>AP-485, Intel® Processor Identification and the CPUID Instruction</i>	241618
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 1: Basic Architecture</i> <i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2A: Instruction Set Reference Manual A-M</i> <i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 2B: Instruction Set Reference Manual N-Z</i> <i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide</i> <i>Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3B: System Programming Guide</i> <i>Intel® 64 and IA-32 Intel Architecture Optimization Reference Manual</i>	<a href="http://www.intel.com/products/processor/manuals/index.htm">http://www.intel.com/products/processor/manuals/index.htm</a>
<i>Intel® 64 and IA-32 Architectures Software Developer's Manual Documentation Changes</i>	<a href="http://www.intel.com/design/processor/specupdt/252046.htm">http://www.intel.com/design/processor/specupdt/252046.htm</a>
<i>Intel® Virtualization Technology Specification for the IA-32 Intel® Architecture</i>	C97063

**Note:** Contact your Intel representative for the latest revision and document number of this document.

## Nomenclature

**Errata** are design defects or errors. These may cause the Quad-Core Intel® Xeon® Processor 5300 Series behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

**S-Spec Number** is a five-digit code used to identify products. Products are differentiated by their unique characteristics, e.g., core speed, L2 cache size, package type, etc. as described in the processor identification information table. Read all notes



associated with each S-Spec number.

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

**Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

**Documentation Changes** include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.

**Note:**

Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).



# Summary Tables of Changes

---

The following tables indicate the errata, specification changes, specification clarifications, or documentation changes which apply to the Quad-Core Intel® Xeon® Processor 5300 Series product. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. These tables use the following notations:

## Codes Used in Summary Tables

### Stepping

X:	Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
(No mark) or (Blank box):	This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

### Page

(Page):	Page location of item in this document.
---------	---

### Status

Doc:	Document change or update will be implemented.
Plan Fix:	This erratum may be fixed in a future stepping of the product.
Fixed:	This erratum has been previously fixed.
No Fix:	There are no plans to fix this erratum.

### Row

Each Specification Update item is prefixed with a capital letter to distinguish the product. The key below details the letters that are used in Intel's microprocessor Specification Updates:

A =	Dual-Core Intel® Xeon® processor 7000 sequence
C =	Intel® Celeron® processor
D =	Dual-Core Intel® Xeon® processor 2.80 GHz
E =	Intel® Pentium® III processor
F =	Intel® Pentium® processor Extreme Edition and Intel® Pentium® D processor
I =	Dual-Core Intel® Xeon® processor 5000 series
J =	64-bit Intel® Xeon® processor MP with 1MB L2 cache



- K = Mobile Intel® Pentium® III processor
- L = Intel® Celeron® D processor
- M = Mobile Intel® Celeron® processor
- N = Intel® Pentium® 4 processor
- O = Intel® Xeon® processor MP
- P = Intel® Xeon® processor
- Q = Mobile Intel® Pentium® 4 processor supporting Hyper-Threading technology on 90-nm process technology
- R = Intel® Pentium® 4 processor on 90 nm process
- S = 64-bit Intel® Xeon® processor with 800 MHz system bus (1 MB and 2 MB L2 cache versions)
- T = Mobile Intel® Pentium® 4 processor-M
- U = 64-bit Intel® Xeon® processor MP with up to 8MB L3 cache
- V = Mobile Intel® Celeron® processor on .13 micron process in Micro-FCPGA package
- W = Intel® Celeron® M processor
- X = Intel® Pentium® M processor on 90nm process with 2-MB L2 cache and Intel® processor A100 and A110 with 512-KB L2 cache
- Y = Intel® Pentium® M processor
- Z = Mobile Intel® Pentium® 4 processor with 533 MHz system bus
- AA = Intel® Pentium® D processor 900 sequence and Intel® Pentium® processor Extreme Edition 955, 965
- AB = Intel® Pentium® 4 processor 6x1 sequence
- AC = Intel(R) Celeron(R) processor in 478 pin package
- AD = Intel(R) Celeron(R) D processor on 65nm\_process
- AE = Intel® Core™ Duo processor and Intel® Core™ Solo processor on 65nm process
- AF = Dual-Core Intel® Xeon® processor LV
- AG = Dual-Core Intel® Xeon® processor 5100 series
- AH = Intel® Core™2 Duo/Solo Processor for Intel® Centrino® Duo Processor Technology
- AI = Intel® Core™2 Extreme processor X6800? and Intel® Core™2 Duo desktop processor E6000 and E4000? sequence
- AJ = Quad-Core Intel® Xeon® processor 5300 series



- AK = Intel® Core™2 Extreme quad-core processor QX6000? sequence and Intel® Core™2 Quad processor Q6000 sequence
- AL = Dual-Core Intel® Xeon® processor 7100 series
- AM = Intel® Celeron® processor 400 sequence
- AN = Intel® Pentium® dual-core processor
- AO = Quad-Core Intel® Xeon® processor 3200 series
- AP = Dual-Core Intel® Xeon® processor 3000 series
- AQ = Intel® Pentium® dual-core desktop processor E2000 sequence
- AR = Intel® Celeron processor 500 series
- AS = Intel® Xeon® processor 7200, 7300 series
- AT = Intel® Celeron® processor 200 series
- AV = Intel® Core™2 Extreme processor QX9000 series and Intel® Core™2 Quad processor Q9000 series
- AX = Quad-Core Intel® Xeon® processor 5400 series
- AY = Dual-Core Intel® Xeon® processor 5200 series
- AZ = Intel® Core™2 Duo Processor and Intel® Core™2 Extreme Processor on 45-nm Process
- AAA= Quad-Core Intel® Xeon® processor 3300 series
- AAB= Dual-Core Intel® Xeon® E3110 Processor
- AAC= Intel® Celeron® dual-core processor E1000 series
- AAD= Intel® Core™2 Extreme Processor QX9775
- AAE= Intel® Atom™ processor Z5xx series
- AAF= Intel® Atom™ processor 200 series



## Errata (Sheet 1 of 6)

Number	Steppings		Status	ERRATA
	B-3	G-0		
AJ1	X	X	No Fix	Writing the Local Vector Table (LVT) when an Interrupt is Pending May Cause an Unexpected Interrupt
AJ2	X	X	No Fix	LOCK# Asserted During a Special Cycle Shutdown Transaction May Unexpectedly De-assert
AJ3	X	X	No Fix	Address Reported by Machine-Check Architecture (MCA) on Single-bit L2 ECC Errors May be Incorrect
AJ4	X	X	No Fix	VERW/VERR/LSL/LAR Instructions May Unexpectedly Update the Last Exception Record (LER) MSR
AJ5	X	X	No Fix	DR3 Address Match on MOVD/MOVQ/MOVRTQ Memory Store Instruction May Incorrectly Increment Performance Monitoring Count for Saturating SIMD Instructions Retired (Event CFH)
AJ6	X		Plan Fix	SYSRET May Incorrectly Clear RF (Resume Flag) in the RFLAGS Register
AJ7	X	X	No Fix	General Protection Fault (#GP) for Instructions Greater than 15 Bytes May be Preempted
AJ8	X	X	No Fix	Pending x87 FPU Exceptions (#MF) Following STI May Be Serviced Before Higher Priority Interrupts
AJ9	X	X	No Fix	The Processor May Report a #TS Instead of a #GP Fault
AJ10	X	X	No Fix	Code Segment Limit/Canonical Faults on RSM May be Serviced before Higher Priority Interrupts/Exceptions
AJ11	X	X	No Fix	A Write to an APIC Register Sometimes May Appear to Have Not Occurred
AJ12	X	X	No Fix	Programming the Digital Thermal Sensor (DTS) Threshold May Cause Unexpected Thermal Interrupts
AJ13	X	X	No Fix	Count Value for Performance-Monitoring Counter PMH_PAGE_WALK May be Incorrect
AJ14	X	X	No Fix	LER MSRs May be Incorrectly Updated
AJ15	X	X	No Fix	Performance Monitoring Events for Retired Instructions (C0H) May Not Be Accurate
AJ16	X	X	No Fix	Performance Monitoring Event For Number Of Reference Cycles When The Processor Is Not Halted (3CH) Does Not Count According To The Specification
AJ17	X	X	No Fix	Using 2M/4M Pages When A20M# Is Asserted May Result in Incorrect Address Translations
AJ18	X	X	No Fix	Writing Shared Unaligned Data that Crosses a Cache Line without Proper Semaphores or Barriers May Expose a Memory Ordering Issue
AJ19	X	X	No Fix	Code Segment limit violation may occur on 4-Gbyte limit check
AJ20	X		Plan Fix	FP Inexact-Result Exception Flag May Not Be Set
AJ21	X		Plan Fix	Global Pages in the Data Translation Look-Aside Buffer (DTLB) May Not Be Flushed by RSM instruction before Restoring the Architectural State from SMRAM
AJ22	X		Plan Fix	Sequential Code Fetch to Non-canonical Address May have Non-deterministic Results



## Errata (Sheet 2 of 6)

Number	Steppings		Status	ERRATA
	B-3	G-0		
AJ23	X		Plan Fix	VMCALL to Activate Dual-monitor Treatment of SMMs and SMM Ignores Reserved Bit settings in VM-exit Control Field
AJ24	X	X	No Fix	The PECC Controller Resets to the Idle State
AJ25	X	X	No Fix	Some Bus Performance Monitoring Events May Not Count Local Events under Certain Conditions
AJ26	X	X	No Fix	Premature Execution of a Load Operation Prior to Exception Handler Invocation
AJ27	X	X	No Fix	General Protection (#GP) Fault May Not Be Signaled on Data Segment Limit Violation above 4-G Limit
AJ28	X	X	No Fix	EIP May be Incorrect after Shutdown in IA-32e Mode
AJ29	X	X	No Fix	#GP Fault is Not Generated on Writing IA32_MISC_ENABLE [34] When Execute Disable Bit is Not Supported
AJ30	X		Plan Fix	(E)CX May Get Incorrectly Updated When Performing Fast String REP MOVSB or Fast String REP STOSB With Large Data Structures
AJ31	X		Plan Fix	Performance Monitoring Events for Retired Loads (CBH) and Instructions Retired (COH) May Not Be Accurate
AJ32	X	X	No Fix	Upper 32 bits of 'From' Address Reported through BTMs or BTSs May be Incorrect
AJ33	X		Plan Fix	Unsynchronized Cross-Modifying Code Operations Can Cause Unexpected Instruction Execution Results
AJ34	X	X	No Fix	MSRs Actual Frequency Clock Count (IA32_APERF) or Maximum Frequency Clock Count (IA32_MPERF) May Contain Incorrect Data after a Machine Check Exception (MCE)
AJ35	X	X	No Fix	Incorrect Address Computed For Last Byte of FXSAVE/FXRSTOR Image Leads to Partial Memory Update
AJ36	X	X	No Fix	Split Locked Stores May not Trigger the Monitoring Hardware
AJ37	X		Plan Fix	REP CMPS/SCAS Operations May Terminate Early in 64-bit Mode when RCX >= 0X10000000
AJ38	X		Plan Fix	FXSAVE/FXRSTOR Instructions which Store to the End of the Segment and Cause a Wrap to a Misaligned Base Address (Alignment <= 0x10h) May Cause FPU Instruction or Operand Pointer Corruption
AJ39	X		Plan Fix	Cache Data Access Request from One Core Hitting a Modified Line in the L1 Data Cache of the Other Core May Cause Unpredictable System Behavior
AJ40	X		Plan Fix	PREFETCHH Instruction Execution under Some Conditions May Lead to Processor Livelock
AJ41	X		Plan Fix	PREFETCHH Instructions May Not be Executed when Alignment Check (AC) is Enabled
AJ42	X		Plan Fix	Upper 32 Bits of the FPU Data (Operand) Pointer in the FXSAVE Memory Image May Be Unexpectedly All 1's after FXSAVE
AJ43	X		Plan Fix	Concurrent Multi-processor Writes to Non-dirty Page May Result in Unpredictable Behavior
AJ44	X		Plan Fix	Performance Monitor IDLE_DURING_DIV (18h) Count May Not be Accurate
AJ45	X	X	No Fix	Values for LBR/BTS/BTM will be Incorrect after an Exit from SMM
AJ46	X	X	No Fix	ShutdownCondition May Disable Non-Bootstrap Processors



## Errata (Sheet 3 of 6)

Number	Steppings		Status	ERRATA
	B-3	G-0		
AJ47	X		Plan Fix	SYSCALL Immediately after Changing EFLAGS.TF May Not Behave According to the New EFLAGS.TF
AJ48	X		Plan Fix	Debug Register May Contain Incorrect Information on a MOVSS or POPSS Instruction Followed by SYSRET
AJ49	X	X	No Fix	VM Bit is Cleared on Second Fault Handled by Task Switch from Virtual-8086 (VM86)
AJ50	X		Plan Fix	IA32_FMASK is Reset during an INIT
AJ51	X	X	No Fix	Code Breakpoint May Be Taken after POP SS Instruction if it is followed by an Instruction that Faults
AJ52	X	X	No Fix	Last Branch Records (LBR) Updates May be Incorrect after a Task Switch
AJ53	X	X	No Fix	IO_SMI Indication in SMRAM State Save Area May Be Set Incorrectly
AJ54	X	X	No Fix	INIT Does Not Clear Global Entries in the TLB
AJ55	X		Plan Fix	Using Memory Type Aliasing with Memory Types WB/WT May Lead to Unpredictable Behavior
AJ56	X		No Fix	Update of Read/Write (R/W) or User/Supervisor (U/S) or Present (P) Bits without TLB Shutdown May Cause Unexpected Processor Behavior
AJ57	X		No Fix	BTS Message May Be Lost When the STPCLK# Signal is Active.
AJ58	X	X	No Fix	CMPSB, LODSB, or SCASB in 64-bit Mode with Count Greater or Equal to 2 <sup>48</sup> May Terminate Early
AJ59	X	X	No Fix	REP MOVs/STOS Executing with Fast Strings Enabled and Crossing Page Boundaries with Inconsistent Memory Types may use an Incorrect Data Size or Lead to Memory-Ordering Violations
AJ60	X	X	No Fix	MOV To/From Debug Registers Causes Debug Exception
AJ61	X	X	No Fix	EFLAGS Discrepancy on Page Faults after a Translation Change
AJ62	X	X	No Fix	LBR, BTS, BTM May Report a Wrong Address when an Exception/Interrupt Occurs in 64-bit Mode
AJ63	X	X	No Fix	Returning to Real Mode from SMM with EFLAGS.VM Set May Result in Unpredictable System Behavior
AJ64	X	X	No Fix	A Thermal Interrupt is Not Generated when the Current Temperature is Invalid
AJ65	X	X	No Fix	Performance Monitoring Event FP_ASSIST May Not be Accurate
AJ66	X		Plan Fix	CPL-Qualified BTS May Report Incorrect Branch-From Instruction Record From Address
AJ67	X		Plan Fix	PEBS Does Not Always Differentiate Between CPL-Qualified Events
AJ68	X	X	No Fix	PMI May be Delayed to Next PEBS Event
AJ69	X		Plan Fix	PEBS Buffer Overflow Status Will Not be Indicated Unless IA32_DEBUGCTL[12] is Set
AJ70	X	X	No Fix	The BS Flag in DR6 May be Set for Non-Single-Step #DB Exception
AJ71	X	X	No Fix	An Asynchronous MCE During a Far Transfer May Corrupt ESP
AJ72	X		Plan Fix	In Single-Stepping on Branches Mode, the BS Bit in the Pending-Debug-Exceptions Field of the Guest State Area will be Incorrectly Set by VM-Exit on a MOV to CR8 Instruction



## Errata (Sheet 4 of 6)

Number	Steppings		Status	ERRATA
	B-3	G-0		
AJ73	X	X	No Fix	B0-B3 Bits in DR6 May Not be Properly Cleared After Code Breakpoint
AJ74	X	X	No Fix	Performance Monitoring Events for L1 and L2 Miss May Not be Accurate
AJ75	X	X	No Fix	BTM/BTS Branch-From Instruction Address May be Incorrect for Software Interrupts
AJ76	X		Plan Fix	VMLAUNCH/VMRESUME May Not Fail when VMCS is Programmed to Cause VM Exit to Return to a Different Mode
AJ77	X	X	No Fix	Performance Monitor SSE Retired Instructions May Return Incorrect Values
AJ78	X		Plan Fix	REP Store Instructions in a Specific Situation may cause the Processor to Hang
AJ79	X	X	No Fix	A MOV Instruction from CR8 Register with 16 Bit Operand Size Will Leave Bits 63:16 of the Destination Register Unmodified
AJ80	X	X	No Fix	Store to WT Memory Data May be Seen in Wrong Order by Two Subsequent Loads
AJ81	X	X	No Fix	IRET under Certain Conditions May Cause an Unexpected Alignment Check Exception
AJ82				Removed - Not Applicable
AJ83	X	X	No Fix	Non-Temporal Data Store May be Observed in Wrong Program Order
AJ84				Removed - Not Applicable
AJ85	X		Plan Fix	CPUID Reports Architectural Performance Monitoring Version 2 is Supported, When Only Version 1 Capabilities are Available
AJ86	X	X	No Fix	Unaligned Accesses to Paging Structures May Cause the Processor to Hang
AJ87	X	X	No Fix	Microcode Updates Performed During VMX Non-root Operation Could Result in Unexpected Behavior
AJ88	X	X	No Fix	INVLPG Operation for Large (2M/4M) Pages May be Incomplete under Certain Conditions
AJ89	X	X	No Fix	Page Access Bit May be Set Prior to Signaling a Code Segment Limit Fault
AJ90	X		Plan Fix	Update of Attribute Bits on Page Directories without Immediate TLB Shutdown May Cause Unexpected Processor Behavior
AJ91	X		Plan Fix	Invalid Instructions May Lead to Unexpected Behavior
AJ92	X	X	No Fix	EFLAGS, CR0, CR4 and the EXF4 Signal May be Incorrect after Shutdown
AJ93	X		Plan Fix	Performance Monitoring Counter MACRO_INSTS.DECODED May Not Count Some Decoded Instructions
AJ94	X		Plan Fix	The Stack Size May be Incorrect as a Result of VIP/VIF Check on SYSEXIT and SYSRET
AJ95	X	X	No Fix	Performance Monitoring Event SIMD_UOP_TYPE_EXEC.MUL is Counted Incorrectly for PMULUDQ Instruction
AJ96	X	X	No Fix	Storage of PEBS Record Delayed Following Execution of MOV SS or STI



## Errata (Sheet 5 of 6)

Number	Steppings		Status	ERRATA
	B-3	G-0		
AJ97	X		Plan Fix	Processor On Die Termination of BR1# and LOCK# Signals are Incorrect
AJ98	X	X	No Fix	Store Ordering May be Incorrect between WC and WP Memory Types
AJ99	X	X	No Fix	Updating Code Page Directory Attributes without TLB Invalidation May Result in Improper Handling of Code #PF
AJ100	X	X	No Fix	Performance Monitoring Event CPU_CLK_UNHALTED.REF May Not Count Clock Cycles According to the Processors Operating Frequency
AJ101	X		Plan Fix	Performance Monitoring Event BR_INST_RETIRED May Count CPUID Instructions as Branches
AJ102	X	X	No Fix	Performance Monitoring Event MISALIGN_MEM_REF May Over Count
AJ103	X	X	No Fix	A REP STOS/MOVS to a MONITOR/MWAIT Address Range May Prevent Triggering of the Monitoring Hardware
AJ104	X		Plan Fix	False Level One Data Cache Parity Machine-Check Exceptions May be Signaled
AJ105	X	X	No Fix	A Memory Access May Get a Wrong Memory Type Following a #GP due to WRMSR to an MTRR Mask
AJ106	X	X	No Fix	PMI While LBR Freeze Enabled May Result in Old/Out-of-date LBR Information
AJ107	X		Plan Fix	Overlap of an Intel® VT APIC Access Page in a Guest with the DS Save Area May Lead to Unpredictable Behavior
AJ108	X	X	No Fix	Dual-Processor Incompatibility Between B-step and G-step
AJ109	X	X	No Fix	VTPR Write Access During Event Delivery May Cause an APIC-Access VM Exit
AJ110		X	No Fix	BIST Failure After Reset
AJ111	X	X	No Fix	Performance Monitoring Event FP_MMX_TRANS_TO_MMX May Not Count Some Transitions
AJ112	X	X	No Fix	Instruction Fetch May Cause a Livelock During Snoops of the L1 Data Cache
AJ113	X	X	No Fix	Use of Memory Aliasing with Inconsistent Memory Type may Cause a System Hang or a Machine Check Exception
AJ114	X	X	No Fix	A WB Store Following a REP STOS/MOVS or FXSAVE May Lead to Memory-Ordering Violations
AJ115	X	X	No Fix	VM Exit with Exit Reason "TPR Below Threshold" Can Cause the Blocking by MOV/POP SS and Blocking by STI Bits to be Cleared in the Guest Interruptibility-State Field
AJ116	X	X	No Fix	Using Memory Type Aliasing with cacheable and WC Memory Types May Lead to Memory Ordering Violations
AJ117	X	X	No Fix	VM Exit due to Virtual APIC-Access May Clear RF
AJ118	X	X	No Fix	RSM Instruction Execution under Certain Conditions May Cause Processor Hang or Unexpected Instruction Execution Results
AJ119	X		Fixed	NMIs May Not Be Blocked by a VM-Entry Failure
AJ120	X	X	No Fix	Benign Exception after a Double Fault May Not Cause a Triple Fault Shutdown
AJ121	X	X	No Fix	IA32_MC1_STATUS MSR Bit[60] Does Not Reflect Machine Check Error Reporting Enable Correctly
AJ122	X	X	No Fix	A VM Exit Due to a Fault While Delivering a Software Interrupt May Save Incorrect Data into the VMCS



## Errata (Sheet 6 of 6)

Number	Steppings		Status	ERRATA
	B-3	G-0		
AJ123	X	X	No Fix	A VM Exit Occuring in IA-32e Mode May Not Produce a VMX Abort When Expected
AJ124	X	X	No Fix	Not-Present Page Faults May Set the RSVD Flag in the Error Code
AJ125	X	X	No Fix	VM Exits Due to "NMI-Window Exiting" May Be Delayed by One Instruction

## Specification Changes

Number	SPECIFICATION CHANGES
AJ1	Implementation of System Management Range Registers

## Specification Clarifications

No.	SPECIFICATION CLARIFICATIONS
AJ1	Clarification of TRANSLATION LOOKASIDE BUFFERS (TLBS) Invalidation

## Documentation Changes

No.	DOCUMENTATION CHANGES
	None for this revision of this specification update.



# Identification Information

## Component Identification via Programming Interface

The Quad-Core Intel® Xeon® Processor 5300 Series stepping can be identified by the following register contents:

Family <sup>1</sup>	Model <sup>2</sup>
0110	1111


**Note:**

1. The Family corresponds to bits [11:8] of the EDX register after RESET, bits [11:8] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the generation field of the Device ID register accessible through Boundary Scan.
2. The Model corresponds to bits [7:4] of the EDX register after RESET, bits [7:4] of the EAX register after the CPUID instruction is executed with a 1 in the EAX register, and the model field of the Device ID register accessible through Boundary Scan.

Cache and TLB descriptor parameters are provided in the EAX, EBX, ECX and EDX registers after the CPUID instruction is executed with a 2 in the EAX register.

## Component Marking Information

Figure 1. Processor Top-side Markings (Example)



The Quad-Core Intel® Xeon® Processor 5300 Series stepping can be identified by the following component markings:



**Table 1. Quad-Core Intel® Xeon® Processor 5300 Series Identification Information**

S-Spec	Processor Number	Core Stepping	CPUID	Core Freq (GHz)	Data Bus Freq (MHz)	L2 Cache Size	Processor Package Revision	Notes
SL9YM	X5355	B-3	06F7	2.66	1333	8M	01	1,2 3,6,7,8,9
SLAC4	X5355	B-3	06F7	2.66	1333	8M	01	1,2 3,6,7,8,9
SL9YL	E5345	B-3	06F7	2.33	1333	8M	01	1,2 4,6,7,8,9
SLAC5	E5345	B-3	06F7	2.33	1333	8M	01	1,2 4,6,7,8,9
SL9YK	E5335	B-3	06F7	2	1333	8M	01	1,2 4,6,7,8,9
SLAC7	E5335	B-3	06F7	2	1333	8M	01	1,2 4,6,7,8,9
SL9MV	E5320	B-3	06F7	1.86	1066	8M	01	1,2 4,6,7,8,9
SLAC8	E5320	B-3	06F7	1.86	1066	8M	01	1,2 4,6,7,8,9
SL9XR	E5310	B-3	06F7	1.60	1066	8M	01	1,2 4,7,8,9
SLACB	E5310	B-3	06F7	1.60	1066	8M	01	1,2 4,7,8,9
SLA4Q	L5320	B-3	06F7	1.86	1066	8M	01	1,2 5,7,8,9
SLAC9	L5320	B-3	06F7	1.86	1066	8M	01	1,2 5,7,8,9
SL9MT	L5310	B-3	06F7	1.60	1066	8M	01	1,2 5,7,8,9
SLACA	L5310	B-3	06F7	1.60	1066	8M	01	1,2 5,7,8,9
SLAEG	X5355	G-0	06FB	2.66	1333	8M	01	1,2 3,6,7,8,9
SLAEJ	E5345	G-0	06FB	2.33	1333	8M	01	1,2 4,6,7,8,9
SLAEK	E5335	G-0	06FB	2.00	1333	8M	01	1,2 4,6,7,8,9
SLAEL	E5320	G-0	06FB	1.86	1066	8M	01	1,2 4,6,7,8,9
SLAEM	E5310	G-0	06FB	1.60	1066	8M	01	1,2 4,7,8,9
SLAEP	L5320	G-0	06FB	1.86	1066	8M	01	1,2 5,7,8,9
SLAEQ	L5310	G-0	06FB	1.60	1066	8M	01	1,2 5,7,8,9

**Notes:**

1. Quad-Core Intel® Xeon® Processor 5300 Series supports a Land Grid Array package with 771 lands in a 37.55 x 37.55 mm FC-LGA6 package
2. Refer to the Quad-Core Intel® Xeon® Processor 5300 Series *Datasheet* for the VID values for these processors.
3. This is a Quad-Core Intel® Xeon® Processor 5300 Series with a 120W TDP (Thermal Design Power)
4. This is a Quad-Core Intel® Xeon® Processor 5300 Series with a 80W TDP (Thermal Design Power)
5. This is a Quad-Core Intel® Xeon® Processor 5300 Series with a 50W TDP (Thermal Design Power)
6. These parts are enabled for Enhanced Intel SpeedStep® Technology (EIST).
7. These parts are enabled for Enhanced Halt State (C1E).
8. These parts have Execute Disable bit functionality.
9. These parts have Intel(R) Virtualization Technology (VT) enabled.
10. This is a Quad-Core Intel® Xeon® Processor 5300 Series with a 40W TDP (Thermal Design Power)



# Errata

---

## **AJ1. Writing the Local Vector Table (LVT) when an Interrupt is Pending May Cause an Unexpected Interrupt**

**Problem:** If a local interrupt is pending when the LVT entry is written, an interrupt may be taken on the new interrupt vector even if the mask bit is set.

**Implication:** An interrupt may immediately be generated with the new vector when a LVT entry is written, even if the new LVT entry has the mask bit set. If there is no Interrupt Service Routine (ISR) set up for that vector the system will GP fault. If the ISR does not do an End of Interrupt (EOI) the bit for the vector will be left set in the in-service register and mask all interrupts at the same or lower priority.

**Workaround:** Any vector programmed into an LVT entry must have an ISR associated with it, even if that vector was programmed as masked. This ISR routine must do an EOI to clear any unexpected interrupts that may occur. The ISR associated with the spurious vector does not generate an EOI, therefore the spurious vector should not be used when writing the LVT.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## **AJ2. LOCK# Asserted During a Special Cycle Shutdown Transaction May Unexpectedly De-assert**

**Problem:** During a processor shutdown transaction, when LOCK# is asserted and if a DEFER# is received during a snoop phase and the Locked transaction is pipelined on the front side bus (FSB), LOCK# may unexpectedly de-assert.

**Implication:** When this erratum occurs, the system may hang during shutdown. Intel has not observed this erratum with any commercially available systems or software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## **AJ3. Address Reported by Machine-Check Architecture (MCA) on Single-bit L2 ECC Errors May be Incorrect**

**Problem:** When correctable Single-bit ECC errors occur in the L2 cache, the address is logged in the MCA address register (MCI\_ADDR). Under some scenarios, the address reported may be incorrect.

**Implication:** Software should not rely on the value reported in MCI\_ADDR, for Single-bit L2 ECC errors.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

## **AJ4. VERW/VERR/LSL/LAR Instructions May Unexpectedly Update the Last Exception Record (LER) MSR**

**Problem:** The LER MSR may be unexpectedly updated, if the resultant value of the Zero Flag (ZF) is zero after executing the following instructions

- 1) VERR (ZF=0 indicates unsuccessful segment read verification)
- 2) VERW (ZF=0 indicates unsuccessful segment write verification)
- 3) LAR (ZF=0 indicates unsuccessful access rights load)
- 4) LSL (ZF=0 indicates unsuccessful segment limit load)



**Implication:** The value of the LER MSR may be inaccurate if VERW/VERR/LSL/LAR instructions are executed after the occurrence of an exception.

**Workaround:** Software exception handlers that rely on the LER MSR value should read the LER MSR before executing VERW/VERR/LSL/LAR instructions.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ5. DR3 Address Match on MOVD/MOVQ/MOVNTQ Memory Store Instruction May Incorrectly Increment Performance Monitoring Count for Saturating SIMD Instructions Retired (Event CFH)**

**Problem:** Performance monitoring for Event CFH normally increments on saturating SIMD instruction retired. Regardless of DR7 programming, if the linear address of a retiring memory store MOVD/MOVQ/MOVNTQ instruction executed matches the address in DR3, the CFH counter may be incorrectly incremented.

**Implication:** The value observed for performance monitoring count for saturating SIMD instructions retired may be too high. The size of the error is dependent on the number of occurrences of the conditions described above, while the counter is active.

**Workaround:** None Identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ6. SYSRET May Incorrectly Clear RF (Resume Flag) in the RFLAGS Register**

**Problem:** In normal operation, SYSRET will restore the value of RFLAGS from R11 (the value previously saved upon execution of the SYSCALL instruction). Due to this erratum, the RFLAGS.RF bit will be unconditionally cleared after execution of the SYSRET instruction.

**Implication:** The SYSRET instruction can not be used if the RF flag needs to be set after returning from a system call. Intel has not observed this erratum with any commercially available software.

**Workaround:** Use the IRET instruction to return from a system call, if RF flag has to be set after the return.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ7. General Protection Fault (#GP) for Instructions Greater than 15 Bytes May be Preempted**

**Problem:** When the processor encounters an instruction that is greater than 15 bytes in length, a #GP is signaled when the instruction is decoded. Under some circumstances, the #GP fault may be preempted by another lower priority fault (e.g. Page Fault (#PF)). However, if the preempting lower priority faults are resolved by the operating system and the instruction retried, a #GP fault will occur.

**Implication:** Software may observe a lower-priority fault occurring before or in lieu of a #GP fault. Instructions of greater than 15 bytes in length can only occur if redundant prefixes are placed before the instruction.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ8. Pending x87 FPU Exceptions (#MF) Following STI May Be Serviced Before Higher Priority Interrupts**

**Problem:** Interrupts that are pending prior to the execution of the STI (Set Interrupt Flag) instruction are serviced immediately after the STI instruction is executed. Because of this erratum, if following STI, an instruction that triggers a #MF is executed while STPCLK#, Enhanced Intel SpeedStep® Technology transitions or Thermal Monitor 1 events occur, the pending #MF may be serviced before higher priority interrupts.

**Implication:** Software may observe #MF being serviced before higher priority interrupts.



Workaround: None Identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

### **AJ9. The Processor May Report a #TS Instead of a #GP Fault**

**Problem:** A jump to a busy TSS (Task-State Segment) may cause a #TS (invalid TSS exception) instead of a #GP fault (general protection exception).

**Implication:** Operation systems that access a busy TSS may get invalid TSS fault instead of a #GP fault. Intel has not observed this erratum with any commercially available software.

Workaround: None Identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

### **AJ10. Code Segment Limit/Canonical Faults on RSM May be Serviced before Higher Priority Interrupts/Exceptions and May Push the Wrong Address Onto the Stack**

**Problem:** Normally, when the processor encounters a Segment Limit or Canonical Fault due to code execution, a #GP (General Protection Exception) fault is generated after all higher priority Interrupts and exceptions are serviced. Due to this erratum, if RSM (Resume from System Management Mode) returns to execution flow that results in a Code Segment Limit or Canonical Fault, the #GP fault may be serviced before a higher priority Interrupt or Exception (e.g. NMI (Non-Maskable Interrupt), Debug break(#DB), Machine Check (#MC), etc.). If the RSM attempts to return to a non-canonical address, the address pushed onto the stack for this #GP fault may not match the non-canonical address that caused the fault.

**Implication:** Operating systems may observe a #GP fault being serviced before higher priority Interrupts and Exceptions. Intel has not observed this erratum on any commercially available software.

Workaround: None Identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

### **AJ11. A Write to an APIC Register Sometimes May Appear to Have Not Occurred**

**Problem:** With respect to the retirement of instructions, stores to the uncacheable memory-based APIC register space are handled in a non-synchronized way. For example if an instruction that masks the interrupt flag, e.g. CLI, is executed soon after an uncacheable write to the Task Priority Register (TPR) that lowers the APIC priority, the interrupt masking operation may take effect before the actual priority has been lowered. This may cause interrupts whose priority is lower than the initial TPR, but higher than the final TPR, to not be serviced until the interrupt enabled flag is finally set, i.e. by STI instruction. Interrupts will remain pending and are not lost.

**Implication:** In this example the processor may allow interrupts to be accepted but may delay their service.

**Workaround:** This non-synchronization can be avoided by issuing an APIC register read after the APIC register write. This will force the store to the APIC register before any subsequent instructions are executed. No commercial operating system is known to be impacted by this erratum.

Status: For the steppings affected, see the *Summary Tables of Changes*.

### **AJ12. Programming the Digital Thermal Sensor (DTS) Threshold May Cause Unexpected Thermal Interrupts**

**Problem:** Software can enable DTS thermal interrupts by programming the thermal threshold and setting the respective thermal interrupt enable bit. When programming DTS value, the previous DTS threshold may be crossed. This will generate an unexpected thermal interrupt.



**Implication:** Software may observe an unexpected thermal interrupt occur after reprogramming the thermal threshold.

**Workaround:** In the ACPI/OS implement a workaround by temporarily disabling the DTS threshold interrupt before updating the DTS threshold value.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ13. Count Value for Performance-Monitoring Counter PMH\_PAGE\_WALK May be Incorrect**

**Problem:** Performance-Monitoring Counter PMH\_PAGE\_WALK is used to count the number of page walks resulting from Data Translation Look-Aside Buffer (DTLB) and Instruction Translation Look-Aside (ITLB) misses. Under certain conditions, this counter may be incorrect.

**Implication:** There may be small errors in the accuracy of the counter.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ14. LER MSRs May be Incorrectly Updated**

**Problem:** The LER (Last Exception Record) MSRs, MSR\_LER\_FROM\_LIP (1DDH) and MSR\_LER\_TO\_LIP (1DEH) may contain incorrect values after any of the following:

- Either STPCLK#, NMI (NonMaskable Interrupt) or external interrupts
- CMP or TEST instructions with an uncacheable memory operand followed by a conditional jump
- STI/POP SS/MOV SS instructions followed by CMP or TEST instructions and then by a conditional jump

**Implication:** When the conditions for this erratum occur, the value of the LER MSRs may be incorrectly updated.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ15. Performance Monitoring Events for Retired Instructions (COH) May Not Be Accurate**

**Problem:** The INST\_RETIRE performance monitor may miscount retired instructions as follows:

- Repeat string and repeat I/O operations are not counted when a hardware interrupt is received during or after the last iteration of the repeat flow.
- VMLAUNCH and VMRESUME instructions are not counted.
- HLT and MWAIT instructions are not counted. The following instructions, if executed during HLT or MWAIT events, are also not counted:
  - a) RSM from a C-state SMI during an MWAIT instruction.
  - b) RSM from an SMI during a HLT instruction.

**Implication:** There may be a smaller than expected value in the INST\_RETIRE performance monitoring counter. The extent to which this value is smaller than expected is determined by the frequency of the above cases.

**Workaround:** None Identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



#### **AJ16. Performance Monitoring Event For Number Of Reference Cycles When The Processor Is Not Halted (3CH) Does Not Count According To The Specification**

**Problem:** The CPU\_CLK\_UNHALTED performance monitor with mask 1 counts bus clock cycles instead of counting the core clock cycles at the maximum possible ratio. The maximum possible ratio is computed by dividing the maximum possible core frequency by the bus frequency.

**Implication:** The CPU\_CLK\_UNHALTED performance monitor with mask 1 counts a value lower than expected. The value is lower by exactly one multiple of the maximum possible ratio.

**Workaround:** Multiply the performance monitor value by the maximum possible ratio.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ17. Using 2M/4M Pages When A20M# Is Asserted May Result in Incorrect Address Translations**

**Problem:** An external A20M# pin if enabled forces address bit 20 to be masked (forced to zero) to emulate real-address mode address wraparound at 1 megabyte. However, if all of the following conditions are met, address bit 20 may not be masked.

- Paging is enabled
- A linear address has bit 20 set
- The address references a large page
- A20M# is enabled

**Implication:** When A20M# is enabled and an address references a large page the resulting translated physical address may be incorrect. This erratum has not been observed with any commercially available operating system.

**Workaround:** Operating systems should not allow A20M# to be enabled if the masking of address bit 20 could be applied to an address that references a large page. A20M# is normally only used with the first megabyte of memory.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ18. Writing Shared Unaligned Data that Crosses a Cache Line without Proper Semaphores or Barriers May Expose a Memory Ordering Issue**

**Problem:** Software which is written so that multiple agents can modify the same shared unaligned memory location at the same time may experience a memory ordering issue if multiple loads access this shared data shortly thereafter. Exposure to this problem requires the use of a data write which spans a cache line boundary.

**Implication:** This erratum may cause loads to be observed out of order. Intel has not observed this erratum with any commercially available software or system.

**Workaround:** Software should ensure at least one of the following is true when modifying shared data by multiple agents:


- The shared data is aligned
- Proper semaphores or barriers are used in order to prevent concurrent data accesses.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ19. Code Segment limit violation may occur on 4-Gbyte limit check**

**Problem:** Code Segment limit violation may occur on 4-Gbyte limit check when the code stream wraps around in a way that one instruction ends at the last byte of the segment and the next instruction begins at 0x0.

**Implication:** This is a rare condition that may result in a system hang. Intel has not observed this erratum with any commercially available software, or system.



**Workaround:** Avoid code that wraps around segment limit.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ20. FP Inexact-Result Exception Flag May Not Be Set**

**Problem:** When the result of a floating-point operation is not exactly representable in the destination format (1/3 in binary form, for example), an inexact-result (precision) exception occurs. When this occurs, the PE bit (bit 5 of the FPU status word) is normally set by the processor. Under certain rare conditions, this bit may not be set when this rounding occurs. However, other actions taken by the processor (invoking the software exception handler if the exception is unmasked) are not affected. This erratum can only occur if one of the following FST instructions is one or two instructions after the floating-point operation which causes the precision exception:

- FST m32real
- FST m64real
- FSTP m32real
- FSTP m64real
- FSTP m80real
- FIST m16int
- FIST m32int
- FISTP m16int
- FISTP m32int
- FISTP m64int
- FISTTP m16int
- FISTTP m32int
- FISTTP m64int

Note that even if this combination of instructions is encountered, there is also a dependency on the internal pipelining and execution state of both instructions in the processor.

**Implication:** Inexact-result exceptions are commonly masked or ignored by applications, as it happens frequently, and produces a rounded result acceptable to most applications. The PE bit of the FPU status word may not always be set upon receiving an inexact-result exception. Thus, if these exceptions are unmasked, a floating-point error exception handler may not recognize that a precision exception occurred. Note that this is a “sticky” bit, i.e., once set by an inexact-result condition, it remains set until cleared by software.

**Workaround:** This condition can be avoided by inserting either three NOPs or three non-floating-point non-Jcc instructions between the two floating-point instructions.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ21. Global Pages in the Data Translation Look-Aside Buffer (DTLB) May Not Be Flushed by RSM instruction before Restoring the Architectural State from SMRAM**

**Problem:** The Resume from System Management Mode (RSM) instruction does not flush global pages from the Data Translation Look-Aside Buffer (DTLB) prior to reloading the saved architectural state.

**Implication:** If SMM turns on paging with global paging enabled and then maps any of linear addresses of SMRAM using global pages, RSM load may load data from the wrong location.

**Workaround:** Do not use global pages in system management mode.



Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ22. Sequential Code Fetch to Non-canonical Address May have Non-deterministic Results**

**Problem:** If code sequentially executes off the end of the positive canonical address space (falling through from address 00007fffffffff to non-canonical address 0000800000000000), under some circumstances the code fetch will be converted to a canonical fetch at address ffff800000000000.

**Implication:** Due to this erratum, the processor may transfer control to an unintended address. The result of fetching code at that address is unpredictable and may include an unexpected trap or fault, or execution of the instructions found there.

**Workaround:** If the last page of the positive canonical address space is not allocated for code (4K page at 00007ffffffff000 or 2M page at 00007fffffe00000) then the problem cannot occur.

Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ23. VMCALL to Activate Dual-monitor Treatment of SMIs and SMM Ignores Reserved Bit settings in VM-exit Control Field**

**Problem:** Processors supporting Intel® Virtualization Technology can execute VMCALL from within the Virtual Machine Monitor (VMM) to activate dual-monitor treatment of SMIs and SMM. Due to this erratum, if reserved bits are set to values inconsistent with VMX Capability MSRs, VMCALL may not VMFail.

**Implication:** VMCALL executed to activate dual-monitor treatment of SMIs and SMM may not VMFail due to incorrect reserved bit settings in VM-Exit control field.

**Workaround:** Software should ensure that all VMCS reserved bits are set to values consistent with VMX Capability MSRs.

Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ24. The PECI Controller Resets to the Idle State**

**Problem:** After reset, the Platform Environment Control Interface (PECI) client controller should first identify a PECI bus idle condition and only then search for the first rising edge. Due to this erratum, the processor PECI controller resets into the "Idle Detected" state upon processor reset. If another PECI device on the platform is attempting to send a message as the processor PECI controller comes out of reset, the processor PECI controller will typically experience a Frame Check Sequence error and move to the idle state. Rarely, the processor PECI controller may interpret that the message was intended for it and try to reply. In this case a message may be corrupted but this situation will be caught and handled by the PECI error handling protocol.

**Implication:** The processor PECI controller resets to an incorrect state but the error handling capability of PECI will resolve the situation so that the processor will be able to respond to an incoming message immediately after reset and will not disregard an incoming message that arrives before an idle bus is formally detected.

**Workaround:** No workaround is necessary due to the PECI error handling protocol.

Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ25. Some Bus Performance Monitoring Events May Not Count Local Events under Certain Conditions**

**Problem:** Many Performance Monitoring Events require core-specificity, which specifies which core's events are to be counted (local core, other core or both cores). Due to this erratum, some Bus Performance Monitoring events may not count when the core-specificity is set to the local core.

The following Bus Performance Monitoring events will not count power management



related events for local core-specificity:

- BUS\_TRANS\_ IO (Event: 6CH) – Will not count I/O level reads resulting from package-resolved C-state
- BUS\_TRANS\_ANY (Event: 70H) – Will not count Stop-Grants

**Implication:** The count values for the affected events may be lower than expected. The degree of undercount depends on the occurrence of erratum conditions while the affected events are active.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ26. Premature Execution of a Load Operation Prior to Exception Handler Invocation**

**Problem:** If any of the below circumstances occur, it is possible that the load portion of the instruction will have executed before the exception handler is entered.

- If an instruction that performs a memory load causes a code segment limit violation.
- If a waiting X87 floating-point (FP) instruction or MMX™ technology (MMX) instruction that performs a memory load has a floating-point exception pending.
- If an MMX or SSE/SSE2/SSE3/SSSE3 extensions (SSE) instruction that performs a memory load and has either CR0.EM=1 (Emulation bit set), or a floating-point Top-of-Stack (FP TOS) not equal to 0, or a DNA exception pending.

**Implication:** In normal code execution where the target of the load operation is to write back memory there is no impact from the load being prematurely executed, or from the restart and subsequent re-execution of that instruction by the exception handler. If the target of the load is to uncached memory that has a system side-effect, restarting the instruction may cause unexpected system behavior due to the repetition of the side-effect. Particularly, while CR0.TS [bit 3] is set, a MOVD/MOVB with MMX/XMM register operands may issue a memory load before getting the DNA exception.

**Workaround:** Code which performs loads from memory that has side-effects can effectively workaround this behavior by using simple integer-based load instructions when accessing side-effect memory and by ensuring that all code is written such that a code segment limit violation cannot occur as a part of reading from side-effect memory.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ27. General Protection (#GP) Fault May Not Be Signaled on Data Segment Limit Violation above 4-G Limit**

**Problem:** In 32-bit mode, memory accesses to flat data segments (base = 00000000h) that occur above the 4G limit (0fffffffh) may not signal a #GP fault.

**Implication:** When such memory accesses occur in 32-bit mode, the system may not issue a #GP fault.


**Workaround:** Software should ensure that memory accesses in 32-bit mode do not occur above the 4G limit (0fffffffh).

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ28. EIP May be Incorrect after Shutdown in IA-32e Mode**

**Problem:** When the processor is going into shutdown state the upper 32 bits of the instruction pointer may be incorrect. This may be observed if the processor is taken out of shutdown state by NMI#.

**Implication:** A processor that has been taken out of the shutdown state may have an incorrect EIP. The only software which would be affected is diagnostic software that relies on a valid EIP.



Workaround: None identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

### **AJ29. #GP Fault is Not Generated on Writing IA32\_MISC\_ENABLE [34] When Execute Disable Bit is Not Supported**

**Problem:** A #GP fault is not generated on writing to IA32\_MISC\_ENABLE [34] bit in a processor which does not support Execute Disable Bit functionality.

**Implication:** Writing to IA32\_MISC\_ENABLE [34] bit is silently ignored without generating a fault.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ30. (E)CX May Get Incorrectly Updated When Performing Fast String REP MOVS or Fast String REP STOS With Large Data Structures**

**Problem:** When performing Fast String REP MOVS or REP STOS commands with data structures [(E)CX\*Data Size] larger than the supported address size structure (64K for 16-bit address size and 4G for 32-bit address size) some addresses may be processed more than once. After an amount of data greater than or equal to the address size structure has been processed, external events (such as interrupts) will cause the (E)CX registers to be incremented by a value that corresponds to 64K bytes for 16 bit address size and 4G bytes for 32 bit address size.

**Implication:** (E)CX may contain an incorrect count which may cause some of the MOVS or STOS operations to re-execute. Intel has not observed this erratum with any commercially available software.

**Workaround:** Do not use values in (E)CX that when multiplied by the data size give values larger than the address space size (64K for 16-bit address size and 4G for 32-bit address size).

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ31. Performance Monitoring Events for Retired Loads (CBH) and Instructions Retired (COH) May Not Be Accurate**

**Problem:** The following events may be counted as instructions that contain a load by the MEM\_LOAD\_RETIRED performance monitor events and may be counted as loads by the INST\_RETIRED (mask 01H) performance monitor event:

- Prefetch instructions
- x87 exceptions on FST\* and FBSTP instructions
- Breakpoint matches on loads, stores, and I/O instructions
- Stores which update the A and D bits
- Stores that split across a cache line
- VMX transitions
- Any instruction fetch that misses in the ITLB

**Implication:** The MEM\_LOAD\_RETIRED and INST\_RETIRED (mask 01H) performance monitor events may count a value higher than expected. The extent to which the values are higher than expected is determined by the frequency of the above events.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ32. Upper 32 bits of 'From' Address Reported through BTMs or BTSs May be Incorrect**

**Problem:** When a far transfer switches the processor from 32-bit mode to IA-32e mode, the upper 32 bits of the 'From' (source) addresses reported through the BTMs (Branch Trace Messages) or BTSs (Branch Trace Stores) may be incorrect.



**Implication:** The upper 32 bits of the 'From' address debug information reported through BTMs or BTSs may be incorrect during this transition

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ33. Unsynchronized Cross-Modifying Code Operations Can Cause Unexpected Instruction Execution Results**

**Problem:** The act of one processor, or system bus master, writing data into a currently executing code segment of a second processor with the intent of having the second processor execute that data as code is called cross-modifying code (XMC). XMC that does not force the second processor to execute a synchronizing instruction, prior to execution of the new code, is called unsynchronized XMC.

Software using unsynchronized XMC to modify the instruction byte stream of a processor can see unexpected or unpredictable execution behavior from the processor that is executing the modified code.

**Implication:** In this case, the phrase "unexpected or unpredictable execution behavior" encompasses the generation of most of the exceptions listed in the Intel Architecture Software Developer's Manual Volume 3: System Programming Guide, including a General Protection Fault (GPF) or other unexpected behaviors. In the event that unpredictable execution causes a GPF the application executing the unsynchronized XMC operation would be terminated by the operating system.

**Workaround:** In order to avoid this erratum, programmers should use the XMC synchronization algorithm as detailed in the Intel Architecture Software Developer's Manual Volume 3: System Programming Guide, Section: Handling Self- and Cross-Modifying Code.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ34. MSRs Actual Frequency Clock Count (IA32\_APERF) or Maximum Frequency Clock Count (IA32\_MPERF) May Contain Incorrect Data after a Machine Check Exception (MCE)**

**Problem:** When an MCE occurs during execution of a RDMSR instruction for MSRs Actual Frequency Clock Count (IA32\_APERF) or Maximum Frequency Clock Count (IA32\_MPERF), the current and subsequent RDMSR instructions for these MSRs may contain incorrect data.

**Implication:** After an MCE event, accesses to the IA32\_APERF and IA32\_MPERF MSRs may return incorrect data. A subsequent reset will clear this condition.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ35. Incorrect Address Computed For Last Byte of FXSAVE/FXRSTOR Image Leads to Partial Memory Update**

**Problem:** A partial memory state save of the 512-byte FXSAVE image or a partial memory state restore of the FXRSTOR image may occur if a memory address exceeds the 64KB limit while the processor is operating in 16-bit mode or if a memory address exceeds the 4GB limit while the processor is operating in 32-bit mode.

**Implication:** FXSAVE/FXRSTOR will incur a #GP fault due to the memory limit violation as expected but the memory state may be only partially saved or restored.

**Workaround:** Software should avoid memory accesses that wrap around the respective 16-bit and 32-bit mode memory limits.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



### **AJ36. Split Locked Stores May not Trigger the Monitoring Hardware**

**Problem:** Logical processors normally resume program execution following the MWAIT, when another logical processor performs a write access to a WB cacheable address within the address range used to perform the MONITOR operation. Due to this erratum, a logical processor may not resume execution until the next targeted interrupt event or O/S timer tick following a locked store that spans across cache lines within the monitored address range.

**Implication:** The logical processor that executed the MWAIT instruction may not resume execution until the next targeted interrupt event or O/S timer tick in the case where the monitored address is written by a locked store which is split across cache lines.

**Workaround:** Do not use locked stores that span cache lines in the monitored address range.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ37. REP CMPS/SCAS Operations May Terminate Early in 64-bit Mode when RCX >= 0X10000000**

**Problem:** REP CMPS (Compare String) and SCAS (Scan String) instructions in 64-bit mode may terminate before the count in RCX reaches zero if the initial value of RCX is greater than or equal to 0X10000000.

**Implication:** Early termination of REP CMPS/SCAS operation may be observed and RFLAGS may be incorrectly updated.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ38. FXSAVE/FXRSTOR Instructions which Store to the End of the Segment and Cause a Wrap to a Misaligned Base Address (Alignment <= 0x10h) May Cause FPU Instruction or Operand Pointer Corruption**

**Problem:** If a FXSAVE/FXRSTOR instruction stores to the end of the segment causing a wrap to a misaligned base address (alignment <= 0x10h), and one of the following conditions is satisfied:

- 1) 32-bit addressing, obtained by using address-size override, when in 64-bit mode
- 2) 16-bit addressing in legacy or compatibility mode

Then, depending on the wrap-around point, one of the below saved values may be corrupted:

- FPU Instruction Pointer Offset
- FPU Instruction Pointer Selector
- FPU Operand Pointer Selector
- FPU Operand Pointer Offset

**Implication:** This erratum could cause FPU Instruction or Operand pointer corruption and may lead to unexpected operations in the floating point exception handler.

**Workaround:** Avoid segment base mis-alignment and address wrap-around at the segment boundary.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ39. Cache Data Access Request from One Core Hitting a Modified Line in the L1 Data Cache of the Other Core May Cause Unpredictable System Behavior**

**Problem:** When request for data from Core 1 results in a L1 cache miss, the request is sent to the L2 cache. If this request hits a modified line in the L1 data cache of Core 2, certain internal conditions may cause incorrect data to be returned to the Core 1.



**Implication:** This erratum may cause unpredictable system behavior.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ40. PREFETCHH Instruction Execution under Some Conditions May Lead to Processor Livelock**

**Problem:** PREFETCHH instruction execution after a split load and dependent upon ongoing store operations may lead to processor livelock.

**Implication:** Due to this erratum, the processor may livelock.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ41. PREFETCHH Instructions May Not be Executed when Alignment Check (AC) is Enabled**

**Problem:** PREFETCHT0, PREFETCHT1, PREFETCHT2 and PREFETCHNTA instructions may not be executed when Alignment Check is enabled.

**Implication:** PREFETCHH instructions may not perform the data prefetch if Alignment Check is enabled.

**Workaround:** Clear the AC flag (bit 18) in the EFLAGS register and/or the AM bit (bit 18) of Control Register CR0 to disable alignment checking.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ42. Upper 32 Bits of the FPU Data (Operand) Pointer in the FXSAVE Memory Image May Be Unexpectedly All 1's after FXSAVE**

**Problem:** The upper 32 bits of the FPU Data (Operand) Pointer may incorrectly be set to all 1's instead of the expected value of all 0's in the FXSAVE memory image if all of the following conditions are true:

- The processor is in 64-bit mode.
- The last floating point operation was in compatibility mode
- Bit 31 of the FPU Data (Operand) Pointer is set.
- An FXSAVE instruction is executed

**Implication:** Software depending on the full FPU Data (Operand) Pointer may behave unpredictably.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ43. Concurrent Multi-processor Writes to Non-dirty Page May Result in Unpredictable Behavior**

**Problem:** When a logical processor writes to a non-dirty page, and another logical-processor either writes to the same non-dirty page or explicitly sets the dirty bit in the corresponding page table entry, complex interaction with internal processor activity may cause unpredictable system behavior.

**Implication:** This erratum may result in unpredictable system behavior and hang.

**Workaround:** It is possible for BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ44. Performance Monitor IDLE\_DURING\_DIV (18h) Count May Not be Accurate**

**Problem:** Performance monitoring events that count the number of cycles the divider is busy and no other execution unit operation or load operation is in progress may not be accurate.



**Implication:** The counter may reflect a value higher or lower than the actual number of events.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ45. Values for LBR/BTS/BTM will be Incorrect after an Exit from SMM**

**Problem:** After a return from SMM (System Management Mode), the CPU will incorrectly update the LBR (Last Branch Record) and the BTS (Branch Trace Store), hence rendering their data invalid. The corresponding data if sent out as a BTM on the system bus will also be incorrect.

**Note:** This issue would only occur when one of the 3 above mentioned debug support facilities are used.

**Implication:** The value of the LBR, BTS, and BTM immediately after an RSM operation should not be used.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ46. Shutdown Condition May Disable Non-Bootstrap Processors**

**Problem:** When a logical processor encounters an error resulting in shutdown, non-bootstrap processors in the package may be unexpectedly disabled.

**Implication:** Non-bootstrap logical processors in the package that have not observed the error condition may be disabled and may not respond to INIT#, SMI#, NMI#, SIPI or other events.

**Workaround:** When this erratum occurs, RESET# must be asserted to restore multi-core functionality.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ47. SYSCALL Immediately after Changing EFLAGS.TF May Not Behave According to the New EFLAGS.TF**

**Problem:** If a SYSCALL instruction follows immediately after EFLAGS.TF was updated and IA32\_FMASK.TF (bit 8) is cleared, then under certain circumstances SYSCALL may behave according to the previous EFLAGS.TF.

**Implication:** When the problem occurs, SYSCALL may generate an unexpected debug exception, or may skip an expected debug exception.

**Workaround:** Mask EFLAGS.TF by setting IA32\_FMASK.TF (bit 8).

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ48. Debug Register May Contain Incorrect Information on a MOVSS or POPSS Instruction Followed by SYSRET**

**Problem:** In IA-32e mode, if a MOVSS or POPSS instruction with a debug breakpoint is followed by the SYSRET instruction, incorrect information may exist in the Debug Status Register (DR6).

**Implication:** When debugging or when developing debuggers, this behavior should be noted. This erratum will not occur under normal usage of the MOVSS or POPSS instructions (i.e., following them with a MOV ESP instruction).

**Workaround:** Do not attempt to put a breakpoint on MOVSS and POPSS instructions that are followed by a SYSRET.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



#### **AJ49. VM Bit is Cleared on Second Fault Handled by Task Switch from Virtual-8086 (VM86)**

**Problem:** Following a task switch to any fault handler that was initiated while the processor was in VM86 mode, if there is an additional fault while servicing the original task switch then the VM bit will be incorrectly cleared in EFLAGS, data segments will not be pushed and the processor will not return to the correct mode upon completion of the second fault handler via IRET.

**Implication:** When the OS recovers from the second fault handler, the processor will no longer be in VM86 mode. Normally, operating systems should prevent interrupt task switches from faulting, thus the scenario should not occur under normal circumstances.

**Workaround:** None Identified

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ50. IA32\_FMASK is Reset during an INIT**

**Problem:** IA32\_FMASK MSR (0xC0000084) is reset during INIT.

**Implication:** If an INIT takes place after IA32\_FMASK is programmed, the processor will overwrite the value back to the default value.

**Workaround:** Operating system software should initialize IA32\_FMASK after INIT.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ51. An Enabled Debug Breakpoint or Single Step Trap May Be Taken after MOV SS/POP SS Instruction if it is Followed by an Instruction That Signals a Floating Point Exception**

**Problem:** A MOV SS/POP SS instruction should inhibit all interrupts including debug breakpoints until after execution of the following instruction. This is intended to allow the sequential execution of MOV SS/POP SS and MOV [r/e]SP, [r/e]BP instructions without having an invalid stack during interrupt handling. However, an enabled debug breakpoint or single step trap may be taken after MOV SS/POP SS if this instruction is followed by an instruction that signals a floating point exception rather than a MOV [r/e]SP, [r/e]BP instruction. This results in a debug exception being signaled on an unexpected instruction boundary since the MOV SS/POP SS and the following instruction should be executed atomically.

**Implication:** This can result in incorrect signaling of a debug exception and possibly a mismatched Stack Segment and Stack Pointer. If MOV SS/POP SS is not followed by a MOV [r/e]SP, [r/e]BP, there may be a mismatched Stack Segment and Stack Pointer on any exception. Intel has not observed this erratum with any commercially available software, or system.

**Workaround:** As recommended in the IA32 Intel® Architecture Software Developer's Manual, the use of MOV SS/POP SS in conjunction with MOV [r/e]SP, [r/e]BP will avoid the failure since the MOV [r/e]SP, [r/e]BP will not generate a floating point exception. Developers of debug tools should be aware of the potential incorrect debug event signaling created by this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ52. Last Branch Records (LBR) Updates May be Incorrect after a Task Switch**

**Problem:** A Task-State Segment (TSS) task switch may incorrectly set the LBR\_FROM value to the LBR\_TO value.

**Implication:** The LBR\_FROM will have the incorrect address of the Branch Instruction.

**Workaround:** None Identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



### **AJ53. IO\_SMI Indication in SMRAM State Save Area May Be Set Incorrectly**

**Problem:** The IO\_SMI bit in SMRAM's location 7FA4H is set to "1" by the CPU to indicate a System Management Interrupt (SMI) occurred as the result of executing an instruction that reads from an I/O port. Due to this erratum, the IO\_SMI bit may be incorrectly set by:

- A non-I/O instruction
- SMI is pending while a lower priority event interrupts
- A REP I/O read
- An I/O read that redirects to MWAIT

**Implication:** SMM handlers may get false IO\_SMI indication.

**Workaround:** The SMM handler has to evaluate the saved context to determine if the SMI was triggered by an instruction that read from an I/O port. The SMM handler must not restart an I/O instruction if the platform has not been configured to generate a synchronous SMI for the recorded I/O port address.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ54. INIT Does Not Clear Global Entries in the TLB**

**Problem:** INIT may not flush a TLB entry when:

- The processor is in protected mode with paging enabled and the page global enable flag is set (PGE bit of CR4 register)
- G bit for the page table entry is set
- TLB entry is present in TLB when INIT occurs

**Implication:** Software may encounter unexpected page fault or incorrect address translation due to a TLB entry erroneously left in TLB after INIT.

**Workaround:** Write to CR3, CR4 (setting bits PSE, PGE or PAE) or CR0 (setting bits PG or PE) registers before writing to memory early in BIOS code to clear all the global entries from TLB.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ55. Using Memory Type Aliasing with Memory Types WB/WT May Lead to Unpredictable Behavior**

**Problem:** Memory type aliasing occurs when a single physical page is mapped to two or more different linear addresses, each with different memory type. Memory type aliasing with the memory types WB and WT may cause the processor to perform incorrect operations leading to unpredictable behavior.

**Implication:** Software that uses aliasing of WB and WT memory types may observe unpredictable behavior.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ56. Update of Read/Write (R/W) or User/Supervisor (U/S) or Present (P) Bits without TLB Shutdown May Cause Unexpected Processor Behavior**

**Problem:** Updating a page table entry by changing R/W, U/S or P bits without TLB shutdown (as defined by the 4 step procedure in "Propagation of Page Table and Page Directory Entry Changes to Multiple Processors" in volume 3A of the IA-32 Intel® Architecture Software Developer's Manual), in conjunction with a complex sequence of internal processor micro-architectural events, may lead to unexpected processor behavior.

**Implication:** This erratum may lead to livelock, shutdown or other unexpected processor behavior. Intel has not observed this erratum with any commercially available system.

**Workaround:** None identified.



Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ57. BTS Message May Be Lost When the STPCLK# Signal is Active**

**Problem:** STPCLK# is asserted to enable the processor to enter a low-power state. Under some circumstances, when STPCLK# becomes active, the BTS (Branch Trace Store) message may be either lost and not written or written with corrupted branch address to the Debug Store area.

**Implication:** BTS messages may be lost or be corrupted in the presence of STPCLK# assertions.

**Workaround:** None Identified.

Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ58. CMPSB, LODSB, or SCASB in 64-bit Mode with Count Greater or Equal to 2<sup>48</sup> May Terminate Early**

**Problem:** In 64-bit Mode CMPSB, LODSB, or SCASB executed with a repeat prefix and count greater than or equal to 2<sup>48</sup> may terminate early. Early termination may result in one of the following:

- The last iteration not being executed
- Signaling of a canonical limit fault (#GP) on the last iteration

**Implication:** While in 64-bit mode, with count greater or equal to 2<sup>48</sup>, repeat string operations CMPSB, LODSB or SCASB may terminate without completing the last iteration. Intel has not observed this erratum with any commercially available software.

**Workaround:** Do not use repeated string operations with RCX greater than or equal to 2<sup>48</sup>.

Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ59. REP MOVSB/STOS Executing with Fast Strings Enabled and Crossing Page Boundaries with Inconsistent Memory Types may use an Incorrect Data Size or Lead to Memory-Ordering Violations**

**Problem:** Under certain conditions as described in the Software Developers Manual section “Out-of-Order Stores For String Operations in Pentium 4, Intel Xeon, and P6 Family Processors” the processor performs REP MOVSB or REP STOS as fast strings. Due to this erratum fast string REP MOVSB/REP STOS instructions that cross page boundaries from WB/WC memory types to UC/WP/WT memory types, may start using an incorrect data size or may observe memory ordering violations.

**Implication:** Upon crossing the page boundary the following may occur, dependent on the new page memory type:


- UC the data size of each write will now always be 8 bytes, as opposed to the original data size.
- WP the data size of each write will now always be 8 bytes, as opposed to the original data size and there may be a memory ordering violation.
- WT there may be a memory ordering violation.

**Workaround:** Software should avoid crossing page boundaries from WB or WC memory type to UC, WP or WT memory type within a single REP MOVSB or REP STOS instruction that will execute with fast strings enabled.

Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ60. MOV To/From Debug Registers Causes Debug Exception**

**Problem:** When in V86 mode, if a MOV instruction is executed on to/from a debug registers, a general-protection exception (#GP) should be generated. However, in the case when the general detect enable flag (GD) bit is set, the observed behavior is that a debug exception (#DB) is generated instead.



**Implication:** With debug-register protection enabled (i.e., the GD bit set), when attempting to execute a MOV on debug registers in V86 mode, a debug exception will be generated instead of the expected general-protection fault.

**Workaround:** In general, operating systems do not set the GD bit when they are in V86 mode. The GD bit is generally set and used by debuggers. The debug exception handler should check that the exception did not occur in V86 mode before continuing. If the exception did occur in V86 mode, the exception may be directed to the general-protection exception handler.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ61. EFLAGS Discrepancy on Page Faults after a Translation Change**

**Problem:** This erratum is regarding the case where paging structures are modified to change a linear address from writable to non-writable without software performing an appropriate TLB invalidation. When a subsequent access to that address by a specific instruction (ADD, AND, BTC, BTR, BTS, CMPXCHG, DEC, INC, NEG, NOT, OR, ROL/ROR, SAL/SAR/SHL/SHR, SHLD, SHRD, SUB, XOR, and XADD) causes a page fault, the value saved for EFLAGS may incorrectly contain the arithmetic flag values that the EFLAGS register would have held had the instruction completed without fault. This can occur even if the fault causes a VM exit or if its delivery causes a nested fault.

**Implication:** None identified. Although the EFLAGS saved value may contain incorrect arithmetic flag values, Intel has not identified software that inspects the arithmetic portion of this value while handling page faults. This erratum will have no further effects once the original instruction is restarted because the instruction will produce the same results as if it had initially completed without a page fault.

**Workaround:** System software should perform the appropriate TLB invalidations if its page-fault handler inspects the arithmetic portion of the saved EFLAGS value.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ62. LBR, BTS, BTM May Report a Wrong Address when an Exception/Interrupt Occurs in 64-bit Mode**

**Problem:** An exception/interrupt event should be transparent to the LBR (Last Branch Record), BTS (Branch Trace Store) and BTM (Branch Trace Message) mechanisms. However, during a specific boundary condition where the exception/interrupt occurs right after the execution of an instruction at the lower canonical boundary (0x00007FFFFFFFFF) in 64-bit mode, the LBR return registers will save a wrong return address with bits 63 to 48 incorrectly sign extended to all 1's. Subsequent BTS and BTM operations which report the LBR will also be incorrect.

**Implication:** LBR, BTS and BTM may report incorrect information in the event of an exception/interrupt.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ63. Returning to Real Mode from SMM with EFLAGS.VM Set May Result in Unpredictable System Behavior**

**Problem:** Returning back from SMM mode into real mode while EFLAGS.VM is set in SMRAM may result in unpredictable system behavior.

**Implication:** If SMM software changes the values of the EFLAGS.VM in SMRAM, it may result in unpredictable system behavior. Intel has not observed this behavior in commercially available software.

**Workaround:** SMM software should not change the value of EFLAGS.VM in SMRAM.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



#### **AJ64. A Thermal Interrupt is Not Generated when the Current Temperature is Invalid**

**Problem:** When the DTS (Digital Thermal Sensor) crosses one of its programmed thresholds it generates an interrupt and logs the event (IA32\_THERM\_STATUS MSR (019Ch) bits [9,7]). Due to this erratum, if the DTS reaches an invalid temperature (as indicated IA32\_THERM\_STATUS MSR bit[31]) it does not generate an interrupt even if one of the programmed thresholds is crossed and the corresponding log bits become set.

**Implication:** When the temperature reaches an invalid temperature the CPU does not generate a Thermal interrupt even if a programmed threshold is crossed.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ65. Performance Monitoring Event FP\_ASSIST May Not be Accurate**

**Problem:** Performance monitoring event FP\_ASSIST (11H) may be inaccurate as assist events may be counted twice per actual assist in the following specific cases:

- FADD and FMUL instructions with a NaN (Not a Number) operand and a memory operand
- FDIV instruction with zero operand value in memory

In addition, an assist event may be counted when DAZ (Denormals-Are-Zeros) and FTZ (Flush-To-Zero) flags are turned on even though no actual assist occurs.

**Implication:** The counter value for the performance monitoring event FP\_ASSIST (11H) may be larger than expected. The size of the error is dependent on the number of occurrences of the above conditions while the event is active.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ66. CPL-Qualified BTS May Report Incorrect Branch-From Instruction Record From Address**

**Problem:** CPL (Current Privilege Level)-qualified BTS (Branch Trace Store) may report incorrect branch-from instruction record From address under the following conditions:

- Either BTS\_OFF\_OS[9] or BTS\_OFF\_USR[10] is selected in IA32\_DEBUGCTL MSR (1D9H)
- Privilege-level transitions occur between CPL > 0 and CPL 0 or vice versa.

**Implication:** Due to this erratum, the From address reported by BTS may be incorrect for the described conditions.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.


#### **AJ67. PEBS Does Not Always Differentiate Between CPL-Qualified Events**

**Problem:** Performance monitoring counter configured to sample PEBS (Precise Event Based Sampling) events at a certain privilege level may count samples at the wrong privilege level

**Implication:** Performance monitoring counter may be higher than expected for CPL-qualified events.

**Workaround:** Do not use performance monitoring counters for precise event sampling when the precise event is dependent on the CPL value.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



#### **AJ68. PMI May be Delayed to Next PEBS Event**

**Problem:** After a PEBS (Precise Event-Based Sampling) event, the PEBS index is compared with the PEBS threshold, and the index is incremented with every event. If PEBS index is equal to the PEBS threshold, a PMI (Performance Monitoring Interrupt) should be issued. Due to this erratum, the PMI may be delayed by one PEBS event.

**Implication:** Debug Store Interrupt Service Routines may observe delay of PMI occurrence by one PEBS event.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ69. PEBS Buffer Overflow Status Will Not be Indicated Unless IA32\_DEBUGCTL[12] is Set**

**Problem:** IA32\_PERF\_GLOBAL\_STATUS MSR (38EH) bit [62] when set, indicates that a PEBS (Precise Event-Based Sampling) overflow has occurred and a PMI (Performance Monitor Interrupt) has been sent. Due to this erratum, this bit will not be set unless IA32\_DEBUGCTL MSR (1D9H) bit [12] (which stops all Performance Monitor Counters upon a PMI) is also set.

**Implication:** Unless IA32\_DEBUGCTL[12] is set, IA32\_PERF\_GLOBAL\_STATUS[62] will not indicate that a PMI was generated due to a PEBS Overflow.

**Workaround:** It is possible for the software to set IA32\_DEBUGCTL[12] to avoid this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ70. The BS Flag in DR6 May be Set for Non-Single-Step #DB Exception**

**Problem:** DR6 BS (Single Step, bit 14) flag may be incorrectly set when the TF (Trap Flag, bit 8) of the EFLAGS Register is set, and a #DB (Debug Exception) occurs due to one of the following:

- DR7 GD (General Detect, bit 13) being bit set
- INT1 instruction
- Code breakpoint

**Implication:** The BS flag may be incorrectly set for non-single-step #DB exception.

**Workaround:** None identified

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ71. An Asynchronous MCE During a Far Transfer May Corrupt ESP**

**Problem:** If an asynchronous machine check occurs during an interrupt, call through gate, FAR RET or IRET and in the presence of certain internal conditions, ESP may be corrupted.

**Implication:** If the MCE (Machine Check Exception) handler is called without a stack switch, then a triple fault will occur due to the corrupted stack pointer, resulting in a processor shutdown. If the MCE is called with a stack switch, e.g. when the CPL (Current Privilege Level) was changed or when going through an interrupt task gate, then the corrupted ESP will be saved on the new stack or in the TSS (Task State Segment), and will not be used.

**Workaround:** Use an interrupt task gate for the machine check handler.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



#### **AJ72. In Single-Stepping on Branches Mode, the BS Bit in the Pending-Debug-Exceptions Field of the Guest State Area will be Incorrectly Set by VM-Exit on a MOV to CR8 Instruction**

**Problem:** In a system supporting Intel® Virtualization Technology, the BS bit (bit 14 of the Pending-Debug-Exceptions field) in the guest state area will be incorrectly set when all of the following conditions occur:

- The processor is running in VMX non-root as a 64 bit mode guest
- The “CR8-load existing” VM-execution control is 0 and the “use TPR shadow” VM-execution is 1
- Both BTF (Single-Step On Branches, bit 1) of the IA32\_DEBUGCTL MSR (1D9H) Register and the TF (Trap Flag, bit 8) of the RFLAGS Register are set
- “MOV CR8, reg” attempts to program a TPR (Task Priority Register) value that is below the TPR threshold and causes a VM-exit

**Implication:** A Virtual-Machine will sample the BS bit and will incorrectly inject a Single-Step trap to the guest.

**Workaround:** A Virtual-Machine Monitor must manually disregard the BS bit in the Guest State Area in case of a VM-exit due to a TPR value below the TPR threshold.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ73. B0-B3 Bits in DR6 May Not be Properly Cleared After Code Breakpoint**

**Problem:** B0-B3 bits (breakpoint conditions detect flags, bits [3:0]) in DR6 may not be properly cleared when the following sequence happens:

1. POP instruction to SS (Stack Segment) selector
2. Next instruction is FP (Floating Point) that gets FP assist followed by code breakpoint

**Implication:** B0-B3 bits in DR6 may be set incorrectly not be properly cleared.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ74. Performance Monitoring Events for L1 and L2 Miss May Not be Accurate**

**Problem:** Performance monitoring events 0CBh with an event mask value of 02h or 08h (MEM\_LOAD\_RETIRED.L1\_LINE\_MISS or MEM\_LOAD\_RETIRED.L2\_LINE\_MISS) may under count the cache miss events.

**Implication:** Performance monitoring events 0CBh with an event mask value of 02h or 08h may show a count which is lower than expected; the amount by which the count is lower is dependent on other conditions occurring on the same load that missed the cache.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ75. BTM/BTS Branch-From Instruction Address May be Incorrect for Software Interrupts**

**Problem:** When BTM (Branch Trace Message) or BTS (Branch Trace Store) is enabled, a software interrupt may result in the overwriting of BTM/BTS branch-from instruction address by the LBR (Last Branch Record) branch-from instruction address.

**Implication:** A BTM/BTS branch-from instruction address may get corrupted for software interrupts.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



#### **AJ76. VMLAUNCH/VMRESUME May Not Fail when VMCS is Programmed to Cause VM Exit to Return to a Different Mode**

**Problem:** VMLAUNCH/VMRESUME instructions may not fail if the value of the “host address-space size” VM-exit control differs from the setting of IA32\_EFER.LMA.

**Implication:** Programming the VMCS to allow the monitor to be in different modes prior to VMLAUNCH/VMRESUME and after VM-exit may result in undefined behavior.

**Workaround:** Software should ensure that “host address-space size” VM-exit control has the same value as IA32\_EFER.LMA at the time of VMLAUNCH/VMRESUME.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ77. Performance Monitor SSE Retired Instructions May Return Incorrect Values**

**Problem:** The SIMD\_INST\_RETIRED (Event: C7H) is used to track retired SSE instructions. Due to this erratum, the processor may inaccurately count certain types of instructions resulting in values higher than the number of actual retired SSE instructions.

**Implication:** The event monitor instruction SIMD\_INST\_RETIRED may report count higher than expected.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ78. REP Store Instructions in a Specific Situation may cause the Processor to Hang**

**Problem:** During a series of REP (repeat) store instructions a store may try to dispatch to memory prior to the actual completion of the instruction. This behavior depends on the execution order of the instructions, the timing of a speculative jump and the timing of an uncacheable memory store. All types of REP store instructions are affected by this erratum.

**Implication:** When this erratum occurs, the processor may live lock and/or result in a system hang.

**Workaround:** It is possible for BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ79. A MOV Instruction from CR8 Register with 16 Bit Operand Size Will Leave Bits 63:16 of the Destination Register Unmodified**

**Problem:** Moves to/from control registers are supposed to ignore REW.W and the 66H (operand size) prefix. In systems supporting Intel® Virtualization Technology, when the processor is operating in VMX non-root operation and “use TPR shadow” VM-execution control is set to 1, a MOV instruction from CR8 with a 16 bit operand size (REX.W = 0 and 66H prefix) will only store 16 bits and leave bits 63:16 at the destination register unmodified, instead of storing zeros in them.

**Implication:** Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.


**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ80. Store to WT Memory Data May be Seen in Wrong Order by Two Subsequent Loads**

**Problem:** When data of Store to WT memory is used by two subsequent loads of one thread and another thread performs cacheable write to the same address the first load may get the data from external memory or L2 written by another core, while the second load will get the data straight from the WT Store.

**Implication:** Software that uses WB to WT memory aliasing may violate proper store ordering.

**Workaround:** Do not use WB to WT aliasing.



Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ81. IRET under Certain Conditions May Cause an Unexpected Alignment Check Exception**

**Problem:** In IA-32e mode, it is possible to get an Alignment Check Exception (#AC) on the IRET instruction even though alignment checks were disabled at the start of the IRET. This can only occur if the IRET instruction is returning from CPL3 code to CPL3 code. IRETs from CPL0/1/2 are not affected. This erratum can occur if the EFLAGS value on the stack has the AC flag set, and the interrupt handler's stack is misaligned. In IA-32e mode, RSP is aligned to a 16-byte boundary before pushing the stack frame.

**Implication:** In IA-32e mode, under the conditions given above, an IRET can get a #AC even if alignment checks are disabled at the start of the IRET. This erratum can only be observed with a software generated stack frame.

**Workaround:** Software should not generate misaligned stack frames for use with IRET.

Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ82. Removed - Not Applicable**

#### **AJ83. Non-Temporal Data Store May be Observed in Wrong Program Order**

**Problem:** When non-temporal data is accessed by multiple read operations in one thread while another thread performs a cacheable write operation to the same address, the data stored may be observed in wrong program order (i.e. later load operations may read older data).

**Implication:** Software that uses non-temporal data without proper serialization before accessing the non-temporal data may observe data in wrong program order. Software that conforms to the Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A, section "Buffering of Write Combining Memory Locations" will operate correctly.

**Workaround:** None identified.

Status: For the steppings affected, see the Summary Tables of Changes.

#### **AJ84. Removed - Not Applicable**

#### **AJ85. CPUID Reports Architectural Performance Monitoring Version 2 is Supported, When Only Version 1 Capabilities are Available**

**Problem:** CPUID leaf 0Ah reports the architectural performance monitoring version that is available in EAX[7:0]. Due to this erratum CPUID reports the supported version as 2 instead of 1.

**Implication:** Software will observe an incorrect version number in CPUID.0Ah.EAX [7:0] in comparison to which features are actually supported.

**Workaround:** Software should use the recommended enumeration mechanism described in the Architectural Performance Monitoring section of the Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3: System Programming Guide.

Status: For the steppings affected, see the Summary Tables of Changes.

#### **AJ86. Unaligned Accesses to Paging Structures May Cause the Processor to Hang**

**Problem:** When an unaligned access is performed on paging structure entries, accessing a portion of two different entries simultaneously, the processor may live lock.

**Implication:** When this erratum occurs, the processor may live lock causing a system hang.

**Workaround:** Do not perform unaligned accesses on paging structure entries.

Status: For the steppings affected, see the Summary Tables of Changes.



### **AJ87. Microcode Updates Performed During VMX Non-root Operation Could Result in Unexpected Behavior**

**Problem:** When Intel® Virtualization Technology is enabled, microcode updates are allowed only during VMX root operations. Attempts to apply microcode updates while in VMX non-root operation should be silently ignored. Due to this erratum, the processor may allow microcode updates during VMX non-root operations if not explicitly prevented by the host software.

**Implication:** Microcode updates performed in non-root operation may result in unexpected system behavior.

**Workaround:** Host software should intercept and prevent loads to IA32\_BIOS\_UPDT\_TRIG MSR (79H) during VMX non-root operations. There are two mechanism that can be used (1) Enabling MSR access protection in the VM-execution controls or (2) Enabling selective MSR protection of IA32\_BIOS\_UPDT\_TRIG MSR.

**Status:** For the steppings affected, see the Summary Tables of Changes.

### **AJ88. INVLPG Operation for Large (2M/4M) Pages May be Incomplete under Certain Conditions**

**Problem:** The INVLPG instruction may not completely invalidate Translation Look-aside Buffer (TLB) entries for large pages (2M/4M) when both of the following conditions exist:

- Address range of the page being invalidated spans several Memory Type Range Registers (MTRRs) with different memory types specified
- INVLPG operation is preceded by a Page Assist Event (Page Fault (#PF) or an access that results in either A or D bits being set in a Page Table Entry (PTE))

**Implication:** Stale translations may remain valid in TLB after a PTE update resulting in unpredictable system behavior. Intel has not observed this erratum with any commercially available software.

**Workaround:** Software should ensure that the memory type specified in the MTRRs is the same for the entire address range of the large page.

**Status:** For the steppings affected, see the Summary Tables of Changes.

### **AJ89. Page Access Bit May be Set Prior to Signaling a Code Segment Limit Fault**

**Problem:** If code segment limit is set close to the end of a code page, then due to this erratum the memory page Access bit (A bit) may be set for the subsequent page prior to general protection fault on code segment limit.

**Implication:** When this erratum occurs, a non-accessed page which is present in memory and follows a page that contains the code segment limit may be tagged as accessed.

**Workaround:** Erratum can be avoided by placing a guard page (non-present or non-executable page) as the last page of the segment or after the page that includes the code segment limit.

**Status:** For the steppings affected, see the Summary Tables of Changes.

### **AJ90. Update of Attribute Bits on Page Directories without Immediate TLB Shutdown May Cause Unexpected Processor Behavior.**

**Problem:** Updating a page directory entry (or page map level 4 table entry or page directory pointer table entry in IA-32e mode) by changing Read/Write (R/W) or User/Supervisor (U/S) or Present (P) bits without immediate TLB shutdown (as described by the 4 step procedure in "Propagation of Page Table and Page Directory Entry Changes to Multiple Processors" In volume 3A of the Intel® 64 and IA-32 Architecture Software Developer's Manual), in conjunction with a complex sequence of internal processor micro-architectural events, may lead to unexpected processor behavior.

**Implication:** This erratum may lead to livelock, shutdown or other unexpected processor behavior. Intel has not observed this erratum with any commercially available software.



**Workaround:** None Identified.

**Status:** For the steppings affected, see the Summary Tables of Changes.

### **AJ91. Invalid Instructions May Lead to Unexpected Behavior**

**Problem:** Invalid instructions due to undefined opcodes or instructions exceeding the maximum instruction length (due to redundant prefixes placed before the instruction) may lead, under complex circumstances, to unexpected behavior.

**Implication:** The processor may behave unexpectedly due to invalid instructions. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the Summary Tables of Changes.

### **AJ92. EFLAGS, CR0, CR4 and the EXF4 Signal May be Incorrect after Shutdown**

**Problem:** When the processor is going into shutdown due to an RSM inconsistency failure, EFLAGS, CR0 and CR4 may be incorrect. In addition the EXF4 signal may still be asserted. This may be observed if the processor is taken out of shutdown by NMI#

**Implication:** A processor that has been taken out of shutdown may have an incorrect EFLAGS, CR0 and CR4. In addition the EXF4 signal may still be asserted.

**Workaround:** None identified.

**Status:** For the steppings affected, see the Summary Tables of Changes.

### **AJ93. Performance Monitoring Counter MACRO\_INSTS.DECODED May Not Count Some Decoded Instructions**

**Problem:** MACRO\_INSTS.DECODED performance monitoring counter (Event 0AAH, Umask 01H) counts the number of macro instructions decoded, but not necessarily retired. The event is undercounted when the decoded instructions are a complete loop iteration that is decoded in one cycle and the loop is streamed by the LSD (Loop Stream Detector), as described in the Optimizing the Front End section of the Intel® 64 and IA-32 Architectures Optimization Reference Manual.

**Implication:** The count value returned by the performance monitoring counter MACRO\_INST.DECODED may be lower than expected. The degree of undercounting is dependent on the occurrence of loop iterations that are decoded in one cycle and whether the loop is streamed by the LSD while the counter is active.

**Workaround:** Workaround: None identified.

**Status:** For the steppings affected, see the Summary Tables of Changes.

### **AJ94. The Stack Size May be Incorrect as a Result of VIP/VIF Check on SYSEXIT and SYSRET**

**Problem:** The stack size may be incorrect under the following scenario:

- The stack size was changed due to a SYSEXIT or SYSRET
- PVI (Protected Mode Virtual Interrupts) mode was enabled (CR4.PVI == 1)
- Both the VIF (Virtual Interrupt Flag) and VIP (Virtual Interrupt Pending) flags of the EFLAGS register are set

**Implication:** If this erratum occurs the stack size may be incorrect, consequently this may result in unpredictable system behavior. Intel has not observed this erratum with any commercially available software.

**Workaround:** None Identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



#### **AJ95. Performance Monitoring Event SIMD\_UOP\_TYPE\_EXEC.MUL is Counted Incorrectly for PMULUDQ Instruction**

**Problem:** Performance Monitoring Event SIMD\_UOP\_TYPE\_EXEC.MUL (Event select 0B3H, Umask 01H) counts the number of SIMD packed multiply micro-ops executed. The count for PMULUDQ micro-ops may be lower than expected. No other instruction is affected.

**Implication:** The count value returned by the performance monitoring event SIMD\_UOP\_TYPE\_EXEC.MUL may be lower than expected. The degree of undercount depends on actual occurrences of PMULUDQ instructions, while the counter is active.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ96. Storage of PEBS Record Delayed Following Execution of MOV SS or STI**

**Problem:** When a performance monitoring counter is configured for PEBS (Precise Event Based Sampling), overflow of the counter results in storage of a PEBS record in the PEBS buffer. The information in the PEBS record represents the state of the next instruction to be executed following the counter overflow. Due to this erratum, if the counter overflow occurs after execution of either MOV SS or STI, storage of the PEBS record is delayed by one instruction.

**Implication:** When this erratum occurs, software may observe storage of the PEBS record being delayed by one instruction following execution of MOV SS or STI. The state information in the PEBS record will also reflect the one instruction delay.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ97. Processor On Die Termination of BR1# and LOCK# Signals are Incorrect**

**Problem:** On Die Termination control of BR1# and LOCK# signals are incorrect. BR#1 has its On Die Termination continuously enabled and LOCK# has its On Die Termination continuously disabled.

**Implication:** BR1# has its On Die Termination continuously enabled meaning the VOL (Output Low Voltage) of this signal is expected to be higher than normal losing potential margin for nominal VCCP. LOCK# has its On Die Termination always disabled meaning the VOL of this signal is expected to be lower than normal and could lead to signal degradation. Even if the BR1# and Lock# terminations are always on or always off, VOL electrical specifications are not violated. Intel has not observed any functional failure due to this erratum.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ98. Ordering May be Incorrect between WC and WP Memory Types**

**Problem:** According to Intel® 64 and IA-32 Intel Architecture Software Developer's Manual, Volume 3A "Methods of Caching Available", WP (Write Protected) stores should drain the WC (Write Combining) buffers in the same way as UC (Uncacheable) memory type stores do. Due to this erratum, WP stores may not drain the WC buffers.

**Implication:** Memory ordering may be violated between WC and WP stores.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ99. Updating Code Page Directory Attributes without TLB Invalidation May Result in Improper Handling of Code #PF**

**Problem:** Code #PF (Page Fault exception) is normally handled in lower priority order relative to both code #DB (Debug Exception) and code Segment Limit Violation #GP (General



Protection Fault). Due to this erratum, code #PF may be handled incorrectly, if all of the following conditions are met:

- A PDE (Page Directory Entry) is modified without invalidating the corresponding TLB (Translation Look-aside Buffer) entry
- Code execution transitions to a different code page such that both
  - The target linear address corresponds to the modified PDE
  - The PTE (Page Table Entry) for the target linear address has an A (Accessed) bit that is clear
- One of the following simultaneous exception conditions is present following the code transition
  - Code #DB and code #PF
  - Code Segment Limit Violation #GP and code #PF

**Implication:** Software may observe either incorrect processing of code #PF before code Segment Limit Violation #GP or processing of code #PF in lieu of code #DB.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ100. Performance Monitoring Event CPU\_CLK\_UNHALTED.REF May Not Count Clock Cycles According to the Processors Operating Frequency**

**Problem:** Performance Counter MSR\_PERF\_FIXED\_CTR2 (MSR 30BH) that counts CPU\_CLK\_UNHALTED.REF clocks, should count these clock cycles at a constant rate that is determined by the maximum resolved boot frequency, as programmed by BIOS. Due to this erratum, the rate is instead set by the maximum core-clock to bus-clock ratio of the processor, as indicated by hardware.

**Implication:** No functional impact as a result of this erratum. If the maximum resolved boot frequency as programmed by BIOS is different from the frequency implied by the maximum core-clock to bus-clock ratio of the processor as indicated by hardware, then the following effects may be observed:

- Performance Monitoring Event CPU\_CLK\_UNHALTED.REF will count at a rate different than the TSC (Time Stamp Counter)
- When running a system with several processors that have different maximum core-clock to bus-clock ratios, CPU\_CLK\_UNHALTED.REF monitoring events at each processor will be counted at different rates and therefore will not be comparable.

**Workaround:** Calculate the ratio of the rates at which the TSC and the CPU\_CLK\_UNHALTED.REF performance monitoring event count (this can be done by measuring simultaneously their counted value while executing code) and adjust the CPU\_CLK\_UNHALTED.REF event count to the maximum resolved boot frequency using this ratio.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ101. Performance Monitoring Event BR\_INST\_RETIRED May Count CPUID Instructions as Branches**

**Problem:** Performance monitoring event BR\_INST\_RETIRED (C4H) counts retired branch instructions. Due to this erratum, two of its sub-events mistakenly count for CPUID instructions as well. Those sub events are: BR\_INST\_RETIRED.PRED\_NOT\_TAKEN (Umask 01H) and BR\_INST\_RETIRED.ANY (Umask 00H).

**Implication:** The count value returned by the performance monitoring event BR\_INST\_RETIRED.PRED\_NOT\_TAKEN or BR\_INST\_RETIRED.ANY may be higher than expected. The extent of over counting depends on the occurrence of CPUID instructions, while the counter is active.

**Workaround:** None identified.



Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ102. Performance Monitoring Event MISALIGN\_MEM\_REF May Over Count**

**Problem:** Performance monitoring event MISALIGN\_MEM\_REF (05H) is used to count the number of memory accesses that cross an 8-byte boundary and are blocked until retirement. Due to this erratum, the performance monitoring event MISALIGN\_MEM\_REF also counts other memory accesses.

**Implication:** The performance monitoring event MISALIGN\_MEM\_REF may over count. The extent of over counting depends on the number of memory accesses retiring while the counter is active.

**Workaround:** None identified

Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ103. A REP STOS/MOVS to a MONITOR/MWAIT Address Range May Prevent Triggering of the Monitoring Hardware**

**Problem:** The MONITOR instruction is used to arm the address monitoring hardware for the subsequent MWAIT instruction. The hardware is triggered on subsequent memory store operations to the monitored address range. Due to this erratum, REP STOS/MOVS fast string operations to the monitored address range may prevent the actual triggering store to be propagated to the monitoring hardware.

**Implication:** A logical processor executing an MWAIT instruction may not immediately continue program execution if a REP STOS/MOVS targets the monitored address range.

**Workaround:** Software can avoid this erratum by not using REP STOS/MOVS store operations within the monitored address range

Status: For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ104. False Level One Data Cache Parity Machine-Check Exceptions May be Signaled**

**Problem:** Executing an instruction stream containing invalid instructions/data may generate a false Level One Data Cache parity machine-check exception.

**Implication:** The false Level One Data Cache parity machine-check exception is reported as an uncorrected machine-check error. An uncorrected machine-check error is treated as a fatal exception by the operating system and may cause a shutdown and/or reboot.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

Status: For the steppings affected, see the *Summary Tables of Changes*.


#### **AJ105. A Memory Access May Get a Wrong Memory Type Following a #GP due to WRMSR to an MTRR Mask**

**Problem:** The TLB (Translation Lookaside Buffer) may indicate a wrong memory type on a memory access to a large page (2M/4M Byte) following the recovery from a #GP (General Protection Fault) due to a WRMSR to one of the IA32\_MTRR\_PHYSMASKn MSRs with reserved bits set.

**Implication:** When this erratum occurs, a memory access may get an incorrect memory type leading to unexpected system operation. As an example, an access to a memory mapped I/O device may be incorrectly marked as cacheable, become cached, and never make it to the I/O device. Intel has not observed this erratum with any commercially available software.

**Workaround:** Software should not attempt to set reserved bits of IA32\_MTRR\_PHYSMASKn MSRs.

Status: For the steppings affected, see the *Summary Tables of Changes*.



### **AJ106. PMI While LBR Freeze Enabled May Result in Old/Out-of-date LBR Information**

**Problem:** When Precise Event-Based Sampling (PEBS) is configured with Performance Monitoring Interrupt (PMI) on PEBS buffer overflow enabled and Last Branch Record (LBR) Freeze on PMI enabled by setting FREEZE\_LBRS\_ON\_PMI flag (bit 11) to 1 in IA32\_DEBUGCTL (MSR 1D9H), the LBR stack is frozen upon the occurrence of a hardware PMI request. Due to this erratum, the LBR freeze may occur too soon (i.e. before the hardware PMI request).

**Implication:** Following a PMI occurrence, the PMI handler may observe old/out-of-date LBR information that does not describe the last few branches before the PEBS sample that triggered the PMI.

**Workaround:** None Identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ107. Overlap of an Intel® VT APIC Access Page in a Guest with the DS Save Area May Lead to Unpredictable Behavior**

**Problem:** Logging of a branch record or a PEBS (precise-event-based-sampling) record to the DS (debug store) save area that overlaps with the APIC access page may lead to unpredictable behavior.

**Implication:** Guest software configured to log branch records or PEBS records cannot specify the DS (debug store) save area within the APIC-access page. Under any expected usage model this type of overlap is not expected to exist. One should be aware of the fact that the specified DS address is of linear form while the APIC access page is of a physical form. Any solution that wishes to avoid this condition will need to comprehend the linear-to-physical translation of the DS related address pointers with respect to the mapping of the physical APIC access page to avoid such an overlap. Under normal circumstances for correctly written software, such an overlap is not expected to exist. Intel has not observed this erratum with any commercially available software.

**Workaround:** For a fully comprehensive workaround, the VMM should not allow the logging of branch or PEBS records while guest software is running if the "virtualize APIC accesses" VM-execution control is 1.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ108. Dual-Processor Incompatibility Between B-step and G-step**

**Problem:** Due to several feature differences, Dual-Processor (DP) systems mixing B-step and G-step some VT based virtualization SW that is not designed to run on mixed stepping systems may fail.

**Implication:** VT based virtualization SW running on DP Systems mixing B-step and G-step may fail.

It is possible for BIOS to contain a workaround for this erratum. Please contact your Intel sales representative to obtain a DP upgrade kit.


**Notes:** Once the workaround is applied to BIOS, the behavior of each processor will be modified as follows:

The B-step Processor (Stepping ID (CPUID.01H:EAX[bits 3-0]) = 06H):

- Will be designated as the BSP (Boot Strap Processor)
- Will not signal #GP when attempting to set bits 37-36 of MTRRphysMask MSRs

The G-step Processor (Stepping ID (CPUID.01H:EAX[bits 3-0]) = 0BH):

- Will report VMCS revision 6 or 7 to maintain compatibility with B-step
- Will fail if VMCS revision used to launch either VMXON or VMPTRLD instruction is not



identical to the VMCS revision reported. This check on VMCS revision ID will not be applied for a parallel VMentry - hence, software using parallel SMM monitor will fail.

- Will conform to B-Step Erratum AG87 behavior (AG87 is for Woodcrest, Clovertown must change this id to reflect its own id)

The following differences will still remain:

- The G-step processor will continue reporting G-step PerfMon capabilities (IA32\_PERF\_CAPABILITIES MSR will read 0C2H)
- The G-step processor will get a #GP when writing '1' to the reserved bits [63:31, 10, 6, 2] of IA32\_FIXED\_CTR\_CTRL MSR
- Only the G-step processor will support threshold-based error status (IA32\_MCG\_CAP [bit 11] = 1)
- Only the G-step processor will support threshold-based error status (IA32\_MCG\_CAP [bit 11] = 1)

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ109. VTPR Write Access During Event Delivery May Cause an APIC-Access VM Exit**

**Problem:** VTPR write accesses should not cause APIC-access VM exits but instead should cause data to be written to the virtual-APIC page. Due to this erratum, a VTPR write access during event delivery may cause an APIC-access VM exit with no data being written to the virtual-APIC page.

**Implication:** VTPR accesses are accesses to offset 80H on the APIC-access page. VTPR write accesses can occur during event delivery when pushing data on the stack. Because event delivery performs multiple stack pushes, an event delivery that includes a VTPR write access will also include at least one other write to the APIC-access page. That other write will cause an APIC-access VM exit. Thus, even in the presence of this erratum, any event delivery that includes a VTPR write access will cause an APIC-access VM exit. The only difference with respect to correct behavior will be with regard to page offset saved in the exit qualification by the APIC-access VM exit. A VMM should be able to emulate the event delivery correctly even with the incorrect offset.

**Workaround:** The VMM should emulate any event delivery that causes an APIC-access VM exit in the same way regardless of the offset saved in the exit qualification.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ110. BIST Failure After Reset**

**Problem:** The processor may show an erroneous BIST (built-in self test) result in bit [17] of EAX register when coming out of reset.


**Implication:** When this erratum occurs, an erroneous BIST failure will be reported in EAX bit [17]. This failure can be ignored since it is not accurate.

**Workaround:** It is possible for BIOS to workaround this erratum by masking off bit [17] of the EAX register after coming out of reset.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ111. Performance Monitoring Event FP\_MMX\_TRANS\_TO\_MMX May Not Count Some Transitions**

**Problem:** Performance Monitor Event FP\_MMX\_TRANS\_TO\_MMX (Event CCH, Umask 01H) counts transitions from x87 Floating Point (FP) to MMX™ instructions. Due to this erratum, if only a small number of MMX instructions (including EMMS) are executed immediately after the last FP instruction, a FP to MMX transition may not be counted.



**Implication:** The count value for Performance Monitoring Event FP\_MMX\_TRANS\_TO\_MMX may be lower than expected. The degree of undercounting is dependent on the occurrences of the erratum condition while the counter is active. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ112. Instruction Fetch May Cause a Livelock During Snoops of the L1 Data Cache**

**Problem:** A livelock may be observed in rare conditions when instruction fetch causes multiple level one data cache snoops.

**Implication:** Due to this erratum, a livelock may occur. Intel has not observed this erratum with any commercially available software.

**Workaround:** It is possible for BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ113. Use of Memory Aliasing with Inconsistent Memory Type may Cause a System Hang or a Machine Check Exception**

**Problem:** Software that implements memory aliasing by having more than one linear addresses mapped to the same physical page with different cache types may cause the system to hang or to report a machine check exception (MCE). This would occur if one of the addresses is non-cacheable and used in a code segment and the other is a cacheable address. If the cacheable address finds its way into the instruction cache, and the non-cacheable address is fetched in the IFU, the processor may invalidate the non-cacheable address from the fetch unit. Any micro-architectural event that causes instruction restart will be expecting this instruction to still be in the fetch unit and lack of it will cause a system hang or an MCE.

**Implication:** This erratum has not been observed with commercially available software.

**Workaround:** Although it is possible to have a single physical page mapped by two different linear addresses with different memory types, Intel has strongly discouraged this practice as it may lead to undefined results. Software that needs to implement memory aliasing should manage the memory type consistency.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ114. A WB Store Following a REP STOS/MOVS or FXSAVE May Lead to Memory-Ordering Violations**

**Problem:** Under certain conditions, as described in the Software Developers Manual section "Out-of-Order Stores For String Operations in Pentium 4, Intel Xeon, and P6 Family Processors", the processor may perform REP MOVS or REP STOS as write combining stores (referred to as "fast strings") for optimal performance. FXSAVE may also be internally implemented using write combining stores. Due to this erratum, stores of a WB (write back) memory type to a cache line previously written by a preceding fast string/FXSAVE instruction may be observed before string/FXSAVE stores.

**Implication:** A write-back store may be observed before a previous string or FXSAVE related store. Intel has not observed this erratum with any commercially available software.

**Workaround:** Software desiring strict ordering of string/FXSAVE operations relative to subsequent write-back stores should add an MFENCE or SFENCE instruction between the string/FXSAVE operation and following store-order sensitive code such as that used for synchronization.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



#### **AJ115. VM Exit with Exit Reason “TPR Below Threshold” Can Cause the Blocking by MOV/POP SS and Blocking by STI Bits to be Cleared in the Guest Interruptibility-State Field**

**Problem:** As specified in Section, “VM Exits Induced by the TPR Shadow”, in the *Intel® 64 and IA-32 Architectures Software Developer’s Manual, Volume 3B*, a VM exit occurs immediately after any VM entry performed with the “use TPR shadow”, “activate secondary controls”, and “virtualize APIC accesses” VM-execution controls all set to 1 and with the value of the TPR shadow (bits 7:4 in byte 80H of the virtual-APIC page) less than the TPR-threshold VM-execution control field. Due to this erratum, such a VM exit will clear bit 0 (blocking by STI) and bit 1 (blocking by MOV/POP SS) of the interruptibility-state field of the guest-state area of the VMCS (bit 0 - blocking by STI and bit 1 - blocking by MOV/POP SS should be left unmodified).

**Implication:** Since the STI, MOV SS, and POP SS instructions cannot modify the TPR shadow, bits 1:0 of the interruptibility-state field will usually be zero before any VM entry meeting the preconditions of this erratum; behavior is correct in this case. However, if VMM software raises the value of the TPR-threshold VM-execution control field above that of the TPR shadow while either of those bits is 1, incorrect behavior may result. This may lead to VMM software prematurely injecting an interrupt into a guest. Intel has not observed this erratum with any commercially available software.

**Workaround:** VMM software raising the value of the TPR-threshold VM-execution control field should compare it to the TPR shadow. If the threshold value is higher, software should not perform a VM entry; instead, it could perform the actions that it would normally take in response to a VM exit with exit reason “TPR below threshold”.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ116. Using Memory Type Aliasing with cacheable and WC Memory Types May Lead to Memory Ordering Violations**

**Problem:** Memory type aliasing occurs when a single physical page is mapped to two or more different linear addresses, each with different memory types. Memory type aliasing with a cacheable memory type and WC (write combining) may cause the processor to perform incorrect operations leading to memory ordering violations for WC operations.

**Implication:** Software that uses aliasing between cacheable and WC memory types may observe memory ordering errors within WC memory operations. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified. Intel does not support the use of cacheable and WC memory type aliasing, and WC operations are defined as weakly ordered.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ117. VM Exit due to Virtual APIC-Access May Clear RF**

**Problem:** RF (Resume Flag), bit 16 of the EFLAGS/RFLAGS register, is used to restart instruction execution without getting an instruction breakpoint on the instruction following a debug breakpoint exception. Due to this erratum, in a system supporting Intel® Virtualization Technology, when a VM Exit occurs due to Virtual APIC-Access (Advanced Programmable Interrupt Controller-Access) the EFLAGS/RFLAGS saved in the VMCS (Virtual-Machine Control Structure) may contain an RF value of 0.

**Implication:** When this erratum occurs, following a VM Exit due to a Virtual APIC-access, the processor may unintentionally break on the subsequent instruction after VM entry.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



### **AJ118. RSM Instruction Execution under Certain Conditions May Cause Processor Hang or Unexpected Instruction Execution Results**

**Problem:** RSM instruction execution, under certain conditions triggered by a complex sequence of internal processor micro-architectural events, may lead to processor hang, or unexpected instruction execution results.

**Implication:** In the above sequence, the processor may live lock or hang, or RSM instruction may restart the interrupted processor context through a nondeterministic EIP offset in the code segment, resulting in unexpected instruction execution, unexpected exceptions or system hang. Intel has not observed this erratum with any commercially available software.

**Workaround:** It is possible for the BIOS to contain a workaround for this erratum.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ119. NMIs May Not Be Blocked by a VM-Entry Failure**

**Problem:** The Intel® 64 and IA-32 Architectures Software Developer's Manual Volume 3B: System Programming Guide, Part 2 specifies that, following a VM-entry failure during or after loading guest state, "the state of blocking by NMI is what it was before VM entry." If non-maskable interrupts (NMIs) are blocked and the "virtual NMIs" VMexecution control set to 1, this erratum may result in NMIs not being blocked after a VM-entry failure during or after loading guest state.

**Implication:** VM-entry failures that cause NMIs to become unblocked may cause the processor to deliver an NMI to software that is not prepared for it.

**Workaround:** VMM software should configure the virtual-machine control structure (VMCS) so that VM-entry failures do not occur.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ120. Benign Exception after a Double Fault May Not Cause a Triple Fault Shutdown**

**Problem:** According to the Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A, "Exception and Interrupt Reference", if another exception occurs while attempting to call the double-fault handler, the processor enters shutdown mode. However due to this erratum, only Contributory Exceptions and Page Faults will cause a triple fault shutdown, whereas a benign exception may not.

**Implication:** If a benign exception occurs while attempting to call the double-fault handler, the processor may hang or may handle the benign exception. Intel has not observed this erratum with any commercially available software.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

### **AJ121. IA32\_MC1\_STATUS MSR Bit[60] Does Not Reflect Machine Check Error Reporting Enable Correctly**

**Problem:** IA32\_MC1\_STATUS MSR (405H) bit[60] (EN- Error Enabled) is supposed to indicate whether the enable bit in the IA32\_MC1\_CTL MSR (404H) was set at the time of the last update to the IA32\_MC1\_STATUS MSR. Due to this erratum, IA32\_MC1\_STATUS MSR bit[60] instead reports the current value of the IA32\_MC1\_CTL MSR enable bit.

**Implication:** IA32\_MC1\_STATUS MSR bit [60] may not reflect the correct state of the enable bit in the IA32\_MC1\_CTL MSR at the time of the last update.

**Workaround:** None Identified.

**Status:** For affected stepping see *Summary Table of Changes*.



#### **AJ122. A VM Exit Due to a Fault While Delivering a Software Interrupt May Save Incorrect Data into the VMCS**

**Problem:** If a fault occurs during delivery of a software interrupt (INTn) in virtual-8086 mode when virtual mode extensions are in effect and that fault causes a VM exit, incorrect data may be saved into the VMCS. Specifically, information about the software interrupt may not be reported in the IDT-vectoring information field. In addition, the interruptibility-state field may indicate blocking by STI or by MOV SS if such blocking were in effect before execution of the INTn instruction or before execution of the VM-entry instruction that injected the software interrupt.

**Implication:** In general, VMM software that follows the guidelines given in the section “Handling VM Exits Due to Exceptions” of Intel® 64 and IA-32 Architectures Software Developer’s Manual Volume 3B: System Programming Guide should not be affected. If the erratum improperly causes indication of blocking by STI or by MOV SS, the ability of a VMM to inject an interrupt may be delayed by one instruction.

**Workaround:** VMM software should follow the guidelines given in the section “Handling VM Exits Due to Exceptions” of Intel® 64 and IA-32 Architectures Software Developer’s Manual Volume 3B: System Programming Guide.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ123. A VM Exit Occuring in IA-32e Mode May Not Produce a VMX Abort When Expected**

**Problem:** If a VM exit occurs while the processor is in IA-32e mode and the “host address-space size” VM-exit control is 0, a VMX abort should occur. Due to this erratum, the expected VMX aborts may not occur and instead the VM Exit will occur normally. The conditions required to observe this erratum are a VM entry that returns from SMM with the “IA-32e guest” VM-entry control set to 1 in the SMM VMCS and the “host address-space size” VM-exit control cleared to 0 in the executive VMCS.

**Implication:** A VM Exit will occur when a VMX Abort was expected.

**Workaround:** An SMM VMM should always set the “IA-32e guest” VM-entry control in the SMM VMCS to be the value that was in the LMA bit (IA32\_EFER.LMA.LMA[bit 10]) in the IA32\_EFER MSR (C0000080H) at the time of the last SMM VM exit. If this guideline is followed, that value will be 1 only if the “host address-space size” VM-exit control is 1 in the executive VMCS.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ124. Not-Present Page Faults May Set the RSVD Flag in the Error Code**

**Problem:** Not-Present Page Faults May Set the RSVD Flag in the Error Code

**Implication:** Software may erroneously infer that a page fault was due to a reserved-bit violation when it was actually due to an attempt to access a not-present page. Intel has not observed this erratum with any commercially available software.

**Workaround:** Page-fault handlers should ignore the RSVD flag in the error code if the P flag is 0.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.

#### **AJ125. VM Exits Due to “NMI-Window Exiting” May Be Delayed by One Instruction**

**Problem:** If VM entry is executed with the “NMI-window exiting” VM-execution control set to 1, a VM exit with exit reason “NMI window” should occur before execution of any instruction if there is no virtual-NMI blocking, no blocking of events by MOV SS, and no blocking of events by STI. If VM entry is made with no virtual-NMI blocking but with blocking of events by either MOV SS or STI, such a VM exit should occur after execution of one instruction in VMX non-root operation. Due to this erratum, the VM exit may be delayed by one additional instruction.

**Implication:** VMM software using “NMI-window exiting” for NMI virtualization should generally be unaffected, as the erratum causes at most a one-instruction delay in the injection of a



virtual NMI, which is virtually asynchronous. The erratum may affect VMMs relying on deterministic delivery of the affected VM exits.

**Workaround:** None identified.

**Status:** For the steppings affected, see the *Summary Tables of Changes*.



# Specification Changes

---

The Specification Changes listed in this section apply to the following documents:

- Quad-Core Intel® Xeon® Processor 5300 Series Datasheet

## AJ1.

### **Implementation of System Management Range Registers**

This processor has implemented SMRRs (System Management Range Registers). SMRRs are defined in Section 10.11.2.4 of the Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide.

SMM (System Management Mode) code and data reside in SMRAM. The SMRR interface is an enhancement in Intel® 64 and IA-32 Architectures to limit cacheable reference of addresses in SMRAM to code running in SMM. The SMRR interface can be configured only by code running in SMM.

Under certain circumstances, an attacker who has gained administrative privileges, such as ring 0 privileges in a traditional operating system, may be able to reconfigure an Intel processor to gain access to SMM. The implementation of SMRR mitigates this issue. Intel has provided a recommended update to system and BIOS vendors to incorporate into their BIOS to resolve this issue.



# Specification Clarifications

---

The Specification Clarifications listed in this section apply to the following documents:

- Quad-Core Intel® Xeon® Processor 5300 Series Datasheet
- Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide

## **AJ1. Clarification of TRANSLATION LOOKASIDE BUFFERS (TLBS) Invalidation**

Section 10.9 INVALIDATING THE TRANSLATION LOOKASIDE BUFFERS (TLBS) of the Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide will be modified to include the presence of page table structure caches, such as the page directory cache, which Intel processors implement. This information is needed to aid operating systems in managing page table structure invalidations properly.

Intel will update the Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide in the coming months. Until that time, an application note, *TLBs, Paging-Structure Caches, and Their Invalidation* (<http://www.intel.com/products/processor/manuals/index.htm>), is available which provides more information on the paging structure caches and TLB invalidation. In rare instances, improper TLB invalidation may result in unpredictable system behavior, such as system hangs or incorrect data. Developers of operating systems should take this documentation into account when designing TLB invalidation algorithms. For the processors affected, Intel has provided a recommended update to system and BIOS vendors to incorporate into their BIOS to resolve this issue.

### **Affected Docs:**

Intel® 64 and IA-32 Architectures Software Developer's Manual, Volume 3A: System Programming Guide



## Documentation Changes

---

The Documentation Changes listed in this section apply to the following documents:  
Quad-Core Intel® Xeon® Processor 5300 Series Datasheet

All Documentation Changes will be incorporated into a future version of the appropriate Processor documentation.

Note: Documentation changes for Intel® 64 and IA-32 Architecture Software Developer's Manual volumes 1, 2A, 2B, 3A, and 3B will be posted in a separate document Intel® 64 and IA-32 Architecture Software Developer's Manual Documentation Changes. Follow the link below to become familiar with this file.  
<http://developer.intel.com/design/pentium4/manuals/indexnew>.

There are no new Documentation Changes in this Specification Update revision.

§