

Intel[®] 3200/3210 Chipset Memory Controller Hub (MCH)

Specification Update

May 2012



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. Intel products are not intended for use in medical, life saving, life sustaining, critical control or safety systems, or in nuclear facility applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.


The Intel® X38 Express Chipset Memory Controller Hub (MCH) may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Intel and the Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

*Other names and brands may be claimed as the property of others.


Copyright © 2012, Intel Corporation. All Rights Reserved.



Contents

1	Revision History	5
2	Preface	6
3	Summary Tables of Changes	7
4	Identification Information	9
5	Errata	10
6	Specification Changes	11
7	Specification Clarifications	11
8	Documentation Changes	11





1 *Revision History*

Revision	Description	Date
-001	<ul style="list-style-type: none">Initial Release	November 2007
-002	<ul style="list-style-type: none">Added Errata 2	December 2007
-003	<ul style="list-style-type: none">Updated parts information to include 65 nm process SKUs in the Identification Information section.	May 2012



2 Preface

This document is an update to the specifications contained in the [Affected Documents](#) table below. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in [Nomenclature](#) are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

2.1 Affected Documents

Document Title	Document Number/Location
Intel® 3200/3210 Chipset Memory Controller Hub (MCH) Datasheet	318463-001

2.2 Nomenclature


Errata are design defects or errors. These may cause the MCH's behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

Documentation Changes include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.

Note: Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).



3 Summary Tables of Changes

The following tables indicate the errata, specification changes, specification clarifications, or documentation changes which apply to the MCH product. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. These tables use the following notations:

3.1 Codes Used in Summary Tables

3.1.1 Stepping

X: Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.

(No mark)

or (Blank box): This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

3.1.2 Page

(Page): Page location of item in this document.

3.1.3 Status

Doc: Document change or update will be implemented.

Plan Fix: This erratum may be fixed in a future stepping of the product.

Fixed: This erratum has been previously fixed.

No Fix: There are no plans to fix this erratum.

3.1.4 Row

Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.



3.2 Errata

Number	Steppings		Status	ERRATA
	A0	A1		
1	X	X	No Fix	PCIe 1.1 cards in PCIe slots off the MCH lead to boot failures.
2	X	X	No Fix	IERR due to DMI/PCIe Link Not Trained

3.3 Specification Changes


No.	SPECIFICATION CHANGES
-	There are no Specification Changes in this Specification Update revision.

3.4 Specification Clarifications

No.	SPECIFICATION CLARIFICATIONS
-	There are no Specification Changes in this Specification Update revision.

3.5 Documentation Changes

No.	DOCUMENTATION CHANGES
-	There are no Documentation Changes in this Specification Update revision.



4 Identification Information

4.1 Component Marking Information

The Intel® 3200/3210 Chipset MCH stepping can be identified by the following component markings:

Stepping	Top Marking	Notes
A1	NU3210MC SLALH	Intel® 3210 Chipset MCH - Production
A1	NU3210MC SLJEF	Intel® 3210 Chipset MCH - Production ¹
A1	NU3200MC SLALG	Intel® 3200 Chipset MCH - Production

NOTES:

1. Manufactured on 65 nm process.

In future samples releases, Intel® 3210 Chipset MCH and Intel® 3200 Chipset MCH can be identified by the presence or absence of Bus 0, Device 6.

Stepping	Product
Intel® 3210 Chipset MCH	Present
Intel® 3200 Chipset MCH	Absent

5 Errata

1. PCIe 1.1 cards in PCIe slots off the MCH lead to boot failures.

Problem: The Intel® X38 Express Chipset sets the TS1 Ordered Set - Symbol 4 Bit[6] to 1b when a PCIe 1.1 card is plugged in. This is a reserved bit which is used in PCIe 2.0 to broadcast support for selectable de-emphasis. PCIe 1.1 Specification states that Bit[6] should be set to 0b. With some 2.5 GT/s PCIe 1.1 I/O cards of widths x8/x4/x1, system restarts and hangs were exhibited during PCIe link initialization when populated in MCH slots.

Implication: System unable to train some 2.5 GT/s PCIe 1.1 cards that don't comply with the PCIe 1.1 Specification. Failures have occurred across multiple vendors and different types of PCIe 1.1 cards.

Workaround: Contact your Intel field representative for the latest BIOS information. Modification to the Link Stability/Recovery Algorithm will fix this issue when using non-compliant cards but customers should continue working with their card vendors for PCIe 1.1 Spec compliance.

Status: No Fix. For affected steppings, see the Summary Table of Changes.

2. IERR due to DMI/PCIe Link Not Trained

Problem: The MCH has a rare meta-stability condition within the DMI/PCIe [3210: DMI/primary PCIe and secondary PCIe] receiver PLL divider circuitry. The MCH DMI/PCIe [3210: DMI/primary PCIe] receiver may not be locked at the correct internal clock phase during warm or cold reset - causing the DMI [3210: DMI/primary PCIe] link to not train. [3210: The MCH secondary PCIe receiver may not be locked - causing the secondary PCIe link to not train. Each lock independently.] If the DMI/PCIe receiver divider locked to the correct clock phase, the receiver divider stays locked - and the DMI/PCIe [3210: DMI/primary PCIe and secondary PCIe] link stays trained - until the next warm or cold reset.


Implication:

- If the rare meta-stability condition occurs, the processor may assert IERR due to traffic across the DMI link not completing. If the ICH Watch Dog Timer is enabled, the timer will time out and reboot the system. On the subsequent reset, the DMI/PCIe [3210: DMI/primary PCIe] receiver may lock at the correct phase - and normal operation continues.
- In the extremely rare event that meta-stability occurs on back-to-back resets, the system could hang due to the DMI link not being trained. The Watch Dog Timer has timed out once, and would not timeout again to reboot the system. Intel has not observed the occurrence of back-to-back meta-stable conditions.
- [3210: If the rare meta-stability condition occurs on the secondary PCIe receiver PLL divider circuitry, a PCIe add-in card present in the slot would not be trained.]

Workaround:

- BIOS enable ICH Watch Dog Timer. If an external BMC is present, the BMC should ignore IERR during reset and POST. See latest Intel® X38 Express Chipset Family and 3200/3210 Chipset Family BIOS Specification for proper handling of ignoring IERR.
- [3210: If a PCIe add-in card is present but not trained, BIOS resets the secondary PCIe link to retrain the card. See latest BIOS specification.]

Status: No Fix.



6 *Specification Changes*

There are no Specification Changes in this Specification Update revision.

7 *Specification Clarifications*

There are no Specification Clarifications in this Specification Update revision.

8 *Documentation Changes*

There are no Documentation Changes in this Specification Update revision.

§

