

# Intel<sup>®</sup> X48 Express Chipset Memory Controller Hub (MCH)

Specification Update

---

*March 2008*



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL® PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER, AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT. Intel products are not intended for use in medical, life saving, life sustaining, critical control or safety systems, or in nuclear facility applications.

Intel may make changes to specifications and product descriptions at any time, without notice.

Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights.

Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them.

The Intel® X48 Express Chipset Memory Controller Hub (MCH) may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature may be obtained by calling 1-800-548-4725 or by visiting Intel's website at <http://www.intel.com>.

Intel and the Intel logo are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

\*Other names and brands may be claimed as the property of others.

Copyright © 2008, Intel Corporation. All Rights Reserved.



## Contents

---

<b>Preface</b> .....	5
<b>Summary Tables of Changes</b> .....	6
<b>Identification Information</b> .....	8
<b>Errata</b> .....	9
<b>Specification Changes</b> .....	11
<b>Specification Clarifications</b> .....	12
<b>Documentation Changes</b> .....	13




## Revision History

---

Revision	Description	Date
-001	• Initial Release	March 2008

§ §



## Preface

---

This document is an update to the specifications contained in the [Affected Documents](#) table below. This document is a compilation of device and documentation errata, specification clarifications and changes. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools.

Information types defined in [Nomenclature](#) are consolidated into the specification update and are no longer published in other documents.

This document may also contain information that was not previously published.

## Affected Documents

Title	Number
Intel® X48 Express Chipset Memory Controller Hub (MCH) Datasheet	319122-001

## Nomenclature

**Errata** are design defects or errors. These may cause the Intel X48 Express Chipset MCH's behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

**Specification Changes** are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

**Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

**Documentation Changes** include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.

*Note:* Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, etc.).



## Summary Tables of Changes

---

The following tables indicate the errata, specification changes, specification clarifications, or documentation changes which apply to the MCH product. Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. These tables use the following notations.

### Codes Used in Summary Tables

#### Stepping

- X: Errata exists in the stepping indicated. Specification Change or Clarification that applies to this stepping.
- (No mark)  
or (Blank box): This erratum is fixed in listed stepping or specification change does not apply to listed stepping.

#### Page


- (Page): Page location of item in this document.

#### Status

- Doc: Document change or update will be implemented.
- Plan Fix: This erratum may be fixed in a future stepping of the product.
- Fixed: This erratum has been previously fixed.
- No Fix: There are no plans to fix this erratum.

#### Row

- | Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.



## Errata

Number	Steppings	Status	ERRATA
	A1		
1	X	No Fix	PCIe 1.1 cards in PCIe slots off the MCH lead to boot failures
2	X	No Fix	Intermittent IERR# hangs during cold boot does not detect PCIe cards
3	X	No Fix	IERR due to DMI/PCIe Link Not Trained

## Specification Changes

No.	SPECIFICATION CHANGES
	There are no Specification Changes in this Specification Update revision.

## Specification Clarifications

No.	SPECIFICATION CLARIFICATIONS
	There are no Specification Clarifications in this Specification Update revision.

## Documentation Changes

No.	DOCUMENTATION CHANGES
	There are no Documentation Changes in this Specification Update revision.



## Identification Information

---

### Component Identification via Programming Interface

The Intel® X48 Express Chipset MCH stepping can be identified by the following register contents:

Stepping	Vendor ID <sup>1</sup>	Device ID <sup>2</sup>	Revision ID <sup>3</sup>	Notes
A1	8086h	29E0	01h	

**Notes:**

1. The Vendor ID corresponds to bits 15:0 of the Vendor ID Register located at offset 00-01h in the PCI function 0 configuration space.
2. The Device ID corresponds to bits 15:0 of the Device ID Register located at offset 02-03h in the PCI function 0 configuration space.
3. The Revision Number corresponds to bits 7:0 of the Revision ID Register located at offset 08h in the PCI function 0 configuration space.
4. The Intel® X48 Express Chipset MCH and Intel® X38 Express chipset MCH share the same Device ID. The CAPID0 (Capability Register, bit 89) is used to determine the differences between both chipsets. See the CAPID0 (Capability Register) in the datasheet for additional component identification details.

### Component Marking Information

The Intel® X48 Express Chipset MCH stepping can be identified by the following component markings:

Stepping	S-Spec	Top Marking	Notes
A1	SLASF	NU82X48	MCH Production Sample





## Errata

---

### 1. PCIe 1.1 Cards in PCIe Slots off the MCH Lead to Boot Failures

**Problem:** The Intel X48 Express Chipset sets the TS1 Ordered Set - Symbol 4 Bit[6] to 1b when a PCIe 1.1 card is plugged in. This is a reserved bit which is used in PCIe 2.0 to broadcast support for selectable de-emphasis. PCIe 1.1 Specification states that Bit[6] should be set to 0b. With some 2.5 GT/s PCIe 1.1 I/O cards of widths x8/x4/x1, system restarts and hangs were exhibited during PCIe link initialization when populated in MCH slots.

**Implication:** System unable to train some 2.5 GT/s PCIe 1.1 cards that don't comply with the PCIe 1.1 Specification. Failures have occurred across multiple vendors and different types of PCIe 1.1 cards.

**Workaround:** See latest Bearlake Chipset BIOS Specification (Revision 2.1 or later) for more information. Modification to the Link Stability/Recovery Algorithm will fix this issue when using non-compliant cards but customers should continue working with their card vendors for PCIe 1.1 Spec compliancy.

**Status:** For affected steppings, see the Summary Table of Changes.

### 2. Intermittent IERR# Hangs During Cold Boot Does Not Detect PCIe Cards

**Problem:** During cold boots, the MCH may hang during power-on and assert IERR or may not detect PCIe cards off the primary port or secondary port. The 1.8V on-die voltage regulator which powers the PCIe & DMI PLL may not be stable when powering on, causing above issues.

**Implication:** PLL not operating correctly could result in not detecting PCIe cards or DMI may not operate correctly, resulting in system hang and IERR# assertion.

**Workaround:** Motherboard designers are required to implement board changes:

- Require 1.25V through LC filter on MCH VCCAPLL\_EXT (Ball A20) & VCCAPLL\_EXT2 (Ball AR10).
- Require 1.25V on MCH VCC\_EXP\_PLL (Ball AB13).
- BIOS must disable 1.8V on-die VR. Contact your Intel field representative for the latest BIOS information.

**Status:** For affected steppings, see the Summary Table of Changes.



### 3. IERR due to DMI/PCIe Link Not Trained

**Problem:** The MCH has a rare meta-stability condition within the DMI/primary PCIe and secondary PCIe receiver PLL divider circuitry. The MCH DMI/primary PCIe receiver may not be locked at the correct internal clock phase during warm or cold reset - causing the DMI/primary PCIe link to not train. The MCH secondary PCIe receiver may not be locked - causing the secondary PCIe link to not train. Each lock independently. If the DMI/PCIe receiver divider locked the correct clock phase, the receiver divider stays locked - and the link stays trained - until the next warm or cold reset.

**Implication:**

- If the rare meta-stability condition occurs, the processor may assert IERR due to traffic across the DMI link not completing. If the ICH Watch Dog Timer is enabled, the timer will time out and reboot the system. On the subsequent reset, the DMI/primary PCIe receiver may lock at the correct phase - and normal operation continues.
- In the extremely rare event that meta-stability occurs on back-to-back resets, the system could hang due to the DMI link not being trained. The Watch Dog Timer has timed out once, and would not timeout again to reboot the system. Intel has not observed the occurrence of back-to-back meta-stable conditions.
- If the rare meta-stability condition occurs when the system is in ACPI S3 state, data saved in memory may be lost.
- If the rare meta-stability condition occurs on the secondary PCIe receiver PLL divider circuitry, a PCIe add-in card present in the slot would not be trained.

**Workaround:**

- BIOS enable ICH Watch Dog Tiimer.
- If a PCIe add-in card is present but not trained, the BIOS resets the secondary PCIe link to retrain the card. Contact your Intel field representative for the latest BIOS information.
- There is no workaround for S3. However, the occurrence of this meta-stability condition during resume from S3 is rare.

**Status:** For affected steppings, see the Summary Table of Changes.



## **Specification Changes**

---

There are no Specification Changes in this Specification Update revision.



## **Specification Clarifications**

---

There are no Specification Clarifications in this Specification Update revision.



## Documentation Changes

---

There are no Documentation Changes in this Specification Update revision.

§ §

