



Motherboard Logo Program (MLP)

**Intel® Desktop Board**

**DX79TO**

---

**MLP Report**

11/9/2011

**Purpose:**

This report describes the DX79TO Motherboard Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel® Core™ i7 and Intel® are trademarks of Intel Corporation in the U.S. and other countries.

\*Other names and brands may be claimed as the property of others

Copyright © 2009, Intel Corporation. All rights reserved.

# Contents

---

- Introduction .....4**
  - Terms and Definitions..... 4
- Desktop Board Configuration .....5**
  - Desktop Board DX79T0 Final Configuration Report: Completion of MLP ..... 5
    - Board Information..... 5
    - Product Code..... 5
    - Processor ..... 5
    - Motherboard ..... 5
    - System Memory..... 5
    - Power Management..... 5
    - Operating System Tested..... 5
    - Onboard Integrated Devices and Driver for Vista 32-bit and 64-bit ..... 6
    - Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit..... 7
  - Windows Logo Kits Used (WLK) ..... 7
  - Errata and Contingencies ..... 8
  - Test Notes ..... 12

# Introduction

---

## Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
WLK	Windows Logo Kits
MLP	Motherboard Logo Program. For further information see: <a href="http://www.microsoft.com/whdc/hwtest/default.msp">http://www.microsoft.com/whdc/hwtest/default.msp</a>
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: <a href="http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;q=s">http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;q=s</a>

# Desktop Board Configuration

---

## Desktop Board DX79T0 Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

### Board Information

Product Code <sup>1</sup>	BIOS String/Model	Technologies NOT Logo'd (yet)
DX79T0	SIX7910J.86A.0281.2011.1019.1612	N/A - all technologies logo'd
<b>Processor</b>		
Speed	3.30GHz	
Family	Intel(R) Core(TM) i7-3960X	
Bus Speed	4 GB/s (DMI 2.0)	
<b>Motherboard</b>		
Board AA #	AA G28805-300	
Board FAB #	C	
<a href="#">* This report applies to the production FAB revision; Please consult your Intel Corporation representative to clarify the motherboard revision you intend to perform logo testing if not the same.</a>		
<b>System Memory</b>		
Speed	Dual Channel, DDR3, 1600MHz	
Memory Type	DIMM	
Connector Type	DDR3, 240 Pin	
<b>Power Management</b>		
BIOS Default	S3	
<b>Operating System Tested</b>		
	<b>Check Tested</b>	<b>Comments</b>
Windows 7 and 64-bit	<input checked="" type="checkbox"/>	Windows 7 Ultimate with Service Pack 1
Windows Vista and 64-bit	<input checked="" type="checkbox"/>	Vista Ultimate with Service Pack 2
Windows Vista Basic and 64-bit	<input type="checkbox"/>	Vista Basic with Service Pack 2

---

<sup>1</sup> These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

## Onboard Integrated Devices and Driver for Vista 32-bit and 64-bit

Technology	OS	Version	Package version
<b>Chipset Update Utility</b> Intel® Chipset Software Utility	Windows Vista	V 9.2.3.1022	INF_allIOS_9.2.3.1022_PV
	Windows Vista 64-bit	V 9.2.3.1022	INF_allIOS_9.2.3.1022_PV
<b>Audio</b> Realtek High Definition Audio	Windows Vista	V 6.0.1.6449	6449_PG334_R265_Win7_Vista_XP
	Windows Vista 64-bit	V 6.0.1.6449	6449_PG334_R265_Win7_Vista_XP
<b>LAN</b> Intel(R) 82579LM Gigabit Network Connection	Windows Vista	V 11.13.51.0	LAN_allIOS_11.13.51.0_PV
	Windows Vista 64-bit	V 11.13.51.0	LAN_allIOS_11.13.51.0_PV
<b>ME</b> Intel(R) Management Engine Interface	Windows Vista	V7.1.21.1134	MEI_allIOS_7.1.21.1134_PV
	Windows Vista 64-bit	V7.1.21.1134	MEI_allIOS_7.1.21.1134_PV
<b>CIR</b> Nuvoton W836x7HG CIR Device Driver	Windows Vista	V1.8.2009.514	CIR_Vista_1.8.2009.0514_PV
	Windows Vista 64-bit	V1.8.2009.514	CIR_Vista_1.8.2009.0514_PV
<b>USB 3.0</b> Renesas Electronics USB 3.0 Host Controller	Windows Vista	V2.1.19.0	USB3_allIOS_2.1.19.0_PV
	Windows Vista 64-bit	V2.1.19.0	USB3_allIOS_2.1.19.0_PV
<b>RSTE</b> Intel(R) C600 Series Chipset SATA AHCI Controller	Windows Vista	V3.0.0.1112	RSTE_Vista_Win7_3.0.0.1112_PV
	Windows Vista 64-bit	V3.0.0.1112	RSTE_Vista_Win7_3.0.0.1112_PV

## Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit

Technology	6	Version	Package version
<b>Chipset Update Utility</b> Intel® Chipset Software Utility	Windows Windows7	V 9.2.3.1022	INF_allIOS_9.2.3.1022_PV
	Windows Windows7 64-bit	V 9.2.3.1022	INF_allIOS_9.2.3.1022_PV
<b>Audio</b> Realtek High Definition Audio	Windows Windows7	Windows Vista V6.0.1.6449	6449_PG334_R265_W in7_Vista_XP
	Windows Windows7 64-bit	Windows Vista 64-bit V6.0.1.6449	6449_PG334_R265_W in7_Vista_XP
<b>LAN</b> intel(R) 82579LM Gigabit Network Connection	Windows Windows7	Windows Vista V11.13.51.0	LAN_allIOS_11.13.51.0_PV
	Windows Windows7 64-bit	Windows Vista 64-bit V11.13.51.0	LAN_allIOS_11.13.51.0_PV
<b>ME</b> Intel(R) Management Engine Interface	Windows Windows7	Windows Vista V7.1.21.1134	MEI_allIOS_7.1.21.1134_PV
	Windows Windows7 64-bit	Windows Vista 64-bit V7.1.21.1134	MEI_allIOS_7.1.21.1134_PV
<b>CIR</b> Nuvoton W836x7HG CIR Device Driver	Windows Windows7	Windows Vista V2.2.2011.128	CIR_Win7_2.2.2011.128_PV
	Windows Windows7 64-bit	Windows Vista 64-bit V2.2.2011.128	CIR_Win7_2.2.2011.128_PV
<b>USB 3.0</b> Renesas Electronics USB 3.0 Host Controller	Windows Windows7	Windows Vista V2.1.19.0	USB3_allIOS_2.1.19.0_PV
	Windows Windows7 64-bit	Windows Vista 64-bit V2.1.19.0	USB3_allIOS_2.1.19.0_PV
<b>RSTE</b> Intel(R) C600 Series Chipset SATA AHCI Controller	Windows Windows7	Windows Vista V3.0.0.1112	RSTE_Vista_Win7_3.0.0.1112_PV
	Windows Windows7 64-bit	Windows Vista 64-bit V3.0.0.1112	RSTE_Vista_Win7_3.0.0.1112_PV

## Windows Logo Kits Used (WLK)

Microsoft website: <http://www.microsoft.com/whdc/DevTools/WDK/DTM.msp>

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit
Windows 7 Windows 7 64-bit	<a href="#">WLK1.6 for Windows 7 SP1</a>	<a href="#">WLK1.6 for Windows 7 SP1</a>
Windows Vista Windows Vista 64-bit	<a href="#">WLK1.6 for Windows Vista SP2</a>	<a href="#">WLK1.6 for Windows Vista SP2</a>

## Errata and Contingencies

Operating System	Failing Test	Expiry Date	ID Number	Type	Error Description
Windows Vista Windows Vista 64bit	HDAudio Class Driver Fidelity Test - Vista (System, Manual)	7/31/2015	598	Erratum	The European Union requires the headphone output level to be $\leq 150$ mVrms for headphone jacks. There's a note in WLP requirement AUDIO-0006 that states, in the presence of regional regulations, the output level requirement for headphones is dropped from $\geq 1000$ mVrms to $\geq 120$ mVrms. This provides freedom for manufacturers to meet both the EU $\leq 150$ mVrms @ 32 Ohms and the WLP $\geq 120$ mVrms @ 32 Ohms requirements. The Fidelity Test tests headphones at 300 Ohm load, though. Without knowledge of the output impedance at the jack, the test cannot extrapolate what the output level at 32 Ohms would have been from the output level at 300 Ohms. The test assumes that the output level at 32 Ohms will be *less* than the output level at 300 Ohms, though. So any measurement $\geq 120$ mVrms at 300 Ohms "could be" a passing result, depending on the output impedance.
Windows Vista Windows Vista 64bit	PCI Hardware Compliance Test For Systems	12/1/2012	528	Erratum	Assertion 5FC5B29C-0F24-423B-856A-87C9E31C6802 Bit 14 (Completion Timeout Mask) in the Uncorrectable Error Mask register (offset 8h) in the Advanced Error Reporting Capability table must be read-writable . Assertion 908C881D-29ED-4B57-A1A6-BE1DBD45522E Bit 14 (Completion Timeout Error Severity) in the Uncorrectable Error Severity register (offset Ch) in the Advanced Error Reporting Capability table must be read-writable . These failures are incorrect for PCI Express switch ports that do not issue Non-Posted Requests on their own behalf (vs. only forwarding such Requests generated by other devices).
Windows Vista Windows Vista 64bit	PCI Hardware Compliance Test For Systems	12/1/2012	401	Erratum	The following PCI Compliance test failure is acceptable: Bit 15 (Bridge Configuration Retry Enable) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-only and always return 0 as it is reserved for devices other than PCI Express to PCI/PCI-X Bridges. Assertion 13A41D3E-2576-41DC-A67C-525DA3637CEA This failure is acceptable because this is a PCIe 1.1 feature and the WLP requires compliance with only PCIe 1.0a.
Windows Vista Windows Vista 64bit	PCI Hardware Compliance Test For Systems	12/1/2012	2051	Erratum	PCIHCT - Bit range 11:10 (ASPM Support)in the Link Capabilities register (offset Ch) in the PCI Express Capability table is 0h. It cannot be in the set of values {0x0, 0x2}. (Assertion 5CAF4993-B8D1-4E4E-99EC-CC5895364E32)



Operating System	Falling Test	Expiry Date	ID Number	Type	Error Description
Windows Vista Windows Vista 64bit	PCI Hardware Compliance Test For Systems	12/1/2012	2066	Erratum	<h3 xmlns="http://www.w3.org/1999/xhtml">Assertion 3CDD17AF-215E-4921-894F-C99434A3B3CA </h3> Bit range 31:21 (Reserved_3)in the Uncorrectable Error Mask register (offset 8h) in the Advanced Error Reporting Capability table must be read-only and always return 0 . <h3 xmlns="http://www.w3.org/1999/xhtml">Assertion 461CA4DE-9266-4420-9B5F-F33622A5D02B</h3> Bit range 31:21 (Reserved_3)in the Uncorrectable Error Severity register (offset Ch) in the Advanced Error Reporting Capability table must be read-only and always return 0 .
Windows Vista Windows Vista 64bit	PCI Hardware Compliance Test For Systems	12/1/2012	1167	Erratum	Assertion EB8AA49D-4825-4542-B549-289F1076C0F9 Bit range 23:21 (Reserved)in the Link Capabilities register (offset Ch) in the PCI Express Capability table must be read-only and always return 0 . It was found to return 1.
Windows Vista Windows Vista 64bit	PCI Hardware Compliance Test For Systems	12/1/2012	1241	Erratum	This happens because the PCI Compliance test assumes that if the Data Link Layer Link Active Reporting Capable bit in the Link Capabilities register for a given PCIe port is set then that indicates that the Data Link Layer Link Active bit will also be set. This is an incorrect assumption because the Data Link Layer Link Active bit can be reset when there is no device below the port. This assertion needs to be removed from the PCIHCT. The current architecture of the PCIHCT prevents it from knowing whether devices exist below a bridge/port.
Windows Vista Windows Vista 64bit	PCI Hardware Compliance Test For Systems	12/1/2012	1650	Erratum	Assertion 2C79B356-6B37-4BEC-8F4E-DD6588082AC2 Bit range 31:14 (Reserved_3)in the Correctable Error Mask register (offset 14h) in the Advanced Error Reporting Capability table must be read-only and always return 0 .
Windows Vista Windows Vista 64bit	PCI Hardware Compliance Test For Systems	12/1/2012	923	Erratum	Assertion FAE18121-9177-4FB2-A081-0D04C285EFF2 Bit range 15:0 (Extended Capability ID)in the Enhanced Capability Header register (offset 0h) in the Unrecognized Enhanced Capability ID 13 table is Dh. It must be in the range [0x0 - 0xB] as all other Capability IDs are reserved.
Windows Vista Windows Vista 64bit	UAA Test - Vista or Server08 (System)	6/1/2015	513	Erratum	UAA Test requires the Traffic Priority bit to be read/write - however there are two specs that apply, and they conflict. One says the bit must be read/write, the other says it must be read-only. Contact has been made with the author of both specs (Intel) but until this point is clarified we cannot fail submissions containing this test failure.
Windows Vista Windows Vista 64bit	USB Host Controller Compliance (Automated)	12/1/2012	1787	Erratum	Errata 1787 This Preview Test is being filtered until the expiration date of this Errata. After the expiration date of this filter these failures must be fixed to have a passing submission. Microsoft strongly recommends that these errors be investigated prior to this test or job being required for submission. XHCI spec compliance test is in preview

Operating System	Failing Test	Expiry Date	ID Number	Type	Error Description
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/1/2012	528	Erratum	Assertion 5FC5B29C-0F24-423B-856A-87C9E31C6802 Bit 14 (Completion Timeout Mask) in the Uncorrectable Error Mask register (offset 8h) in the Advanced Error Reporting Capability table must be read-writable . Assertion 908C881D-29ED-4B57-A1A6-BE1DBD45522E Bit 14 (Completion Timeout Error Severity) in the Uncorrectable Error Severity register (offset Ch) in the Advanced Error Reporting Capability table must be read-writable . These failures are incorrect for PCI Express switch ports that do not issue Non-Posted Requests on their own behalf (vs. only forwarding such Requests generated by other devices).
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/1/2012	401	Erratum	The following PCI Compliance test failure is acceptable: Bit 15 (Bridge Configuration Retry Enable) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-only and always return 0 as it is reserved for devices other than PCI Express to PCI/PCI-X Bridges. Assertion 13A41D3E-2576-41DC-A67C-525DA3637CEA This failure is acceptable because this is a PCIe 1.1 feature and the WLP requires compliance with only PCIe 1.0a.
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/1/2012	2051	Erratum	PCIHCT - Bit range 11:10 (ASPM Support)in the Link Capabilities register (offset Ch) in the PCI Express Capability table is 0h. It cannot be in the set of values {0x0, 0x2}. (Assertion 5CAF4993-B8D1-4E4E-99EC-CC5895364E32)

Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/1/2012	2066	Erratum	<h3 xmlns="http://www.w3.org/1999/xhtml">Assertion 3CDD17AF-215E-4921-894F-C99434A3B3CA </h3> Bit range 31:21 (Reserved_3)in the Uncorrectable Error Mask register (offset 8h) in the Advanced Error Reporting Capability table must be read-only and always return 0 . <h3 xmlns="http://www.w3.org/1999/xhtml">Assertion 461CA4DE-9266-4420-9B5F-F33622A5D02B</h3> Bit range 31:21 (Reserved_3)in the Uncorrectable Error Severity register (offset Ch) in the Advanced Error Reporting Capability table must be read-only and always return 0 .
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/1/2012	1167	Erratum	Assertion EB8AA49D-4825-4542-B549-289F1076C0F9 Bit range 23:21 (Reserved)in the Link Capabilities register (offset Ch) in the PCI Express Capability table must be read-only and always return 0 . It was found to return 1.
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/1/2012	1241	Erratum	This happens because the PCI Compliance test assumes that if the Data Link Layer Link Active Reporting Capable bit in the Link Capabilities register for a given PCIe port is set then that indicates that the Data Link Layer Link Active bit will also be set. This is an incorrect assumption because the Data Link Layer Link Active bit can be reset when there is no device below the port. This assertion needs to be removed from the PCIHCT. The current architecture of the PCIHCT prevents it from knowing whether devices exist below a bridge/port.
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/1/2012	1650	Erratum	Assertion 2C79B356-6B37-4BEC-8F4E-DD6588082AC2 Bit range 31:14 (Reserved_3)in the Correctable Error Mask register (offset 14h) in the Advanced Error Reporting Capability table must be read-only and always return 0 .
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/1/2012	923	Erratum	Assertion FAE18121-9177-4FB2-A081-0D04C285EFF2 Bit range 15:0 (Extended Capability ID)in the Enhanced Capability Header register (offset 0h) in the Unrecognized Enhanced Capability ID 13 table is Dh. It must be in the range [0x0 - 0xB] as all other Capability IDs are reserved.
Windows 7 Windows 7 64-bit	UAA Test - Win7 (System)	6/1/2015	513	Erratum	UAA Test requires the Traffic Priority bit to be read/write - however there are two specs that apply, and they conflict. One says the bit must be read/write, the other says it must be read-only. Contact has been made with the author of both specs (Intel) but until this point is clarified we cannot fail submissions containing this test failure.
Windows 7 Windows 7 64-bit	USB Host Controller Compliance (Automated)	12/1/2012	1787	Erratum	Errata 1787 This Preview Test is being filtered until the expiration date of this Errata. After the expiration date of this filter these failures must be fixed to have a passing submission. Microsoft strongly recommends that these errors be investigated prior to this test or job being required for submission. XHCI spec compliance test is in preview

## Test Notes

Operating System	Test	Description
Windows 7 and Vista	BIOS download	Internal: <a href="http://bios.intel.com/downloads/">http://bios.intel.com/downloads/</a> External: <a href="http://www.intel.com/">http://www.intel.com/</a> click on Support and Download
Windows 7 and Vista	BIOS setup	Please make sure the BIOS setting are as below, otherwise use default settings.  System Date and Time: Current date and time Peripheral Configuration: Enable all onboard component Drive Configuration: Set to AHCI Chipset Configuration: Enable HPET ACPI Suspend State: Set to <S3 State> Boot Device Priority: set <Hard Disk Driver> to first
Windows 7 and Vista filter update	WLK WHQL test	<a href="http://winqual.microsoft.com/member/SubmissionWizard/LegalExemptions/filterupdates.cab">http://winqual.microsoft.com/member/SubmissionWizard/LegalExemptions/filterupdates.cab</a>
Special H/W that use to PASS the test	None	None