



This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-1125

5200 NE Elam Young Parkway
Hillsboro, OR 97124

August 01, 2017

Intel® Server Board S2600WF, S2600BP and S2600ST Product Family fail to initialize the operating system video driver for the ASPEED* Base Management Controller (BMC)

Affected Products

Product Code	MM#
S2600WFT	952641
S2600WFO	952644
S2600WFQ	952645
S2600BPB	948899
S2600BPQ	948900
S2600BPS	952609
S2600STB	957180
S2600STQ	957318

Description

Intel® has discovered an issue in which the host fails to initialize the operating system video driver for the ASPEED* Baseboard Management Controller (BMC). Headless or remote management environments are not affected.

On different Linux* distributions the failure might be displayed as a **CPU soft lockup** message as shown in the example below:

```
[ OK ] Reached target Paths.
[ OK ] Reached target Basic System.
Mounting Configuration File System...
[ OK ] Mounted Configuration File System.
[ 36.219792] BUG: soft lockup - CPU#3 stuck for 22s! [migration/3:918]
[ 36.233800] BUG: soft lockup - CPU#4 stuck for 22s! [migration/4:923]
[ 36.247806] BUG: soft lockup - CPU#5 stuck for 22s! [migration/5:928]
[ 36.321831] BUG: soft lockup - CPU#6 stuck for 22s! [systemd-udevd:1538]
[ 36.335837] BUG: soft lockup - CPU#7 stuck for 22s! [migration/7:938]
[ 36.349842] BUG: soft lockup - CPU#8 stuck for 22s! [migration/8:943]
[ 36.363847] BUG: soft lockup - CPU#9 stuck for 22s! [migration/9:948]
[ 36.377852] BUG: soft lockup - CPU#10 stuck for 22s! [migration/10:953]
[ 36.391857] BUG: soft lockup - CPU#11 stuck for 22s! [migration/11:958]
[ 40.193314] BUG: soft lockup - CPU#1 stuck for 22s! [migration/1:908]
[ 40.193316] BUG: soft lockup - CPU#0 stuck for 22s! [migration/0:7]
```

Root Cause

Full root cause of this issue has been determined. Intel has confirmed that the failure has no bearing on system performance, it only impacts local video graphics. In detail, when the operating system loads, the OS-embedded ASPEED* video driver is not able to access a portion of the BMC memory space, therefore the process stalls.

Corrective Action

This issue is resolved at the driver level.

ASPEED* released an updated driver version v1.03 (<https://www.aspeedtech.com/support.php>) that corrects the failure for multiple operating systems. More details in the next section.

Red Hat*Enterprise Linux* will include the driver update in RHEL* v7.4

SUSE* Linux* Enterprise Server will include the driver update in SLES* v12 SP3

Ubuntu* Server will include the driver update in Ubuntu* v16.04.3 and v17.04

Recommended Customer Action / Workaround

Intel® developed a set of Installation Guides with step-by-step instructions to workaround this issue and to load the updated ASPEED* video driver v1.03. Please refer to these documents already included in every System Update Package (firmware) release.

The following are simple guidelines for three common operating systems:

Red Hat* Enterprise Linux* v7.3

1. Append the text `modprobe.blacklist=ast` before the `quiet` option at the end of the `linuxefi` line in the GRUB boot loader option
2. Upgrade the ASPEED* video driver

SUSE* Linux* Enterprise Server v12 SP2

1. Append the text `modprobe.blacklist=ast` at the end of the `linuxefi` line in the GRUB boot loader option
2. Upgrade the ASPEED* video driver

Microsoft* Windows* Server 2016

1. Windows built-in video driver will display graphics
2. Upgrade the ASPEED* video driver

If local video graphics features are not required, the driver update is not required in these environments.

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel Corporation