

Intel® Pentium® Processor N3500-series, J2850, J2900 and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750

Specification Update

April 2019



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting: <http://www.intel.com/design/literature.htm>

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Learn more at <http://www.intel.com/> or from the OEM or retailer.

No computer system can be absolutely secure.

Intel, Celeron, Pentium, and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.


*Other names and brands may be claimed as the property of others.

Copyright © 2019, Intel Corporation. All rights reserved.



Revision History

Date	Revision	Description
April 2019	021	<ul style="list-style-type: none"> Updated Specification Clarifications table Updated Specification Clarifications section Remove duplicate Errata in VLP71 and VLP84 and replace with two missing Errata. Updated Errata Summary Table Updated Related Documents section
December 2018	020	<ul style="list-style-type: none"> Added Errata VLP85 Updated Documentation Changes table Updated Specification Changes section Updated Documentation Changes Section
February 2018	019	<ul style="list-style-type: none"> Revised Errata VLP71
January 2018	018	<ul style="list-style-type: none"> Updated Errata Summary Table Revised Errata VLP52 Added Errata VLP84 Added Figure 65 to Specification Changes #2
November 2017	017	<ul style="list-style-type: none"> Updated errata VLP62 Added PCU-SPI AC Specification in chapter Specification Changes
October 2017	016	<ul style="list-style-type: none"> Removed legal disclaimer from title page and entered on legal disclaimer page Updated Identification Information Table Updated Errata Summary Table Removed VLP52, fixed Removed VLP61 duplicate of Errata VLP50 Added Erratum VLP75 through VLP183 Added Specification Changes Table Updated Specification Clarifications
August 2017	015	<ul style="list-style-type: none"> Added Erratum VLP74
January 2017	014	<ul style="list-style-type: none"> Added Erratum VLP73
July 2015	013	<ul style="list-style-type: none"> Added Erratum VLP70, VLP71 and VLP72
March 2015	012	<ul style="list-style-type: none"> Added Errata VLP67 and VLP68
February 2015	011	<ul style="list-style-type: none"> Added Erratum VLP66
November 2014	010	<ul style="list-style-type: none"> Added Erratum VLP 65
October 2014	009	<ul style="list-style-type: none"> Added errata VLP61-64 Added Specification Change VLP1
July 2014	008	<ul style="list-style-type: none"> Updated Table 2, "Identification Table for Intel® Celeron® and Pentium® Processor N- and J- Series"
May 2014	007	<ul style="list-style-type: none"> Added Erratum VLP60
March 2014	006	<ul style="list-style-type: none"> Updated Table 2, Identification Table for Intel® Celeron® and Pentium® Processor N- and J- Series Added CO Stepping to the Errata Summary Table
March 2014	005	<ul style="list-style-type: none"> Added Errata VLP55 – VLP59 Removed Q-Spec SKUs from Table 2
February 2014	004 v2	<ul style="list-style-type: none"> Minor corrections to 004 release



Date	Revision	Description
February 2014	004	<ul style="list-style-type: none">Updated Errata status to "Plan Fix"
January 2014	003	<ul style="list-style-type: none">Revision 002 skipped to align with current releaseAdded B3 to Table 1 stepping IDAdded 8 Refresh Sku detail to Table 2Removal of CSI Erratum (was VLP7)Added Gen2 to VLP6 contentNewly added Errata VLP34 to VLP46Added Errata VLP48-VLP53Added Erratum VLP54
October 2013	001	<ul style="list-style-type: none">Initial Release



Contents

Revision History	3
Introduction	6
Identification Information	8
Summary Table of Changes	11
Errata	16
Specification Changes	37
Specification Clarifications	39
Documentation Changes	40

§ §



Introduction

Purpose/Scope/Audience

This document contains specification updates for Intel® Celeron® and Pentium® Processor N- and J- Series. It is intended for hardware system manufacturers and software developers. It contains:

- Device Errata
- Document Errata
- Specification Clarifications
- Specification Changes


Note: Information types defined in the Nomenclature section of this document are consolidated and are no longer published in other documents. Refer to the section [Summary Table of Changes](#) for more information.

Affected Documents

Document Title	Document Number
Intel® Pentium® Processor N3500-series, J2850, J2900, and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750 Datasheet	329670

Related Documents

Document Title	Document Number/ Location
Intel® 64 and IA-32 Architectures Software Developer's Manuals: <ul style="list-style-type: none">• Volume 1: Basic Architecture• Volume 2A: Instruction Set Reference, A-L• Volume 2B: Instruction Set Reference, M-U• Volume 2C: Instruction Set Reference, V-Z• Volume 2D: Instruction Set Reference• Volume 3A: System programming guide, part 1• Volume 3B: System programming guide, part 2• Volume 3C: System programming guide, part 3• Volume 3D: System programming guide, part 4• Volume 4: Model-specific registers	http://www.intel.com/content/www/us/en/processors/architectures-software-developer-manuals.html
IA-32 Intel® Architectures Optimization Reference Manual	https://software.intel.com/en-us/articles/intel-sdm#optimization



Nomenclature

Errata are design defects or errors. These may cause the processor behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.

S-Spec Number is a five-digit code used to identify products. Products are differentiated by their unique characteristics, for example, core speed, L2 cache size, package type, etc. as described in the processor identification information table. Read all notes associated with each S-Spec number.

Specification Changes are modifications to the current published specifications. These changes will be incorporated in any new release of the specification.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in any new release of the specification.

Documentation Changes include typos, errors, or omissions from the current published specifications. These will be incorporated in any new release of the specification.

Note: Errata remain in the specification update throughout the product's lifecycle, or until a particular stepping is no longer commercially available. Under these circumstances, errata removed from the specification update are archived and available upon request. Specification changes, specification clarifications and documentation changes are removed from the specification update when the appropriate changes are made to the appropriate product specification or user documentation (datasheets, manuals, and so on).





Identification Information

Intel® Celeron® and Pentium® Processor N- and J- Series on 22-nm process stepping can be identified by the following register contents:

Table 1. Component Identification Using Programming Interface


Reserved	Extended Family ¹	Extended Model ²	Reserved	Processor Type ³	Family Code ⁴	Model Number ⁵	Stepping ID ⁶
31:28	27:20	19:16	15:13	12	11:8	7:4	3:0
0000b	0000000b	0011b	000b	0b	0110b	0111b	B1: 0010b B2/B3: 0011b C0: 0100b

Notes:

1. The Extended Family, bits [27:20] are used in conjunction with the Family Code, specified in bits [11:8], to indicate whether the processor belongs to the Intel386®, Intel486®, Pentium®, Pentium Pro, Pentium 4, or Intel Core processor family.
2. The Extended Model, bits [19:16] in conjunction with the Model Number, specified in bits [7:4], are used to identify the model of the processor within the processor's family.
3. The Processor Type, specified in bits [13:12] indicates whether the processor is an original OEM processor, an OverDrive processor, or a dual processor (capable of being used in a dual processor system).
4. The Family Code corresponds to bits [11:8] of the EDX register after RESET, bits [11:8] of the EAX register after the CPUID instruction is executed with 1 in the EAX register, and the generation field of the Device ID register, accessible through Boundary Scan.
5. The Model Number corresponds to bits [7:4] of the EDX register after RESET, bits [7:4] of the EAX register after the CPUID instruction is executed with 1 in the EAX register, and the model field of the Device ID register, accessible through Boundary Scan.
6. The Stepping ID in bits [3:0] indicates the revision number of that model. See for the processor stepping ID number in the CPUID information.

When EAX is initialized to a value of 1, the CPUID instruction returns the Extended Family, Extended Model, Type, Family, Model and Stepping value in the EAX register.


Note: The EDX processor signature value after reset is equivalent to the processor signature output value in the EAX register.



Component Marking Information

Intel® Celeron® and Pentium® Processor N- and J- Series are identified by the following component markings.

Figure 1. Intel® Celeron® and Pentium® Processor N- and J- Series (Micro-FCBGA13) Markings



SAMPLE MARKING INFORMATION:

GRP1LINE1: i{M}{C}YY_FPO12345

GRP2LINE1: QDF / SSPEC

GRP3LINE1: {e1}

Table 2. Identification Table for Intel® Celeron® and Pentium® Processor N- and J- Series (Sheet 1 of 2)

S-Spec	MM#	Product Stepping	Processor Number	CPUID	Core Speed		Package	Cache Size (KB)
					Highest Freq. Mode (HFM)/ GHz	Lowest Freq. Mode (LFM)/ MHz		
SR1LM	931090	B2	J2850	00030673	2.41	1333	Micro-FCBGA13	2 x1024
SR1LN	931092	B2	J1850	00030673	2.0	500	Micro-FCBGA13	2 x1024
SR1LP	931094	B2	J1750	00030673	2.41	500	Micro-FCBGA13	1s x1024
SR1LV	931112	B2	N3510	00030673	2	500	Micro-FCBGA13	2 x1024
SR1LW	931114	B2	N2810	00030673	2	533	Micro-FCBGA13	1 x1024



Table 2. Identification Table for Intel® Celeron® and Pentium® Processor N- and J- Series (Sheet 2 of 2)

S-Spec	MM#	Product Stepping	Processor Number	CPUID	Core Speed		Package	Cache Size (KB)
					Highest Freq. Mode (HFM)/ GHz	Lowest Freq. Mode (LFM)/ MHz		
SR1LX	931116	B2	N2805	00030673	1.46	533	Micro-FCBGA13	1 x1024
SR1LY	931118	B2	N2910	00030673	1.6	533	Micro-FCBGA13	2 x1024
SR1SE	932485	B3	N3520	00030673	2.17/2.42 (B)	500	Micro-FCBGA13	2 x1024
SR1SF	932490	B3	N2920	00030673	1.86/2.00 (B)	532	Micro-FCBGA13	2 x1024
SR1SG	932492	B3	N2820	00030673	2.13/2.39 (B)	532	Micro-FCBGA13	1 x1024
SR1SH	932494	B3	N2806	00030673	1.6/2.00 (B)	532	Micro-FCBGA13	1 x1024
SR1SJ	932579	B3	N2815	00030673	1.86/2.13 (B)	532	Micro-FCBGA13	1 x1024
SR1SB	932479	B3	J2900	00030673	2.41/2.67 (B)	1333	Micro-FCBGA13	2 x1024
SR1SC	932481	B3	J1900	00030673	2.0/2.42 (B)	1333	Micro-FCBGA13	2 x1024
SR1SD	932483	B3	J1800	00030673	2.41/2.58 (B)	1333	Micro-FCBGA13	1 x1024
SR1W2	934895	C0	N3530	30678	2.17/2.58 (B)	1333	Micro-FCBGA13	2 x1024
SR1W3	934896	C0	N2930	30678	1.83/2.17 (B)	1333	Micro-FCBGA13	2 x1024
SR1W4	934897	C0	N2830	30678	2.17/2.42 (B)	1333	Micro-FCBGA13	1 x1024
SR1W5	934898	C0	N2807	30678	1.58/2.17 (B)	1333	Micro-FCBGA13	1 x1024
SR1YW	936003	C0	N3540	30678	2.16/2.66 (B)	500	Micro-FCBGA13	2 x1024
SR1YV	935999	C0	N2940	30678	1.83/2.25 (B)	500	Micro-FCBGA13	2 x1024
SR1YJ	935933	C0	N2840	30678	2.16/2.58 (B)	500	Micro-FCBGA13	1 x1024
SR1YH	935931	C0	N2808	30678	1.58/2.25 (B)	500	Micro-FCBGA13	1 x1024

Note: “B” is the Burst Technology feature which is included with the Refresh sku. §

§ §



Summary Table of Changes

The table included in this section indicates the sightings that apply to the Intel® Celeron® and Pentium® Processor N- and J- Series. If a sighting becomes an Erratum, Intel may fix some of the errata in a future stepping of the component, and account for the other outstanding issues through documentation or specification changes as noted. This table uses the following notations:

Codes Used in Summary Table

Stepping

- X:** This sighting applies to this stepping.
- Blank (No mark):** This sighting is fixed or does not exist in the listed stepping.

Status

- Doc:** Document change or update will be implemented.
- Plan Fix:** Root caused to a silicon issue and will be fixed in a future stepping.
- Fixed:** Root caused to a silicon issue and has been fixed in a subsequent stepping.
- No Fix:** Root caused to a silicon issue that will not be fixed.
- Shaded:** This item is either new or modified from the previous version of the document.

Row

Change bar to left of table row indicates this erratum is either new or modified from the previous version of the document.

Note: Intel processor numbers are not a measure of performance. Processor numbers differentiate features within each processor family, not across different processor families. See http://www.intel.com/products/processor_number for details.



Errata Summary Table

Number	Status	Affected Stepping			Sighting Description
		B2	B3	C0	
VLP1	No Fix	X	X	X	GPIO Registers Do Not Support 8 or 16 Bit Transactions
VLP2	No Fix	X	X	X	Quad Word Transactions in Violation of Programming Model May Result in System Hang
VLP3	No Fix	X	X	X	SoC PCIe LTSSM May Not Enter Detect Within 20 ms
VLP4	No Fix	X	X	X	LFPS Detect Threshold
VLP5	No Fix	X	X	X	Set Latency Tolerance Value Command Completion Event Issue
VLP6	No Fix	X	X	X	SATA Signal Voltage Level Violation
VLP8	No Fix	X	X	X	Anomalies in USB xHCI PME Enable and PME Status
VLP9	No Fix	X	X	X	xHCI Port Assigned Highest SlotID When Resuming from Sx Issue
VLP10	No Fix	X	X	X	xHCI Data Packet Header and Payload Mismatch Error Condition
VLP11	No Fix	X	X	X	USB xHCI SuperSpeed Packet with Invalid Type Field Issue
VLP12	No Fix	X	X	X	USB xHCI Behavior with Three Consecutive Failed U3 Entry Attempts
VLP13	No Fix	X	X	X	USB xHCI Max Packet Size and Transfer Descriptor Length Mismatch
VLP14	No Fix	X	X	X	PCIe* Root Ports Unsupported Request Completion
VLP15	No Fix	X	X	X	USB EHCI RMH Port Disabled Due to Device Initiated Remote Wake
VLP16	No Fix	X	X	X	SMBus Hold Time
VLP17	No Fix	X	X	X	USB EHCI Isoch in Transfer Error Issue
VLP18	No Fix	X	X	X	USB EHCI Babble Detected with SW Overscheduling
VLP19	No Fix	X	X	X	USB EHCI Full-/Low-Speed EOP Issue
VLP20	No Fix	X	X	X	USB EHCI Asynchronous Retries Prioritized Over Periodic Transfers
VLP21	No Fix	X	X	X	USB EHCI FS/LS Incorrect Number of Retries
VLP22	No Fix	X	X	X	USB EHCI Full-/Low-speed Port Reset or Clear TT Buffer Request
VLP23	No Fix	X	X	X	USB EHCI RMH Think Time Issue
VLP24	No Fix	X	X	X	USB EHCI Full-/low-speed Device Removal Issue
VLP25	No Fix	X	X	X	Reported Memory Type May not Be Used to Access the VMCS and Referenced Data Structures
VLP26	No Fix	X	X	X	A Page Fault May not BE GENERATED when the PS Bit Is Set to "1" in PML4E or PDPTE
VLP27	No Fix	X	X	X	CS Limit Violations May not Be Detected after VM Entry
VLP28	No Fix	X	X	X	IA32_DEBUGCTL.FREEZE_PERFMON_ON_PMI Is Incorrectly Cleared by SMI
VLP29	No Fix	X	X	X	PEBS Record EventingIP Field May Be Incorrect after CS.Base Change
VLP30	No Fix	X	X	X	Some Performance Counter Overflows May not Be Logged in IA32_PERF_GLOBAL_STATUS When FREEZE_PERFMON_ON_PMI Is Enabled
VLP31	No Fix	X	X	X	MOVNTDQA from WC Memory May Pass Earlier Locked Instructions
VLP32	No Fix	X	X	X	Performance Monitor Instructions Retired Event May Not Count Consistently



Number	Status	Affected Stepping			Sighting Description
		B2	B3	C0	
VLP33	No Fix	X	X	X	Unsynchronized Cross-Modifying Code Operations Can Cause Unexpected Instruction Execution Results
VLP34	No Fix	X	X	X	USB HSIC Ports Incorrectly Reported as Removable
VLP35	No Fix	X	X	X	Paging Structure Entry May Be Used before Accessed and Dirty Flags Are Updated
VLP36	No Fix	X	X	X	VGA Max Luminance Voltage May Exceed VESA Limits
VLP37	No Fix	X	X	X	Certain eMMC Host Controller Registers Are Not Cleared by Software Reset
VLP38	No Fix	X	X	X	SD Host Controller Incorrectly Reports Supporting of Suspend/Resume Feature
VLP39	No Fix	X	X	X	SD Host Controller Error Status Registers May be Incorrectly Set
VLP40	No Fix	X	X	X	SD Host Controller Registers Are Not Cleared by Software Reset
VLP41	No Fix	X	X	X	eMMC Asynchronous Abort May Cause a Hang
VLP42	No Fix	X	X	X	Timing Specification Violation on SD Card Interface
VLP43	No Fix	X	X	X	SD Card Controller Does Not Disable Clock During Card Power Down
VLP44	No Fix	X	X	X	Reset Sequence May Take longer Than Expected When ACG is Enabled in SD And SDIO Controllers
VLP45	No Fix	X	X	X	SDIO Host Controller Does Not Control the SDIO Bus Power
VLP46	No Fix	X	X	X	Premature Asynchronous Interrupt Enabling May Lead to Loss of SDIO Wi-Fi Functionality
VLP47	No Fix	X	X	X	MTF VM Exit May Be Delayed Following a VM Entry That Injects a Software Interrupt
VLP48	No Fix	X	X	X	LBR Stack and Performance Counter Freeze on PMI May Not Function Correctly
VLP49	No Fix	X	X	X	USB Legacy Support SMI Not Available from xHCI Controller
VLP50	No Fix	X	X	X	SD Card UHS-I Mode Is Not Fully Supported
VLP51	No Fix	X	X	X	HD Audio Recording and Playback May Glitch or Stop
VLP52	Fixed	-	-	-	EOI Transactions May Not be Sent if Software Enters Core C6 During and Interrupt Service Routine - REMOVED
VLP53	No Fix	X	X	X	USB xHCI May Execute a Stale Transfer Request Block (TRB)
VLP54	No Fix	X	X	X	Frequency Reported by CPUID Instruction May Not Match Published Frequency
VLP55	No Fix	X	X	X	Reset Sequence May Not Complete Under Certain Conditions
VLP56	No Fix	X	X	X	Multiple Drivers That Access the GPIO Registers Concurrently May Result in Unpredictable System Behavior
VLP57	No Fix	X	X	X	Boot May Not Complete When SMI Occurs during Boot
VLP58	No Fix	X	X	X	Interrupts That Target an APIC That is Being Disabled May Result in a System Hang
VLP59	No Fix	X	X	X	Corrected or Uncorrected L2 Cache Machine Check Errors May Log Incorrect Address in IA32_MCI_ADDR
VLP60	No Fix	X	X	X	Some USB Controller Capability Registers May Be Invalid After S3 Resume
VLP61					Removed duplicate of VLP50
VLP62	No Fix	X	X	X	Top Swap Mechanism May Become Incorrectly Configured



Number	Status	Affected Stepping			Sighting Description
		B2	B3	C0	
VLP63	No Fix	X	X	X	Certain Peripheral I/O Controllers May Hang After an Unexpectedly Long Latency Memory Transaction
VLP64	No Fix	X	X	X	Disabling SDIO or SDCARD May Lead To a System Hang
VLP65	No Fix	X	X	X	Video And/or Audio Artifact May Occur When Changing Frequencies
VLP66	No Fix	X	X	X	USB Device May Not be Detected at System Power-On
VLP67	No Fix	X	X	X	VM Exits During Execution of INTn in Virtual-8086 Mode with Virtual-Mode Extensions May Save RFLAGS Incorrectly
VLP68	No Fix	X	X	X	Clearing IA32_MC0_CTL[5] May Prevent Machine Check Notification
VLP69	No Fix	X	X	X	System May Unexpectedly Reboot After Shutdown
VLP70	No Fix	X	X	X	LPE Audio Playback May Result in System Hang
VLP71	No Fix	X	X	X	LPC SERR Generation Can Not Be Independently Disabled
VLP72	No Fix	–	–	X	Some RTIT Packets Following PSB May be Sent Out of Order or Dropped
VLP73	No Fix	X	X	X	Accessing Unimplemented ISP MMIO Space May Cause a System Hang
VLP74	No Fix	X	X	X	LPC Clock Control Using the ILB_LPC_CLKRUN# Signal May Not Behave As Expected
VLP75	No Fix	–	–	X	RTIT Trace May Contain FUP.FAR Packet with Incorrect Address
VLP76	No Fix	–	–	X	RTIT May Delay the PSB by One Packet
VLP77	No Fix	–	–	X	RTIT TraceStop Condition Detected During Buffer Overflow May Not Clear TraceActive
VLP78	No Fix	–	–	X	RTIT FUP.BufferOverflow Packet may be Incorrectly Followed by a TIP Packet
VLP79	No Fix	–	–	X	RTIT CYC Packet Payload Values may be Off by 1 Cycle
VLP80	No Fix	–	–	X	First MTC Packet after RTIT Enable May be Incorrect
VLP81	No Fix	X	X	X	Performance Monitoring Counter Overflows May Not be Reflected in IA32_PERF_GLOBAL_STATUS
VLP82	No Fix	X	X	X	xHCI Host Controller Reset May Cause a System Hang
VLP83	No Fix	X	X	X	PMI May be Pended When PMI LVT Mask Bit Set
VLP84	No Fix	X	X	X	TLB Entries May Not Be Invalidated Properly When Bit 8 Is Set in EPT Paging - Structure Entries
VLP85	No Fix	X	X	X	eMMC CRC Detection

Number	Specification Changes
1	Top Swap Feature
2	PCU-SPI AC Specification
2	PCU-SPI NOR AC Timing
2	SPI NOR Timing

Number	Specification Clarifications
	S4/S5 to S0 (Power Up) Sequence



Number	Documentation Changes
1	tREFI Refresh Period Unit of Measurement Correction
2	FIFOSE_RCVR (RCVR) and RES_TET (TET) Field Name Description trigger levels correction
3	IC_SLAVE_DISABLE Field Name Description Correction
4	SPEED Field Name Description Correction
5	MASTER MODE (MASTER_MODE) Field Name Description Correction
6	IC_10BITADDR_MASTER Field Name Description Correction
7	The following registers are an addition to section 17.10 of the EDS to document which register fields are programmed as part of the workaround for erratum VLP66
8	PCU-iLB-LPC AC Specification Numbering Correction

§§



Errata

VLP1. GPIO Registers Do Not Support 8 or 16 Bit Transactions

Problem: Due to this erratum, only aligned DWord accesses to GPIO registers function correctly. This erratum applies to GPIO registers whether in MMIO space or IO space.

Implication: GPIO register transactions using byte or word accesses or unaligned DWord accesses will not work correctly.

Workaround: Always use aligned 32-Bit transactions when accessing GPIO registers.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP2. Quad Word Transactions in Violation of Programming Model May Result in System Hang

Problem: Quad word (64-bit data) transactions to access two adjacent 32-Bit registers of SoC internal devices that do not support such transactions may cause system hang.

Implication: Due to this erratum, violations of a device programming model may result in a hang instead of a fatal Target Abort / Completer Abort error. Software written in compliance to correct programming model will not be affected.

Workaround: Software must be written and compiled in compliance to correct programming model.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP3. SoC PCIe LTSSM May Not Enter Detect Within 20 ms

Problem: The PCIe specification requires the LTSSM (Link Training and Status State Machine) to enter Detect within 20 ms of the end of Fundamental Reset. Due to this erratum, the SoC may violate this specification.

Implication: Intel has not observed this erratum to impact operation of any commercially available add-in card.

Workaround: None identified.

Status: For the steppings affected, see [“Summary Table of Changes”](#).


VLP4. LFPS Detect Threshold

Problem: The USB 3.0 host and device controllers' LFPS (Low Frequency Periodic Signal) detect threshold is higher than the USB 3.0 specification maximum of 300 mV.

Implication: The USB 3.0 host and device controllers may not recognize LFPS from SuperSpeed devices transmitting at the minimum low power peak-to-peak differential voltage (400 mV) as defined by USB 3.0 specification for the optional capability for Low-Power swing mode. Intel has not observed this erratum to impact the operation of any commercially available system.

Workaround: None identified.

Status: For the steppings affected, see [“Summary Table of Changes”](#).



VLP5. Set Latency Tolerance Value Command Completion Event Issue

Problem: The xHCI controller does not return a value of '0' for slot ID in the command completion event TRB (Transfer Request Block) for a set latency tolerance value command.

Note: This violates the command completion event TRB description in section 6.4.2.2 of the extensible Host Controller Interface for Universal Serial Bus (xHCI) specification, revision 1.0.

Implication: There are no known functional failures due to this issue.

Note: Set latency tolerance value command is specific to the controller and not the slot. Software knows which command was issued and which fields are valid to check for the event.

Note: xHCI CV compliance test suite: Test TD4.10: Set Latency Tolerance Value Command Test may issue a warning.

Workaround: None identified.

Status: For the steppings affected, see ["Summary Table of Changes"](#).

VLP6. SATA Signal Voltage Level Violation

Problem: SATA transmit buffers have been designed to maximize performance and robustness over a variety of routing scenarios. As a result, the SATA transmit signaling voltage levels may exceed the maximum motherboard TX connector and device RX connector voltage specifications as defined in section 7.2.2.3 of the Serial ATA specification, rev 3.1. This issue applies to Gen 1 (1.5 Gb/s) and Gen 2 (3Gb/s).

Implication: None known.

Workaround: None identified.

Status: For the steppings affected, see ["Summary Table of Changes"](#).

VLP8. Anomalies in USB xHCI PME Enable and PME Status

Problem: The PME_En (Bit 8) and PME_Status (Bit 15) in xHCI's PCI PMCSR (Bus 0, Device 20, Function 0, Offset 0x74) do not comply with the PCI specification.

Implication: If a standard bus driver model for this register is applied, wake issues and system slowness may happen.

Workaround: None identified

Status: For the steppings affected, see ["Summary Table of Changes"](#).

VLP9. xHCI Port Assigned Highest SlotID When Resuming from Sx Issue

Problem: If a device is attached while the platform is in S3 or S4 and the device is assigned the highest assignable Slot ID upon resume, the xHCI may attempt to access an unassigned main memory address.

Implication: Accessing unassigned main memory address may cause a system software timeout leading to possible system hang.

Workaround: System SW can detect the timeout and perform a host controller reset prior to avoid a system hang.

Status: For the steppings affected, see ["Summary Table of Changes"](#).



VLP10. xHCI Data Packet Header and Payload Mismatch Error Condition

Problem: If a SuperSpeed device sends a DPH (Data Packet Header) to the xHCI with a data length field that specifies less data than is actually sent in the RSM (Data Packet Payload), the xHCI will accept the packet instead of discarding the packet as invalid.

Note: The USB 3.0 specification requires a device to send a DPP matching the amount of data specified by the DPH.

Implication: The amount of data specified in the DPH will be accepted by the xHCI and the remaining data will be discarded and may result in anomalous system behavior.

Note: This issue has only been observed in a synthetic test environment with a synthetic device.

Workaround: None identified.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP11. USB xHCI SuperSpeed Packet with Invalid Type Field Issue

Problem: If the encoding for the “type” field for a SuperSpeed packet is set to a reserved value and the encoding for the “subtype” field is set to “ACK”, the xHCI may accept the packet as a valid acknowledgement transaction packet instead of ignoring the packet.

Note: The USB 3.0 specification requires that a device never set any defined fields to reserved values.

Implication: System implication is dependent on the misbehaving device and may result in anomalous system behavior.

Note: This issue has only been observed in a synthetic test environment with a synthetic device.

Workaround: None identified.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP12. USB xHCI Behavior with Three Consecutive Failed U3 Entry Attempts

Problem: The xHCI does not transition to the SS. Inactive USB 3.0 LTSSM (Link Training and Status State Machine) state after a SuperSpeed device fails to enter U3 upon three consecutive attempts.

Note: The USB 3.0 specification requires a SuperSpeed device to enter U3 when directed.

Implication: The xHCI will continue to try to initiate U3. The implication is driver and operating system dependent.

Workaround: None identified.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP13. USB xHCI Max Packet Size and Transfer Descriptor Length Mismatch

Problem: The xHCI may incorrectly handle a request from a low-speed or full-speed device when all the following conditions are true:

- The sum of the packet fragments equals the length specified by the TD (Transfer Descriptor).
- The TD length is less than the MPS (Max Packet Size) for the device.
- The last packet received in the transfer is “0” or babble bytes.

Implication: The xHCI will halt the endpoint if all the above conditions are met. All functions associated with the endpoint will stop functioning until the device is unplugged and reinserted.

Workaround: None identified.

Status: For the steppings affected, see [“Summary Table of Changes”](#).



VLP14. PCIe* Root Ports Unsupported Request Completion

Problem: The PCIe* root ports may return an Unsupported Request (UR) completion with an incorrect lower address field in response to a memory read if any of the following occur:

- Bus Master Enable is disabled in the PCIe Root Port's Command register (PCICMD Bit 2 =0).
- Address Type (AT) field of the Transaction Layer Packet (TLP) header is non-zero.
- The requested upstream address falls within the memory range claimed by the secondary side of the bridge.
- Requester ID with Bus Number of 0.

Implication: The UR Completion with an incorrect lower address field may be handled as a Malformed TLP causing the Requestor to send an ERR_NONFATAL or ERR_FATAL message.

Workaround: None identified.

Status: For the steppings affected, see ["Summary Table of Changes"](#).

VLP15. USB EHCI RMH Port Disabled Due to Device Initiated Remote Wake

Problem: During resume from Global Suspend, the RMH controller may not send SOF soon enough to prevent a device from entering suspend again. A collision on the port may occur if a device initiated remote wake occurs before the RMH controller sends SOF.

Note: Intel has only observed this issue when two USB devices on the same RMH controller send remote wake within 30 ms window while RMH controller is resuming from Global Suspend.

Implication: The RMH host controller may detect the collision as babble and disable the port.

Workaround: Intel recommends system software to check Bit 3 (Port Enable/Disable Change) together with Bit 7 (Suspend) of Port N Status and Control PORTC registers when determining which port(s) have initiated remote wake. Intel recommends the use of the USB xHCI controller, which is not affected by this erratum.

Status: For the steppings affected, see ["Summary Table of Changes"](#).

VLP16. SMBus Hold Time

Problem: The SMBus data hold time may be less than the 300 ns minimum defined by the Bay Trail-D/M SoC (System On Chip) External Design Specification (EDS).

Implication: There are no known functional failures due to this issue.

Workaround: None identified.

Status: For the steppings affected, see ["Summary Table of Changes"](#).



VLP17. USB EHCI Isoch in Transfer Error Issue

Problem: If a USB full-speed inbound isochronous transaction with a packet length 190 bytes or greater is started near the end of a microframe the SoC may see more than 189 bytes in the next microframe.

Implication: If the SoC sees more than 189 bytes for a microframe an error will be sent to software and the isochronous transfer will be lost. If a single data packet is lost no perceptible impact for the end user is expected.

Note: Intel has only observed the issue in a synthetic test environment where precise control of packet scheduling is available, and has not observed this failure in its compatibility validation testing.

- Isochronous traffic is periodic and cannot be retried thus it is considered good practice for software to schedule isochronous transactions to start at the beginning of a microframe. Known software solutions follow this practice.
- To sensitize the system to the issue additional traffic such as other isochronous transactions or retries of asynchronous transactions would be required to push the inbound isochronous transaction to the end of the microframe.

Workaround: Intel recommends the use of the USB xHCI controller, which is not affected by this erratum.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP18. USB EHCI Babble Detected with SW Overscheduling

Problem: If software violates USB periodic scheduling rules for full-speed isochronous traffic by overscheduling, the RMH may not handle the error condition properly and return a completion split with more data than the length expected.


Implication: If the RMH returns more data than expected, the endpoint will detect packet babble for that transaction and the packet will be dropped. Since overscheduling occurred to create the error condition, the packet would be dropped regardless of RMH behavior. If a single isochronous data packet is lost, no perceptible impact to the end user is expected.

Note: USB software overscheduling occurs when the amount of data scheduled for a microframe exceeds the maximum budget. This is an error condition that violates the USB periodic scheduling rule.

Note: This failure has only been recreated synthetically with USB software intentionally overscheduling traffic to hit the error condition.

Workaround: Intel recommends the use of the USB xHCI controller, which is not affected by this erratum.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

**VLP19. USB EHCI Full-/Low-Speed EOP Issue**

Problem: If the EOP of the last packet in a USB Isochronous split transaction (Transaction >189 bytes) is dropped or delayed 3 ms or longer the following may occur:

- If there are no other pending low-speed or full-speed transactions the RMH will not send SOF, or Keep-Alive. Devices connected to the RMH will interpret this condition as idle and will enter suspend.
- If there is other pending low-speed or full-speed transactions, the RMH will drop the isochronous transaction and resume normal operation.

Implication: If there are no other transactions pending, the RMH is unaware a device has entered suspend and may start sending a transaction without waking the device. The implication is device dependent, but a device may stall and require a reset to resume functionality. If there are other transactions present, only the initial isochronous transaction may be lost. The loss of a single isochronous transaction may not result in end user perceptible impact.

Note: Intel has only observed this failure when using software that does not comply with the USB specification and violates the hardware isochronous scheduling threshold by terminating transactions that are already in progress

Workaround: Intel recommends the use of the USB xHCI controller, which is not affected by this erratum.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP20. USB EHCI Asynchronous Retries Prioritized Over Periodic Transfers

Problem: The integrated USB RMH incorrectly prioritizes full-speed and low-speed asynchronous retries over dispatchable periodic transfers.

Implication: Periodic transfers may be delayed or aborted. If the asynchronous retry latency causes the periodic transfer to be aborted, the impact varies depending on the nature of periodic transfer:

- If a periodic interrupt transfer is aborted, the data may be recovered by the next instance of the interrupt or the data could be dropped.
- If a periodic isochronous transfer is aborted, the data will be dropped. A single dropped periodic transaction should not be noticeable by end user.

Note: This issue has only been seen in a synthetic environment. The USB spec does not consider the occasional loss of periodic traffic a violation.

Workaround: Intel recommends the use of the USB xHCI controller, which is not affected by this erratum.

Status: For the steppings affected, see [“Summary Table of Changes”](#).



VLP21. USB EHCI FS/LS Incorrect Number of Retries

Problem: A USB low-speed transaction may be retried more than three times, and a USB full-speed transaction may be retried less than three times if all of the following conditions are met:

- A USB low-speed transaction with errors or the first retry of the transaction occurs near the end of a microframe, and there is not enough time to complete another retry of the low-speed transaction in the same microframe.
- There is pending USB full-speed traffic and there is enough time left in the microframe to complete one or more attempts of the full-speed transaction.
- Both the low-speed and full-speed transactions must be asynchronous (Bulk/Control) and must have the same direction either in or out.

Note: Per the USB EHCI Specification, a transaction with errors should be attempted a maximum of 3 times if it continues to fail.

Implication: For low-speed transactions the extra retry(s) allow a transaction additional chance(s) to recover regardless of if the full-speed transaction has errors or not. If the full-speed transactions also have errors, the SoC may retry the transaction fewer times than required, stalling the device prematurely. Once stalled, the implication is software dependent, but the device may be reset by software.

Workaround: Intel recommends the use of the USB xHCI controller, which is not affected by this erratum.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP22. USB EHCI Full-/Low-speed Port Reset or Clear TT Buffer Request

Problem: One or more full-/low-speed USB devices on the same RMH controller may be affected if the devices are not suspended and either (a) software issues a Port Reset OR (b) software issues a Clear TT Buffer request to a port executing a split full-/low-speed Asynchronous Out command. The small window of exposure for full-speed device is around 1.5 microseconds and around 12 microseconds for a low-speed device.

Implication: The affected port may stall or receive stale data for a newly arrived split transfer occurring at the time of the Port Reset or Clear TT Buffer request.

Note: This issue has only been observed in a synthetic test environment.

Workaround: Intel recommends the use of the USB xHCI controller, which is not affected by this erratum.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP23. USB EHCI RMH Think Time Issue

Problem: The USB RMH Think Time may exceed its declared value in the RMH hub descriptor register of 8 full-speed Bit times.

Implication: If the USB driver fully subscribes a USB microframe, LS/FS transactions may exceed the microframe boundary.

Note: No functional failures have been observed.

Workaround: Intel recommends the use of the USB xHCI controller, which is not affected by this erratum.

Status: For the steppings affected, see [“Summary Table of Changes”](#).



VLP24. USB EHCI Full-/low-speed Device Removal Issue

Problem: If two or more USB full-/low-speed devices are connected to the EHCI USB controller, the devices are not suspended, and one device is removed, one or more of the devices remaining in the system may be affected by the disconnect.

Implication: The implication is device dependent. A device may experience a delayed transaction, stall and be recovered via software, or stall and require a reset such as a hot plug to resume normal functionality.

Workaround: Intel recommends the use of the USB xHCI controller, which is not affected by this erratum.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP25. Reported Memory Type May not Be Used to Access the VMCS and Referenced Data Structures

Problem: Bits 53:50 of the IA32_VMX_BASIC MSR report the memory type that the processor uses to access the VMCS and data structures referenced by pointers in the VMCS. Due to this erratum, a VMX access to the VMCS or referenced data structures will instead use the memory type that the MTRRs (memory-type range registers) specify for the physical address of the access.

Implication: Bits 53:50 of the IA32_VMX_BASIC MSR report that the WB (write-back) memory type will be used but the processor may use a different memory type.

Workaround: Software should ensure that the VMCS and referenced data structures are located at physical addresses that are mapped to WB memory type by the MTRRs.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP26. A Page Fault May not BE GENERATED when the PS Bit Is Set to “1” in PML4E or PDPTE

Problem: On processors supporting Intel® 64 architecture the PS Bit (Page Size Bit 7) is reserved in PML4Es and PDPTEs. If the translation of the linear address of a memory access encounters a PML4E or a PDPTE with PS set to 1 a page fault should occur. Due to this erratum, PS of such an entry is ignored and no page fault will occur due to it is being set.

Implication: Software may not operate properly if it relies on the processor to deliver page faults when reserved bits are set in paging-structure entries.

Workaround: Software should not set Bit 7 in any PML4E or PDPTE that has Present Bit (Bit 0) set to “1”.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP27. CS Limit Violations May not Be Detected after VM Entry

Problem: The processor may fail to detect a CS limit violation on fetching the first instruction after VM entry if the first byte of that instruction is outside the CS limit but the last byte of the instruction is inside the limit.

Implication: The processor may erroneously execute an instruction that should have caused a general protection exception.

Workaround: When a VMM emulates a branch instruction it should inject a general protection exception if the instruction's target EIP is beyond the CS limit.

Status: For the steppings affected, see [“Summary Table of Changes”](#).



VLP28. IA32_DEBUGCTL.FREEZE_PERFMON_ON_PMI Is Incorrectly Cleared by SMI

Problem: FREEZE_PERFMON_ON_PMI (Bit 12) in the IA32_DEBUGCTL MSR (1D9H) is erroneously cleared during delivery of an SMI (system-management interrupt).

Implication: As a result of this erratum the performance monitoring counters will continue to count after a PMI occurs in SMM (system-management Mode).

Workaround: None identified.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP29. PEBS Record EventingIP Field May Be Incorrect after CS.Base Change

Problem: Due to this erratum a PEBS (Precise Event Base Sampling) record generated after an operation which changes CS.Base may contain an incorrect address in the EventingIP field.

Implication: Software attempting to identify the instruction which caused the PEBS event may identify the incorrect instruction when non-zero CS.Base is supported and CS.Base is changed. Intel has not observed this erratum to impact the operation of any commercially available system.

Workaround: None identified.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP30. Some Performance Counter Overflows May not Be Logged in IA32_PERF_GLOBAL_STATUS When FREEZE_PERFMON_ON_PMI Is Enabled

Problem: When enabled, FREEZE_PERFMON_ON_PMI Bit 12 in IA32_DEBUGCTL MSR (1D9H) freezes PMCs (performance monitoring counters) on a PMI (Performance Monitoring Interrupt) request by clearing the IA32_PERF_GLOBAL_CTRL MSR (38FH). Due to this erratum, when FREEZE_PERFMON_ON_PMI is enabled and two or more PMCs overflows within a small window of time and PMI is requested, then subsequent PMC overflows may not be logged in IA32_PERF_GLOBAL_STATUS MSR (38EH).

Implication: On a PMI, subsequent PMC overflows may not be logged in IA32_PERF_GLOBAL_STATUS MSR.

Workaround: Re-enabling the PMCs in IA32_PERF_GLOBAL_CTRL will log the overflows that were not previously logged in IA32_PERF_GLOBAL_STATUS.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.


VLP31. MOVNTDQA from WC Memory May Pass Earlier Locked Instructions

Problem: An execution of MOVNTDQA that loads from WC (write combining) memory may appear to pass an earlier locked instruction to a different cache line.

Implication: Software that expects a lock to fence subsequent MOVNTDQA instructions may not operate properly. If the software does not rely on locked instructions to fence the subsequent execution of MOVNTDQA then this erratum does not apply.

Workaround: Software that requires a locked instruction to fence subsequent executions of MOVNTDQA should insert an LFENCE instruction before the first execution of MOVNTDQA following the locked instruction. If there is already fencing or serializing instruction between the locked instruction and the MOVNTDQA, then an additional LFENCE is not necessary.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

**VLP32. Performance Monitor Instructions Retired Event May Not Count Consistently**

Problem: Performance Monitor Instructions Retired (Event COH; Umask 00H) and the instruction retired fixed counter (IA32_FIXED_CTR0 MSR (309H)) are used to track the number of instructions retired. Due to this erratum, certain situations may cause the counter(s) to increment when no instruction has retired or to not increment when specific instructions have retired.

Implication: A performance counter counting instructions retired may over or under count. The count may not be consistent between multiple executions of the same code.

Workaround: None identified.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP33. Unsynchronized Cross-Modifying Code Operations Can Cause Unexpected Instruction Execution Results

Problem: The act of one processor or system bus master writing data into a currently executing code segment of a second processor with the intent of having the second processor execute that data as code is called cross-modifying code (XMC). XMC that does not force the second processor to execute a synchronizing instruction prior to execution of the new code is called unsynchronized XMC. Software using unsynchronized XMC to modify the instruction byte stream of a processor can see unexpected or unpredictable execution behavior from the processor that is executing the modified code.

Implication: In this case the phrase “unexpected or unpredictable execution behavior” encompasses the generation of most of the exceptions listed in the Intel Architecture Software Developer’s Manual Volume 3: System Programming Guide including a General Protection Fault (GPF) or other unexpected behaviors. In the event that unpredictable execution causes a GPF the application executing the unsynchronized XMC operation would be terminated by the operating system.

Workaround: To avoid this erratum, programmers should use the XMC synchronization algorithm as detailed in the *Intel Architecture Software Developer’s Manual Volume 3: System Programming Guide Section: Handling Self- and Cross-Modifying Code*.

Status: For the steppings affected, see the [“Summary Table of Changes”](#).

VLP34. USB HSIC Ports Incorrectly Reported as Removable

Problem: The DR (Device Removable) bit in the PORTSC registers of the two USB HSIC ports incorrectly indicates that devices on these ports may be removed.

Implication: Software that relies solely on the state of DR bits will consider fixed devices to be removable. This may lead the software to improper actions (for example, requesting the user remove a fixed device).

Workaround: In conjunction with the DR bits, software should use BIOS-configured ACPI tables and factor in the CONNECTABLE field of the USB Port Capabilities object when determining whether a port is removable.

Status: For the steppings affected, see [“Summary Table of Changes”](#).



VLP35. Paging Structure Entry May Be Used before Accessed and Dirty Flags Are Updated

Problem: If software modifies a paging structure entry while the processor is using the entry for linear address translation, the processor may erroneously use the old value of the entry to form a translation in a Translation Lookaside Buffer (TLB) (or an entry in a paging structure cache) and then update the entry's new value to set the accessed flag or dirty flag. This will occur only if both the old and new values of the entry result in valid translations.

Implication: Incorrect behavior may occur with algorithms that atomically check that the accessed flag or the dirty flag of a paging structure entry is clear and modify other parts of that paging structure entry in a manner that results in a different valid translation.

Workaround: Affected algorithms must ensure that appropriate TLB invalidation is done before assuming that future accesses do not use translations based on the old value of the paging structure entry.

Status: For the steppings affected, see ["Summary Table of Changes"](#).

VLP36. VGA Max Luminance Voltage May Exceed VESA Limits

Problem: The max luminance voltage on the VGA video outputs may range from 640 mV to 810mV (the VESA specification range is 665 mV to 770mV) with linearity (INL/DNL) of up to ± 3 LSB (the VESA linearity specification is ± 1 LSB).

Implication: Intel has not observed any functional issues due to this erratum.

Workaround: None identified.

Status: For the steppings affected, see ["Summary Table of Changes"](#).

VLP37. Certain eMMC Host Controller Registers Are Not Cleared by Software Reset

Problem: Due to this erratum, when an eMMC Host Controller software reset is requested by setting bit 0 of the Software Reset Register (Offset 2FH), the Command Response Register (Offset 10H) and ADMA Error Status Register (Offset 54H) are not cleared. This does not comply with the SD Host Controller Specification 3.0.

Implication: Intel has not observed this erratum to impact any commercially available software.

Workaround: Software should not read these registers until a response is received from the eMMC device.

Status: For the steppings affected, see ["Summary Table of Changes"](#).

VLP38. SD Host Controller Incorrectly Reports Supporting of Suspend/Resume Feature

Problem: SDIO, SD Card, and eMMC Controllers should not indicate the support of optional Suspend/Resume feature documented in the SD Host Controller Standard Specification Version 3.0. Due to this erratum, the default value in the Capabilities Register (offset 040H) incorrectly indicates to the software that this feature is supported.

Implication: If software utilizes the Suspend/Resume feature, data may not be correctly transferred between memory and SD Device.

Workaround: A BIOS code change has been identified and may be implemented as a workaround for this erratum.

Status: For the steppings affected, see ["Summary Table of Changes"](#).

**VLP39. SD Host Controller Error Status Registers May be Incorrectly Set**

Problem: This erratum impacts SDIO, SD Card, and eMMC SD Host Controllers. Auto CMD Error Status Register (offset 03CH, bits [7:1]) may be incorrectly set for software-issued commands (for example: CMD13) that generate errors when issued close to the transmission of an Auto CMD12 command. In addition, the Error Interrupt Status Register bits (offset 032H) are similarly affected.

Implication: Software may not be able to interpret SD Host controller error status.

Workaround: Software should follow the same error recovery flow whenever an error status bit is set. Alternatively, do not use software-issued commands, which have Auto CMD12 enabled.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP40. SD Host Controller Registers Are Not Cleared by Software Reset

Problem: This erratum impacts SDIO, SD Card, and eMMC SD Host Controllers. When Software Reset is asserted, registers such as SDMA System Address / Argument 2 (offset 00H) in SD Host Controller are not cleared, failing to comply with the SD Host Controller Specification 3.0.

Implication: Intel has not observed this erratum to impact any commercially available software.

Workaround: Driver is expected to reprogram these registers before issuing a new command.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP41. eMMC Asynchronous Abort May Cause a Hang

Problem: Use of an Asynchronous Abort command to recover from an eMMC transfer error or use of a high priority interrupt STOP_TRANSMISSION command may result in a hang.

Implication: Using Asynchronous Abort command may cause a hang. Intel has not observed this erratum to impact the operation of any commercially available system.

Workaround: The eMMC driver should use High Priority Interrupt SEND_STATUS mode per JEDEC STANDARD eMMC, version 4.5. A minimum wait time of 128us between getting an error interrupt and issuing a software reset will avoid this erratum.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP42. Timing Specification Violation on SD Card Interface

Problem: SD Card interface I/O circuitry is not optimized for platform conditions during operation at 3.3V.

Implication: Due to this erratum, there is an increased risk of a transfer error.

Workaround: A BIOS code change has been identified and may be implemented as a workaround for this erratum.

Status: For the steppings affected, see [“Summary Table of Changes”](#).

VLP43. SD Card Controller Does Not Disable Clock During Card Power Down

Problem: The clock and power control of the SD card controller are not linked. Therefore, the SD card controller does not automatically disable the SD card clock when the SD card power is disabled.

Implication: When an SD card is inserted into the system and powered off, the clock to the SD card will continue to be driven. Although this behavior is common, it is a violation of the SD Card Spec 3.0.

Workaround: To address this problem, the SD card clock should be enabled/disabled in conjunction with SD card power.

Status: For the steppings affected, see [“Summary Table of Changes”](#).



VLP44. Reset Sequence May Take longer Than Expected When ACG is Enabled in SD And SDIO Controllers

Problem: When ACG (Auto Clock Gating) is enabled in SD and SDIO controllers, the reset sequence may take longer than expected, possibly resulting in a software timeout.

Implication: Due to this erratum, a longer response time may be observed after software initiates reset.

Workaround: A BIOS code change has been identified and may be implemented as a workaround for this erratum.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP45. SDIO Host Controller Does Not Control the SDIO Bus Power

Problem: The SD Bus Power bit in Power Control Register (Bus 0; Device 17; Function 0; Offset 029H) is not connected to any SOC IO pin that can reset the SDIO bus power. Due to this erratum, SDIO device Power-On-Reset cannot be controlled by Power Control Register. SDIO Controller may fail to comply with SD Host Controller Specification Version 3.00.

Implication: SDIO devices may not be powered up and initialized correctly.

Workaround: A GPIO pin must be implemented on the platform to control the SDIO bus power. GPIO pin can be asserted/de-asserted from ASL methods in firmware.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP46. Premature Asynchronous Interrupt Enabling May Lead to Loss of SDIO Wi-Fi Functionality

Problem: Setting the SDIO controller's Host Control 2 Register Asynchronous Interrupt Enable (Bus 0; Device 17; Function 0; Offset 03EH, bit 14) to '1' before the signal voltage switch sequence completion may result in SDIO card initialization failure.

Implication: SDIO card initialization failure may lead to software time out and loss of Wi-Fi device functionality. Currently released common operating system drivers do not use Asynchronous Interrupt mode.

Workaround: The SDIO driver should either use SDIO Synchronous Interrupt Mode or enable SDIO Asynchronous Interrupt Mode after the SDIO card signal voltage switch sequence completes.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP47. MTF VM Exit May Be Delayed Following a VM Entry That Injects a Software Interrupt

Problem: If the “monitor trap flag” VM-execution control is 1 and VM entry is performing event injection, an MTF VM exit should be delivered immediately after the VM entry. Due to this erratum, delivery of the MTF VM exit may be delayed by one instruction if the event being injected is a software interrupt and if the guest state being loaded has RFLAGS.VM = CR4.VME = 1. In this case, the MTF VM exit is delivered following the first instruction of the software interrupt handler.

Implication: Software using the monitor trap flag to trace guest execution may fail to get a notifying VM exit after injecting a software interrupt. Intel has not observed this erratum with any commercially available system.

Workaround: None identified. An affected virtual-machine monitor could emulate delivery of the software interrupt before VM entry.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.



VLP48. LBR Stack and Performance Counter Freeze on PMI May Not Function Correctly

- Problem:** When FREEZE_LBRS_ON_PMI flag (bit 11) in IA32_DEBUGCTL MSR (1D9H) is set, the LBR (Last Branch Record) stack is frozen on a hardware PMI (Performance Monitoring Interrupt) request. When FREEZE_PERFMON_ON_PMI flag (bit 12) in IA32_DEBUGCTL MSR is set, a PMI request clears each of the ENABLE fields of the IA32_PERF_GLOBAL_CTRL MSR (38FH) to disable counters. Due to this erratum, when FREEZE_LBRS_ON_PMI and/or FREEZE_PERFMON_ON_PMI is set in IA32_DEBUGCTL MSR and the local APIC is disabled or the PMI LVT is masked, the LBR Stack and/or Performance Counters Freeze on PMI may not function correctly.
- Implication:** Performance monitoring software may not function properly if the LBR Stack and Performance Counters Freeze on PMI do not operate as expected. Intel has not observed this erratum to impact any commercially available system.
- Workaround:** None identified.
- Status:** For the steppings affected, see [“Summary Table of Changes”](#).

VLP49. USB Legacy Support SMI Not Available from xHCI Controller

- Problem:** SMIs are routed using the PMC (Power Management Controller) SMI_STS and SMI_EN registers. However, the USB SMI Enable (USB_SMI_EN) and USB Status (USB_STS) fields only reflect SMIs for the EHCI USB controller. SMIs triggered by the xHCI controller’s USBLEGCTLSTS mechanism are not available.
- Implication:** BIOS is unable to receive SMI interrupts from the xHCI controller. BIOS mechanisms such as legacy keyboard emulation for pre-OS environments will be impacted.
- Workaround:** Use the EHCI controller for legacy keyboard emulation that requires legacy USB SMI support by BIOS.
- Status:** For the steppings affected, see [“Summary Table of Changes”](#).

VLP50. SD Card UHS-I Mode Is Not Fully Supported

- Problem:** The SD Card Specification rev 3.01 Addendum 1 specifies a relaxed NCRC (Number of clocks to Cyclic Redundancy Check) timing specification for UHS-I (DDR50) mode. Due to this erratum, the SD Host Controller is not fully compatible with this relaxed timing specification.
- Implication:** Using UHS-I mode with SD devices that rely upon relaxed NCRC may cause SD host commands to fail to complete, resulting in device access failures.
- Workaround:** BIOS and driver code changes have been identified and may be implemented as a workaround for this erratum.
- Status:** For the steppings affected, see [“Summary Table of Changes”](#).

VLP51. HD Audio Recording and Playback May Glitch or Stop

- Problem:** Under certain conditions generally involving extended simultaneous video and HD audio playback and/or recording, glitches, distortion, or persistent muting of the audio stream may occur due to improper processing of input stream data or response packets.
- Implication:** Due to this erratum, media device operation may not be reliable.
- Workaround:** A BIOS code change has been identified and may be implemented to minimize the effect of this erratum. The third-party codec driver should minimize HD audio device command traffic.
- Status:** For the steppings affected, see [“Summary Table of Changes”](#).



VLP52. EOI Transactions May Not be Sent if Software Enters Core C6 During and Interrupt Service Routine

Status: Removed because erratum is fixed in the processor core for all Steppings.

VLP53. USB xHCI May Execute a Stale Transfer Request Block (TRB)

Problem: When a USB 3.0 or USB 2.0 hub with numerous active Full-Speed (FS) or Low-Speed (LS) periodic endpoints attached is removed and then reconnected to a USB xHCI port, the xHCI controller may fail to fully refresh its cache of TRB records. The controller may read and execute a stale TRB and place a pointer to it in a Transfer Event TRB.

Implication: In some cases, the xHCI controller may read de-allocated memory pointed to by a TRB of a disabled slot. The xHCI controller may also place a pointer to that memory in the event ring, causing the xHCI driver to access that memory and process its contents, resulting in system hang, failure to enumerate devices, or other anomalous system behavior.

Note: This issue has only been observed in a stress test environment.

Workaround: None Identified.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP54. Frequency Reported by CPUID Instruction May Not Match Published Frequency

Problem: When the CPUID instruction is executed with EAX = 80000002H, 80000003H, and 80000004H, the frequency reported in the brand string may be truncated while the published frequency is rounded. For example a processor with a frequency of 2.166667GHz may be reported as 2.16GHz in the brand string instead of the published frequency of 2.17GHz

Implication: Intel® Pentium® Processor N3000 and J2000 series, and Intel® Celeron® N2000, J1700, J1800, and J1900 series processors may report in the brand string a frequency lower than the published frequency.

Workaround: None identified.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP55. Reset Sequence May Not Complete Under Certain Conditions

Problem: Under certain conditions, the SoC may not complete initialization either during a reset issued while the system is running or from the G3 (mechanically off) global system state.


Implication: When this erratum occurs, the SoC will detect an initialization problem and halt the initialization sequence prior to normal operation, leading to a system hang. The system will subsequently require a power cycle via the system power button.

Workaround: For the erratum occurring during reset while the system is running, a firmware code change has been identified which significantly reduces the likelihood of this erratum after the initial reset at power on.

In the rare situation of this sighting occurring, the end user is expected to execute a global reset by performing a Power Button Override by pressing the power button for approx. 4 seconds.

Contact your Intel representative on the guidance to implement these workarounds.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.



VLP56. Multiple Drivers That Access the GPIO Registers Concurrently May Result in Unpredictable System Behavior

Problem: The PCU (Platform Control Unit) in SoC may not be able to process concurrent accesses to the GPIO registers. Due to this erratum, read instructions may return 0xFFFFFFFF and write instructions may be dropped.

Implication: Multiple drivers concurrently accessing GPIO registers may result in unpredictable system behavior.

Workaround: GPIO drivers should not access GPIO registers concurrently. Each driver should acquire a global lock before accessing the GPIO register, and then release the lock after the access is completed. The Intel-provided drivers implement this workaround.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP57. Boot May Not Complete When SMI Occurs during Boot

Problem: During boot, the system should be able to handle SMIs (System Management Interrupt). Due to this erratum, boot may not complete when SMI occurs during boot.

Implication: If the system receives an SMI during boot, the boot may not complete.

Workaround: A BIOS code change has been identified and may be implemented as a workaround for this erratum.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP58. Interrupts That Target an APIC That is Being Disabled May Result in a System Hang

Problem: Interrupts that target a Logical Processor whose Local APIC is either in the process of being hardware disabled by clearing bit 11 in the IA32_APIC_BASE_MSR or software disabled by clearing bit 8 in the Spurious-Interrupt Vector Register at offset 0FOH from the APIC base are neither delivered nor discarded.

Implication: When this erratum occurs, the processor may hang.

Workaround: None identified. Software must follow the recommendation that all interrupt sources that target an APIC must be masked or changed to no longer target the APIC, and that any interrupts targeting the APIC be quashed, before the APIC is disabled.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP59. Corrected or Uncorrected L2 Cache Machine Check Errors May Log Incorrect Address in IA32_MCi_ADDR

Problem: For L2 Cache errors with IA32_MCi_STATUS.MCACOD (bits [15:0]) value 0000_0001_0000_1010b, the address reported in IA32_MCi_ADDR MSR may not be the address that caused the machine check.

Implication: Due to this erratum, the address reported in IA32_MCi_ADDR may be incorrect.

Workaround: None identified.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP60. Some USB Controller Capability Registers May Be Invalid After S3 Resume

Problem: The contents of several USB xHCI host capability registers may be invalid after an S3 Resume. Registers impacted by this erratum are HCCPARAMS, HCSPARAMS1, HCPARAMS3, USB2_PHY_PMC, USB_PGC, and XLTP_LTV1.

Implication: Software that depends on the contents of the named registers may not behave as expected, possibly leading to a USB driver failure or a system hang.

Workaround: A BIOS workaround has been identified.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.



VLP61. Removed duplicate of VLP50

VLP62. Top Swap Mechanism May Become Incorrectly Configured

Problem: Writing to the GCS (RCRB_GENERAL_CONTROL) register (RCRB_BAR, Offset 0x0) may cause the top swap mechanism to become incorrectly configured, resulting in unreliable boot behavior.

Implication: Due to this erratum, boot behavior may become unreliable which may impact system availability.

Workaround: It is possible for the firmware to contain a workaround for this erratum that disables the Top Swap mechanism

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP63. Certain Peripheral I/O Controllers May Hang After an Unexpectedly Long Latency Memory Transaction

Problem: When an eMMC (Embedded MultiMedia Card), LPE (Low Power Engine), xDCI (USB Device Mode Controller), SDIO (Secure Digital Input Output), or SD (Secure Digital) controller memory transaction encounters an unexpectedly long latency, this may cause the controller to hang.

Implication: When this erratum occurs, the peripheral I/O controller will hang.

Workaround: It is possible for the firmware to contain a workaround for this erratum.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP64. Disabling SDIO or SDCARD May Lead To a System Hang

Problem: If BIOS disables either the SDIO or the SDCard (but not both) and follows the recommended sequence of placing the disabled controller in D3, the remaining enabled controller may stop functioning and hang the system. If BIOS doesn't put the disabled controller in D3, the enabled controller will operate normally but entry to the S0ix low-power state is blocked.

Implication: When this erratum occurs, the SDIO or the SDCARD stops functioning and may hang the system.

Workaround: It is possible for the firmware to contain a workaround for this erratum.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP65. Video And/or Audio Artifact May Occur When Changing Frequencies

Problem: When changing the processor frequency, the SoC may fail to update the USB descriptor prior to xHCI consuming the descriptor when in ISOC mode.

Implication: When this erratum occurs, video or audio artifacts may occur.

Workaround: It is possible for firmware to contain processor configuration data and code changes as a workaround for this erratum.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.


VLP66. USB Device May Not be Detected at System Power-On

Problem: Certain internal conditions may cause the D- signal of one or more USB ports to get stuck at +3.3V during system power-on.

Implication: When this erratum occurs, a USB device attached to the affected port will not function. In addition, the OS may report problems with the USB port. This erratum may not affect all SoCs and has been observed only on platforms that ramp the 1.8V sustain rail (V1P8A) before ramping the 3.3V sustain rail (V3P3A).

Workaround: It is possible for the firmware to contain a workaround for this erratum.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.



VLP67. VM Exits During Execution of INTn in Virtual-8086 Mode with Virtual-Mode Extensions May Save RFLAGS Incorrectly

Problem: An APIC-access VM exit or a VM exit due to an EPT (Extended Page Table) violation or an EPT misconfiguration that occurs during execution of the INTn instruction in virtual-8086 mode (EFLAGS.VM = 1) with virtual-mode extensions (CR4.VME = 1) may save an incorrect value for RFLAGS in the guest-state area of the VMCS.

Implication: This erratum may cause a virtual-machine monitor to handle the VM exit incorrectly, may cause a subsequent VM entry to fail, or may cause incorrect operation of guest software.

Workaround: It is possible for the firmware to contain a workaround for this erratum.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP68. Clearing IA32_MCO_CTL[5] May Prevent Machine Check Notification

Problem: Clearing bit 5 of a logical processor’s IA32_MCO_CTL MSR (400H) may incorrectly block notifying other logical processors of any local machine check

Implication: The system may not react as expected to a machine check exception when IA32_MCO_CTL[5] is 0

Status: None identified.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP69. System May Unexpectedly Reboot After Shutdown

Problem: Certain internal conditions may cause the system to reboot immediately after a shutdown

Implication: A user shutdown request may not result in the system reaching a power-off condition

Workaround: It is possible for the firmware to contain a workaround for this erratum.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP70. LPE Audio Playback May Result in System Hang

Problem: Extended audio playback with the LPE (Low Power Engine) may result in a system hang if the SOC concurrently enters C6 or deeper sleep states.

Implication: The system may hang when this erratum occurs.

Workaround: It is possible for the driver to contain a workaround for this erratum.

Status: For the steppings affected, see “[Summary Table of Changes](#)”.

VLP71. LPC SERR Generation Can Not Be Independently Disabled

Problem: LPC SERR# events are incorrectly propagated to trigger the NMI interrupt when the SEE field of the PCIE_REG_COMMAND register (Bus 0; Device 31; Function 0; Offset 4h) is cleared. This erratum only affects systems with attached LPC devices that signal SERR# events.

Implication: SERR for LPC cannot be disabled using PCIE_REG_COMMAND SEE bit. SERR# is used on the LPC bus to carry the legacy ISA IOCHK# parity error indication.

Workaround: None identified. Software can clear NSC (NMI Status and Control) MSR (Bus 0; Device 31; Function 0; Offset 61h) SNE field to disable SERR for both NMI and LPC.

Status: For the steppings affected, see the “[Summary Table of Changes](#)”.



VLP72. Some RTIT Packets Following PSB May be Sent Out of Order or Dropped

Problem: When a complex micro-architectural condition occurs concurrently with the generation of a RTIT (Real-Time Instruction Trace) PSB (Packet Stream Boundary) packet, the packets that immediately follow the PSB could precede or overwrite some older packets. This erratum applies to no more than 21 packets immediately following the PSB.

Implication: The RTIT packet output immediately following a PSB may not accurately reflect software behavior, and may result in an RTIT decoder error.

Workaround: None identified.

Status: For the steppings affected, see the [“Summary Table of Changes”](#).

VLP73. Accessing Unimplemented ISP MMIO Space May Cause a System Hang

Problem: Access to unimplemented ISP (Image Signal Processor) registers should result in a software error. Due to this erratum, the transaction may not complete.

Implication: When this erratum occurs, the system may hang.

Workaround: Do not access unimplemented ISP MMIO space.

Status: For the steppings affected, see the [“Summary Table of Changes”](#).

VLP74. LPC Clock Control Using the ILB_LPC_CLKRUN# Signal May Not Behave As Expected

Problem: The ILB_LPC_CLKRUN# pin should be an input/open drain output signal as stated for the CLKRUN# signal in Section 2 of the Intel Low Pin Count (LPC) Interface Specification, Revision 1.1. Due to this erratum, if the signal is configured to be an output signal, the buffer may drive an active high level.

Implication: The processor may prevent a peripheral device from successfully requesting the LPC clock.

Workaround: None identified.

Status: For the steppings affected, see the [“Summary Table of Changes”](#).

VLP75. RTIT Trace May Contain FUP.FAR Packet with Incorrect Address

Problem: The FUP.FAR (Flow Update Packet for Far Transfer) generated by RTIT (Real Time Instruction Trace) on a far transfer instruction should contain the linear address of the first byte of the next sequential instruction after the far transfer instruction. Due to this erratum, far transfer instructions with more than 3 prefixes may incorrectly include an address between the first byte of the far transfer instruction and the last byte of the far transfer instruction.

Implication: The RTIT Trace decoder may incorrectly decode the trace due to an incorrect address in the FUP packet.

Workaround: The RTIT trace decoder can identify a FUP.FAR in the middle of a far transfer instruction and treat that FUP.FAR as if it was coming from the first byte of the following sequential instruction.

Status: For the steppings affected, see the Summary Table of Changes.

VLP76. RTIT May Delay the PSB by One Packet

Problem: After an RTIT (Real Time Instruction Trace) packet that exceeds the limit specified by Pkt_Mask in RTIT_PACKET_COUNT (MSR 77Ch) bits [17:16], the PSB (Packet Stream Boundary) packet should be sent immediately. Due to this erratum, the PSB packet may be delayed by one packet.

Implication: The PSB packet may be delayed by one packet.

Workaround: None identified.

Status: For the steppings affected, see the [“Summary Table of Changes”](#).



VLP77. RTIT TraceStop Condition Detected During Buffer Overflow May Not Clear TraceActive

- Problem:** If an RTIT (Real Time Instruction Trace) TraceStop condition is detected while RTIT_STATUS.Buffer_Overflow MSR (769H) bit 3 is set, the processor may not clear RTIT_CTL.TraceActive MSR (768H) bit 13, and tracing will continue after the overflow resolves. Such a case will be evident if the TraceStop packet is inserted before overflow is resolved, as indicated by the FUP.BuffOvf (Flow Update Packet for Buffer Overflow) packet.
- Implication:** The RTIT trace will continue tracing beyond the intended stop point.
- Workaround:** None identified.
- Status:** For the steppings affected, see the [“Summary Table of Changes”](#).

VLP78. RTIT FUP.BuffOvf Packet may be Incorrectly Followed by a TIP Packet

- Problem:** When RTIT (Real Time Instruction Trace) suffers an internal buffer overflow, packet generation stops temporarily, after which a FUP.BuffOvf (Flow Update Packet for Buffer Overflow) is sent to indicate the LIP that follows the instruction upon which tracing resumes. In some cases, however, this packet will be immediately followed by a FUP.TIP (Flow Update Packet for Target IP) which was generated by a branch instruction that executed during the overflow. The IP payload of this FUP.TIP will be the LIP of the instruction upon which tracing resumes.
- Implication:** The spurious FUP.TIP packet may cause the RTIT trace decoder to fail.
- Workaround:** The RTIT trace decoder should ignore any FUP.TIP packet that immediately follows a FUP.BuffOvf whose IP matches the IP payload of the FUP.BuffOvf.
- Status:** For the steppings affected, see the [“Summary Table of Changes”](#).

VLP79. RTIT CYC Packet Payload Values may be Off by 1 Cycle

- Problem:** When RTIT (Real Time Instruction Trace) is enabled with RTIT_CTL.Cyc_Acc MSR (768H) bit 1 set to 1, all CYC (Cycle Count) packets have a payload value that is one less than the number of cycles that have actually passed. Note that for CYC packets with a payload value of 0, the correct value may be 0 or 1.
- Implication:** The trace decoder will produce inaccurate performance data when using CYC packets to track software performance.
- Workaround:** As a partial workaround, the trace decoder should add 1 to the payload value of any CYC packet with a non-zero payload.
- Status:** For the steppings affected, see the [“Summary Table of Changes”](#).

VLP80. First MTC Packet after RTIT Enable May be Incorrect

- Problem:** When RTIT (Real Time Instruction Trace) is enabled, indicated by TriggerEn in bit 2 of the RTIT_STATUS MSR (769H) transitioning from 0 to 1, the first MTC (Mini Time Counter) packet may be sent at the wrong time.
- Implication:** The RTIT trace decoder will make incorrect assumptions about the TSC value based on an asynchronous MTC packet.
- Workaround:** The RTIT trace decoder should ignore the first MTC that follows trace enabling
- Status:** For the steppings affected, see the [“Summary Table of Changes”](#).



VLP81. Performance Monitoring Counter Overflows May Not be Reflected in IA32_PERF_GLOBAL_STATUS

Problem: When an overflow indication in IA32_PERF_GLOBAL_STATUS MSR (38EH) is cleared via either the logging of a PEBS (Precise Event Based Sampling) record or an MSR write to IA32_PERF_GLOBAL_OVF_CTRL MSR (390H), a simultaneous counter overflow may not set its corresponding overflow bit.

Implication: When this erratum occurs, a counter overflow will not be logged in IA32_PERF_GLOBAL_STATUS, although it may still pend a Performance Monitoring Interrupt.

Workaround: None identified.

Status: For the steppings affected, see the [“Summary Table of Changes”](#).

VLP82. xHCI Host Controller Reset May Cause a System Hang

Problem: xHCI Host Controller may not respond following system software setting (Bit 1='1') the Host Controller Reset (HCRST) of the USB Command Register (xHCIBAR+80h).

Implication: CATERR# may occur resulting in a system hang.

Workaround: A 1ms delay is necessary following system software setting (Bit 1='1') Host Controller Reset (HCRST) of the USB Command Register (xHCIBAR+80h).

Status: For the steppings affected, see the [“Summary Table of Changes”](#).

VLP83. PMI May be Pended When PMI LVT Mask Bit Set

Problem: If a performance counter overflow or Precise Event Based Sampling (PEBS) record generation is unable to trigger a Performance Monitoring Interrupt (PMI) due to the PMI Local Vector Table (LVT) entry's mask bit being set, the PMI should be dropped. Due to this erratum, the PMI may instead be pended and may be taken after the PMI LVT entry mask bit is cleared.

Implication: An unexpected PMI may occur.

Workaround: None identified.

Status: For the steppings affected, see the [“Summary Table of Changes”](#).

VLP84. TLB Entries May Not Be Invalidated Properly When Bit 8 Is Set in EPT Paging - Structure Entries

Problem: EPT (extended page tables) translates guest-physical addresses to physical addresses using EPT paging structures. Bit 8 of each EPT paging-structure entry is available to software and should be ignored by the processor. Due to this erratum, the INVVPID and MOV to CR3 instructions may fail to invalidate TLB entries that were created using EPT paging-structure entries in which bit 8 was set.

Implication: The affected TLB entries may be incorrectly shared across linear-address spaces, possibly leading to unpredictable guest behavior.

Workaround: It is possible for the firmware to contain a workaround for this erratum.

Status: For the steppings affected, see the [“Summary Table of Changes”](#).

VLP85. eMMC CRC Detection

Problem: The eMMC controller may fail to detect a CRC error if a bit error occurs on the DATA3 signal during read operations when in eMMC High Speed DDR mode. CRC detection on other DATA signals is not impacted.

Implication: The controller will not flag the CRC error to the driver or application, which could result in data integrity issues. Bit errors on eMMC DATA signals are not expected on platforms that follow Intel recommended design guidelines and tuning processes.

Workaround: None identified. To mitigate the issue, eMMC High Speed SDR mode can be used instead of High Speed DDR.



Status: For the steppings affected, see the ["Summary Table of Changes"](#).

§§



Specification Changes

1. Top Swap Feature

Due to Erratum VLP62, Top Swap Mechanism May Become Incorrectly configured” the Top Swap capability is de-featured. Affected documents are:

- Intel® Pentium® Processor N3500-series, J2850, J2900, and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750 Datasheet (document # 512177)

2. PCU-SPI AC Specification

Intel® Pentium® Processor N3500-series, J2850, J2900, and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750 - Datasheet, Document# 512177, Section 9.6.17 PCU-SPI AC Specification and Section 9.6.18 PCU- SPI NOR AC Specification updates:

The setup of PCU_SPI_MISO with respect to serial clock falling edge at the host (t184) as stated in Table 131 PCU-SPI NOR AC Specification, of Section 9.6.18 PCU SPI NOR AC Specification, is listed as 11ns (min). After re-checking post validation and simulation data, the value of t184 can be revised down to 6ns (min).

- Intel® Pentium® Processor N3500-series, J2850, J2900, and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750.


Table 131. PCU-SPI NOR AC Timing

Symbol	Parameter	Min.	Max	Units	Note
t180	Serial Clock Frequency	-	33	MHz	
t182	SPI Clock duty cycle at Host	45	55	%	
t183	Tco of PCU_SPI_MOSI with respect to serial clock falling edge at the host	-2	5	ns	
t184	Setup of PCU_SPI_MISO with respect to serial clock falling edge at the host	6		ns	
t185	Hold of PCU_SPI_MISO with respect to serial clock falling edge at the host	1		ns	
t186	Setup of PCU_SPI_CS[1:0]# with respect to serial clock falling edge at the host	12		ns	
t187	Hold of PCU_SPI_CS[1:0]# with respect to serial clock falling edge at the host	5		ns	
t188/ t189	Min Idle (de-assertion) time for PCU_SPI_CLK signals	32		ns	
Trise/ Tfall	Rise / Fall time	1	5	ns	1,2

15



Figure 65. SPI NOR Timing



§§




Specification Clarifications

S4/S5 to S0 (Power Up) Sequence.

Table 55. S4/S5 to S0 (Power Up) Sequence of the Intel® Pentium® Processor N3500-series, J2850, J2900, and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750 Datasheet, Doc #512177, these timings are allowed to have an error of up to 5%. When no max timing is specified, the actual timing should be as close to the min timing as possible under normal operating conditions (typically within one additional unit of time), but no max timing is guaranteed.

§ §



Documentation Changes

1. tREFI Refresh Period Unit of Measurement Correction

The description of the DRFC.tREFI register field incorrectly lists the unit of measurement as seconds (s) in Doc# 512177 *Intel® Pentium® Processor N3500-series, J2850, J2900, and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750 –Datasheet*, Section 12.3.9. The correct unit of measurement is microseconds (µs) and the corrected description of DRFC.tREFI is as follows:

- tREFI Refresh Period: Specifies the average time between sending REF commands to DRAM. The Dunit will guarantee that the average time is met, but maintains a certain degree of flexibility in the exact REF scheduling in order to increase overall performance. 0h - Refresh disabled 1h - Reserved for pre-silicon simulation 2h - 3.9 µs (Extended Temperature Range, 85-95 C) 3h - 7.8 µs (Normal Temperature Range, 0-85 C).

2. FIFOSE_RCVR (RCVR) and Res_TET (TET) Field Name Description trigger levels correction Intel® Pentium® Processor N3500- series, J2850, J2900, and Intel® Celeron® Processor N2900- series, N2800-series, J1800-series, J1900, J1750 Datasheet, Doc#512177, Section 25.6.3 Interrupt Identification Register and FIFO Control Register (IIR_FCR) – Offset 8h.

The trigger levels for FIFOSE_RCVR (RCVR) and Res_TET (TET) need to be revised as follows:

Table 263. Trigger Levels for FIFOSE_RCVR (RCVR) and Res_TET (TET)

Bit Range	Default and Access	Field Name (ID): Description
7:6	0h RW	FIFOSE_RCVR (RCVR): This is used to select the trigger level in the receiver FIFO at which the Received Data Available Interrupt is generated. In auto flow control mode it is used to determine when the <code>rts_n</code> signal is deasserted. It also determines when the <code>dma_rx_req_n</code> signal is asserted in certain modes of operation. The following trigger levels are supported: <ul style="list-style-type: none"> • 00 = 1 character in the FIFO • 01 = FIFO ¼ full • 10 = FIFO ½ full • 11 = FIFO 2 less than full
5:4	0h RW	Res_TET (TET): TX Empty Trigger. This is used to select the empty threshold level at which the THRE Interrupts are generated when the mode is active. It also determines when the <code>dma_tx_req_n</code> signal is asserted when in certain modes of operation. The following trigger levels are supported: <ul style="list-style-type: none"> • 00 = FIFO empty • 01 = 2 characters in the FIFO • 10 = FIFO ¼ full • 11 = FIFO ½ full

3. IC_SLAVE_DISABLE Field Name Description Correction

Intel® Pentium® Processor N3500- series, J2850, J2900, and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750 Datasheet, Doc #512177, Section 24.7.1 I2C Control Register (IC_CON) - Offset 0h



The Field Name (ID): Description for Bit Range 6, IC_SLAVE_DISABLE, needs to be revised as follows:

Bit Range	Default and Access	Field Name (ID): Description
6	1h RW	IC_SLAVE_DISABLE: This bit controls whether I2C has its slave disabled. By default, the slave is always enabled (in reset state as well). If you need to disable it after reset, set this bit to 1. If this bit is set (slave is disabled), DW_apb_i2c functions only as a master and does not perform any action that requires a slave. <ul style="list-style-type: none"> • 0: slave is enabled • 1: slave is disabled

4. SPEED Field Name Description Correction

Intel® Pentium® Processor N3500- series, J2850, J2900, and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750 Datasheet, Doc #512177, Section 24.7.1 I2C Control Register (IC_CON) - Offset 0h

The Field Name (ID): Description for Bit Range 2:1, SPEED, needs to be revised as follows:

Bit Range	Default and Access	Field Name (ID): Description
2:1	3h RW	SPEED: These bits controls at which speed the DW_apb_i2c operates; its setting is relevant only if one is operating the DW_apb_i2c in master mode. Hardware protects against illegal values being programmed by software. This register should be programmed only with a value in the range of 1 to IC_MAX_SPEED_MODE. <ul style="list-style-type: none"> 01: Standard mode (0 to 100 kbit/s) 10: Fast mode (<= 400 kbit/s) 11: High speed mode (<= 3.4 Mbit/s)

5. MASTER MODE (MASTER_MODE) Field Name Description Correction

Intel® Pentium® Processor N3500- series, J2850, J2900, and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750 Datasheet, Doc #512177, Section 24.7.1 I2C Control Register (IC_CON) - Offset 0h

The Field Name (ID): Description for Bit Range 0, MASTER MODE (MASTER_MODE), needs to be revised as follows:

Bit Range	Default and Access	Field Name (ID): Description
0	1h RW	MASTER MODE (MASTER_MODE): This bit controls whether the DW_apb_i2c master is enabled. Software should ensure that if this bit is set to '1', then bit 6 should also be set to '1'. <ul style="list-style-type: none"> 0: Master disabled 1: Master enabled

6. IC_10BITADDR_MASTER Field Name Description Correction

Intel® Pentium® Processor N3500- series, J2850, J2900, and Intel® Celeron® Processor N2900-series, N2800-series, J1800-series, J1900, J1750 Datasheet, Doc #512177, Section 24.7.2 I2C Target Address Register (IC_TAR) - Offset 4h



The Field Name (ID): Description for Bit Range 12, IC_10BITADDR_MASTER, needs to be revised as follows:

Bit Range	Default and Access	Field Name (ID): Description
12	1h RW	IC_10BITADDR_MASTER: This bit controls whether the DW_apb_i2c starts its transfers in 7- or 10-bit addressing mode when acting as a master. 0: 7-bit addressing 1: 10-bit addressing

The following registers are an addition to section 17.10 of the EDS to document which register fields are programmed as part of the workaround for erratum VLP66.

USB2 Test Per Port Register 1 (USB2_TEST_PERPORT_REG1_LANE0/1/2/3) - Offset 4113h/4213h/4313h/4413h

Access Method

Type: Message Bus Register (Size: 32 bits)

Op Codes: 6h - Read, 7h - Write

Default: 00000000h

Offset: [Port: 0x43] + 4113h/4213h/4313h/4413h

Bit Range	Default and Access	Field Name (ID): Description
31:29	0x0 RO	Reserved
8	0x0 RW	This register field is used in the workaround to erratum VLP66. It is Reserved for all other purposes.
7:4	0x0 RW	Reserved
3	0x0 RW	This register field is used in the workaround to erratum VLP66. It is Reserved for all other purposes.
2:0	RW	Reserved

Per Port RCOMP High Speed Pull down Register (PER_PORT_RCOMP_HS_PULLDOWN_REGISTER_LANE0/1/2/3) - Offset 4123h/4223h/ 4323h/4423h

Access Method

Type: Message Bus Register (Size: 32 bits)

Op Codes: 6h - Read, 7h - Write

Default: 00000011h



Offset: [Port: 0x43] + 4123h/4223h/4323h/4423h

Bit Range	Default and Access	Field Name (ID): Description
31:30	0x0 RO	Reserved
29:24	0x0 RW	Reserved
23:15	0x0 RO	Reserved
14:8	0x0 RW	This register field is used in the workaround to erratum VLP66. It is Reserved for all other purposes.
7:5	0x0 RW	Reserved
4	0x1 RW	Reserved
3	0x0 RW	This register field is used in the workaround to erratum VLP66. It is Reserved for all other purposes.
2:0	0x1 RW	Reserved

USB Per Port (USB2_PER_PORT_2_LANE0/1/2/3) – Offset 4126h/4226h/4326h/4426h

Access Method

Type: Message Bus Register (Size: 32 bits)

Op Codes: 6h - Read, 7h - Write

Default: 00001249h

Offset: [Port: 0x43] + 4126h/4226h/4326h/4426h

Bit Range	Default and Access	Field Name (ID): Description
31:13	0x0 RO	Reserved
12:11	0x2 RW	This register field is used in the workaround to erratum VLP66. It is Reserved for all other purposes.
10:9	0x1 RW	This register field is used in the workaround to erratum VLP66. It is Reserved for all other purposes.
8	0x0 RW	This register field is used in the workaround to erratum VLP66. It is Reserved for all other purposes.



Bit Range	Default and Access	Field Name (ID): Description
7:5	0x2 RW	This register field is used in the workaround to erratum VLP66. It is Reserved for all other purposes.
4:2	0x2 RW	This register field is used in the workaround to erratum VLP66. It is Reserved for all other purposes.
1:0	0x1 RW	This register field is used in the workaround to erratum VLP66. It is Reserved for all other purposes.

PCU-iLB-LPC AC Specification Numbering Correction

Intel Pentium Processor N3500-series, J2850, J2900, and Intel Celeron Processor N2900-series, N2800-series, J1800-series, J1900, J1750 - External Design Specification EDS, Document# 512177, Section 9.6.20 PCU-iLB-LPC AC Specification, Table 134 will be revised as follows:

Numbering for corresponding figures mentioned are wrong and should be corrected as shown below.

Table 134. LPC AC Specifications (with loop back from ILB_LPC_CLK[0] to ILB_LPC_CLK[1])

Sym	Parameter	Min	Max	Units	Notes	Fig
T _{CO}	ILB_LPC_AD[3:0], ILB_LPC_FRAME#, ILB_LPC_SERIRQ Valid Delay from ILB_LPC_CLK[1] Rising	2	14	ns		68
T _{EN_AD}	ILB_LPC_AD[3:0], ILB_LPC_FRAME#, ILB_LPC_SERIRQ Output Enable Delay from ILB_LPC_CLK[1] Rising	2		ns		69
T _{FD_AD}	ILB_LPC_AD[3:0] Float Delay from ILB_LPC_CLK[1] Rising		28	ns		70
T _{SU_AD}	ILB_LPC_AD[3:0] Setup Time to ILB_LPC_CLK[1] Rising	7		ns		71
T _{HD_AD}	ILB_LPC_AD[3:0] Hold Time from ILB_LPC_CLK[1] Rising	0		ns		71
T _{lpc}	ILB_LPC_CLK[1:0] Duty Cycle	35	65	%	1	