



*This Technical Advisory describes an issue which may or may not affect the customer's product*

# Intel Technical Advisory

TA-0981-1

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

June 14, 2011

## Intel® Workstation Board WX58BP, with board PBA# D64644-203 or later, does not support BIOS revisions prior to R0042

*Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The Intel products described herein may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.*

### Products Affected

Product	Product code	MM#
Intel® Workstation Board WX58BP	WX58BPR	911688

### Description

Intel® Workstation Board WX58BP, with PBA# D64644-203 (AA# D64643-203) or later (please refer to the white sticker on the motherboard for this information), does not support BIOS revisions prior to R0042.

The affected product is the Intel® Workstation Board WX58BP.

### Root Cause

PBA# D64644-203 incorporates a new BIOS flash component to replace a discontinued part.

### Corrective Action / Resolution

Intel recommends users of the affected board not to downgrade BIOS to versions prior to BIOS version R0042. Attempting to perform such a downgrade will result in the motherboard being rendered inoperable.

### Workarounds

Performing a BIOS recovery using BIOS R0042 (or later) is the only recommended workaround in instances where corruption (due to downgrading) has rendered the motherboard inoperable. The BIOS recovery process is documented in the BIOS release notes.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division  
Intel Corporation