



Intel® Ethernet Switch Silicon

Product Update Bulletin

PUB: FMxxxx-004

Summary

This Product Update Bulletin (PUB) provides notification of updates to former Fulcrum products as follows:

Notification Date	8/24/11
Effective Date	Effective 9/1/11
Products Affected	Members of the FM2xxx, FM3xxx and FM4xxx families.
Type of Change	FocalPoint part number changes.

Overview

The following FocalPoint product numbers will be changed. This change affects all versions of the base part number.

Base Part Number	New Part Number	New Commercial Temp MM#	New Extended Temp MM#
FM2208	FM2112	920985	920986
FM2104	FM2112	920985	920986
FM2103	FM2112	920985	920986
FM3224	FM4224	921068	921069
FM3212	FM4212	921073	921070
FM3208	FM4112	921071	921072
FM3112	FM4112	921071	921072
FM3410	FM4410	920987	920988
FM3104	FM4112	921071	921072
FM3103	FM4112	921071	921072
FM4208	FM4112	921071	921072
FM4104	FM4112	921071	921072
FM4103	FM4112	921071	921072

Product Changes

This update only affects the part number marking, and there are no changes to the product form, fit or function. There are no changes to the package, die, test or assembly. There will be no price increase for existing customers.

Software Implication

There is no change to the software. The customer software may need to reflect the new replacement part number.

Conversion Timeframe

Customers will have 3 months from the effective date of this notice to start ordering the replacement part numbers. The last shipment date of these part numbers will be 6 months after the effective date. Customer POs should be updated to reflect these changes.

Contact Information

For additional information about this PUB, contact your local Intel sales representative.