



Previously Logo'd Motherboard Logo Program (PLMP)

# Intel® Desktop Board

## DH61WW

---

# PLMP Report

3/30/2011

**Purpose:**

This report describes the DH61WW Previously Logo'd Motherboard Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel® Core™ i7 and Intel® are trademarks of Intel Corporation in the U.S. and other countries.

\*Other names and brands may be claimed as the property of others

Copyright © 2009, Intel Corporation. All rights reserved.

# Contents

---

<b>Introduction .....</b>	<b>4</b>
Terms and Definitions.....	4
<b>Desktop Board Configuration .....</b>	<b>5</b>
Desktop Board DH61WW Final Configuration Report: Completion of PLMP .....	5
Board Information.....	5
Product Code.....	5
Processor .....	5
Motherboard .....	5
System Memory.....	5
Power Management.....	5
Operating System Tested.....	5
Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit.....	6
Windows Logo Kits Used (WLK) .....	6
Errata and Contingencies .....	7
Test Notes .....	8

# Introduction

---

## Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
WLK	Windows Logo Kits
PLMP	Previously Logo'd Motherboard Logo Program. For further information see: <a href="http://www.microsoft.com/whdc/hwtest/default.msp">http://www.microsoft.com/whdc/hwtest/default.msp</a>
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: <a href="http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;q=s">http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;q=s</a>

# Desktop Board Configuration

---

## Desktop Board DH61WW Final Configuration Report: Completion of PLMP

Data in this section reflects system configuration at time of PLMP submission.

### Board Information

Product Code <sup>1</sup>	BIOS String/Model	Technologies NOT Logo'd (yet)
DH61WW	BEH6110H.86A.0016.2011.0118.1128	N/A - all technologies logo'd
<b>Processor</b>		
Speed	3.30GHz	
Family	Intel Core i5 CPU 2500K	
Bus Speed	100 MHz	
<b>Motherboard</b>		
Board AA #	G23116	
Board FAB #	201 (eg. 10x for fab A, 20x for fab B and etc)	
<i>* This report applies to the production FAB revision; Please consult your Intel Corporation representative to clarify the motherboard revision you intend to perform logo testing if not the same.</i>		
<b>System Memory</b>		
Speed	Dual Channel, DDR3, 1333MHz	
Memory Type	DIMM	
Connector Type	DDR3, 240 Pin	
<b>Power Management</b>		
BIOS Default	S3	
<b>Operating System Tested</b>		
	<b>Check Tested</b>	<b>Comments</b>
Windows 7 and 64-bit	<input checked="" type="checkbox"/>	Windows 7 Ultimate
Windows Vista and 64-bit	<input type="checkbox"/>	Vista Ultimate with Service Pack 2
Windows Vista Basic and 64-bit	<input type="checkbox"/>	Vista Basic with Service Pack 2

---

<sup>1</sup> These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

## Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit

Technology	OS	Version	Package version
<b>Chipset Update Utility</b> Intel® Chipset Software Utility	Windows 7	V9.2.0.1019	INF_allIOS_9.2.0.1019_PV
	Windows 7 64-bit	V9.2.0.1019	INF_allIOS_9.2.0.1019_PV
<b>Graphics</b> Intel(R) HD Graphics Family	Windows 7	V8.15.10.2291	GFX_Vista32_Win7_32_8.15.10.2291_PV
	Windows 7 64-bit	V8.15.10.2291	GFX_Vista64_Win7_64_8.15.10.2291_PV
<b>Audio</b> Realtek High Definition Audio	Windows 7	V6.0.1.6299	AUD_Vista_Win7_6.0.1.6299_PV
	Windows 7 64-bit	V6.0.1.6299	AUD_Vista_Win7_6.0.1.6299_PV
<b>LAN</b> Intel(R) 82579V Gigabit Network Connection	Windows 7	V11.8.84.0	LAN_allIOS_11.8.84.0_P V
	Windows 7 64-bit	V11.8.84.0	LAN_allIOS_11.8.84.0_P V
<b>MEI</b> Intel® Management Engine Interface	Windows 7	V7.0.0.1144	MEI_allIOS_7.0.4.1197_PV
	Windows 7 64-bit	V7.0.0.1144	MEI_allIOS_7.0.4.1197_PV

## Windows Logo Kits Used (WLK)

Microsoft website: <http://www.microsoft.com/whdc/DevTools/WDK/DTM.mspx>

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit
Windows 7 Windows 7 64-bit	<a href="#">WLK1.5 for Windows 7</a>	<a href="#">WLK1.5 for Windows 7</a>

## Errata and Contingencies

Operating System	Failing Test	Expiry Date	ID Number	Type	Error Description
Windows7 Windows7 64bit	Class Driver AC3 Test - Win7 (System)	6/30/2025	1256	Erratum	Run AC3 test on a system with the Microsoft HD Audio class driver installed. Expected results: All AC3 kernel streaming data ranges should advertise MinimumBitsPerSample = 16 and MaximumBitsPerSample = 16. Actual results: HD Audio class driver sometimes advertises MaximumBitsPerSample = 24.
Windows7 Windows7 64bit	PCI Hardware Compliance Test For Systems	12/1/2012	401	Erratum	The following PCI Compliance test failure is acceptable: Bit 15 (Bridge Configuration Retry Enable) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-only and always return 0 as it is reserved for devices other than PCI Express to PCI/PCI-X Bridges. Assertion 13A41D3E-2576-41DC-A67C-525DA3637CEA This failure is acceptable because this is a PCIe 1.1 feature and the WLP requires compliance with only PCIe 1.0a.
Windows7 Windows7 64bit	UAA Test - Win7 (System)	6/1/2015	513	Erratum	UAA Test requires the Traffic Priority bit to be read/write - however there are two specs that apply, and they conflict. One says the bit must be read/write, the other says it must be read-only. Contact has been made with the author of both specs (Intel) but until this point is clarified we cannot fail submissions containing this test failure.

## Test Notes

Operating System	Test	Description
Windows 7	BIOS download	Internal: <a href="http://bios.intel.com/downloads/">http://bios.intel.com/downloads/</a> External: <a href="http://www.intel.com/">http://www.intel.com/</a> click on Support and Download
Windows 7	BIOS setup	Please make sure the BIOS setting are as below, otherwise use default settings.  System Date and Time: Current date and time Peripheral Configuration: Enable all onboard component (Except CIR) Drive Configuration: Set to AHCI Chipset Configuration: Enable HPET ACPI Suspend State: Set to <S3 State> Boot Device Priority: set <Hard Disk Driver> to first  Note: Enhanced Consumer IR (CIR) component is not supported under Windows7.
Windows 7 filter update	WLK WHQL test	<a href="http://winqual.microsoft.com/member/SubmissionWizard/LegalExemptions/filterupdates.cab">http://winqual.microsoft.com/member/SubmissionWizard/LegalExemptions/filterupdates.cab</a>
Special H/W that use to PASS the test	None	None