

CUSTOMER ADVISORY
MAX 5000 ORDERING CODE CHANGE

In December of 1995, Altera announced ordering code changes in its Classic EP6XX component line. In keeping with this strategy, we are now consolidating selected MAX 5000 ordering codes (Table 1 lists the ordering codes affected under this consolidation).

Altera will continue to accept orders for the current MAX 5000 ordering codes until September 30, 1996. Final shipments by Altera against existing ordering codes shown in Table 1 below will occur on or before December 31, 1996.

Should you need additional information or assistance, please contact your local Altera sales representative. Your cooperation is greatly appreciated.

Table 2: Affected MAX 5000 Ordering Codes

| Existing Ordering Code | Substitute Ordering Code |
|------------------------|--------------------------|
| EPM5032DC-17 | EPM5032DC-15 |
| EPM5032DC-25 | EPM5032DC-20 |
| EPM5032DI-25 | EPM5032PI-25 |
| EPM5032JC-17 | EPM5032JC-15 |
| EPM5032JC-25 | EPM5032JC-20 |
| EPM5032JI-25 | EPM5032LI-25 |
| EPM5032LC-17 | EPM5032LC-15 |
| EPM5032LC-25 | EPM5032LC-20 |
| EPM5032PC-17 | EPM5032PC-15 |
| EPM5032SC-17 | EPM5032SC-15 |
| EPM5032SC-20 | EPM5032SC-15 |
| EPM5032SC-25 | EPM5032SC-15 |
| EPM5064JC | EPM5064JC-1 |
| EPM5064JI | EPM5064LI |
| EPM5064JC-2 | EPM5064JC-1 |
| EPM5128GC | EPM5128GC-1 |
| EPM5128GC-2 | EPM5128GC-1 |
| EPM5128JC | EPM5128JC-1 |

| Existing Ordering Code | Substitute Ordering Code |
|------------------------|--------------------------|
| EPM5128JI | EPM5128LI-2 |
| EPM5128JC-2 | EPM5128JC-1 |
| EPM5128JI-2 | EPM5128LI-2 |
| EPM5128LI | EPM5128LI-2 |
| EPM5130GC-2 | EPM5130GC-1 |
| EPM5130JC-2 | EPM5130JC-1 |
| EPM5130LC-2 | EPM5130LC-1 |
| EPM5130QC-2 | EPM5130QC-1 |
| EPM5130WC | EPM5130QC |
| EPM5130WC-2 | EPM5130QC-1 |
| EPM5130WC-1 | EPM5130QC-1 |
| EPM5192GC | EPM5192GC-1 |
| EPM5192GC-2 | EPM5192GC-1 |
| EPM5192JC | EPM5192JC-1 |
| EPM5192JI | EPM5192LI |
| EPM5192JC-2 | EPM5192JC-1 |
| EPM5192LC-2 | EPM5192LC-1 |