



## **PRODUCT DISCONTINUANCE NOTIFICATION PDN0314**

### **Change Description:**

Altera will be discontinuing the ordering codes listed in Tables 1–5.

### **Reason For Change:**

Customer usage has declined to the point where continued manufacturing is no longer economical.

### **Key Obsolescence Dates:**

Date for last order acceptance:	December 15, 2004
Date for last Altera shipments:	June 15, 2005

### **Contact:**

Please contact your local Altera® sales representative if you require additional information regarding this discontinuance.

## PRODUCT DISCONTINUANCE NOTIFICATION PDN0314

### PRODUCT ORDERING CODES AFFECTED:

**Table 1: Configuration Device Product Ordering Codes to Become Obsolete**

Ordering Code	Compatible Substitute
EPC1064TC32	EPC1441TC32
EPC1064VLC20	EPC1441LC20
EPC1064VPC8	EPC1441PC8

**Table 2: FLEX® 10KA Product Ordering Code to Become Obsolete**

Ordering Code	Compatible Substitute
EPF10K10AQI208-3	EPF10K10AQC208-2

**Table 3: FLEX 10KE Product Ordering Code to Become Obsolete**

Ordering Code	Compatible Substitute
EPF10K50SFI484-2	EPF10K50SFC484-1

**Table 4: FLEX 6000 Product Ordering Codes to Become Obsolete**

Ordering Code	Compatible Substitute
EPF6016AQI208-2	EPF6016AQC208-1
EPF6016AQI208-3	EPF6016AQC208-2
EPF6016ATI144-2	EPF6016ATC144-1
EPF6024ABI256-2	EPF6024ABC256-1
EPF6024AQI208-3	EPF6024AQC208-2

**Table 5: FLEX 8000 Product Ordering Codes to Become Obsolete**

Ordering Code	Compatible Substitute
EPF81188AQI208-3	EPF81188AQC208-2
EPF8282ALI84-4	EPF8282ALC84-3
EPF8452AQI160-3	EPF8452AQC160-2
EPF8636AGC192-3	C.F.
EPF8636ARC208-3	EPF8636AQC208-3
EPF8636ARC208-4	EPF8636AQC208-4
EPF8820ARI208-4	EPF8820AQC208-3

C.F. – Call Factory