


## Attention!



The processor fan heatsink must align properly with the 370-pin socket. Make sure to align the fan heatsink with the socket base as shown above. This will align the fan cable with the PGA370 mark on the socket. **Note: The Intel® Celeron™ processor at 533 MHz and greater ships with a 3 wire fan.**



Intel recommends this processor for motherboards that utilize the 370-pin socket, and are validated for these processors. Use of this Intel Celeron processor in **some** 370-pin socket motherboards or with some “slot-to-socket” adapters (SSA) may result in processor damage. Contact your motherboard manufacturer to ensure that your motherboard and SSA have been validated for use with this specific processor. For more specific information, please go the World Wide Web as listed below.

**<http://support.intel.com/support/processors>**

Copyright © Intel Corporation 2000.

\*Third-party brands and names are the property of their respective owners.

Part Number A02794-002  
Second Edition January 2000