



Windows Hardware Certification (WHC)

Intel® Desktop Board

DX79TO

---

# Desktop/Motherboard WHC Report

3/21/2013

**Purpose:**

This report describes the DX79TO Motherboard Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel® Core™ i7 and Intel® are trademarks of Intel Corporation in the U.S. and other countries.

\*Other names and brands may be claimed as the property of others

Copyright © 2009, Intel Corporation. All rights reserved.

# Contents

---

<b>Introduction</b> .....	<b>4</b>
Terms and Definitions.....	4
<b>Desktop Board Configuration</b> .....	<b>5</b>
Desktop Board DX79T0 Final Configuration Report: Completion of WHC.....	5
Board Information.....	5
Product Code.....	5
Processor .....	5
Motherboard .....	5
System Memory.....	5
Power Management.....	5
Operating System Tested.....	5
Onboard Integrated Devices and Driver for Windows 8 64-bit .....	6
Windows Hardware Certification Kit Used (WHCK).....	6
Errata and Contingencies.....	7
Test Notes .....	7

# Introduction

---

## Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
WHCK	Windows Hardware Certification Kit
MLP	Motherboard Logo Program. For further information see: <a href="http://msdn.microsoft.com/en-us/windows/hardware/gg463010.aspx">http://msdn.microsoft.com/en-us/windows/hardware/gg463010.aspx</a>
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: <a href="http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;q=s">http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;q=s</a>

# Desktop Board Configuration

---

## Desktop Board DX79TOfinal Configuration Report: Completion of WHC

Data in this section reflects system configuration at time of WHC submission.

### Board Information

Product Code <sup>1</sup>	BIOS String/Model	Technologies NOT Logo'd (yet)
DX79SI	SIX7910D.86A.1777.2013.0204.1605	N/A - all technologies logo'd
<b>Processor</b>		
Speed	3.20GHz	
Family	Core i7 3930K	
Bus Speed	100 MHz	
<b>Motherboard</b>		
Board AA #	G28805	
Board FAB #	402 (eg. 10x for fab A, 20x for fab B and etc)	
* This report applies to the production FAB revision; Please consult your Intel Corporation representative to clarify the motherboard revision you intend to perform logo testing if not the same.		
<b>System Memory</b>		
Speed	Dual Channel, DDR3, 1333MHz	
Memory Type	DIMM	
Connector Type	DDR3, 240 Pin	
<b>Power Management</b>		
BIOS Default	S3	
<b>Operating System Tested</b>		
	<b>Check Tested</b>	<b>Comments</b>
Windows 8 64-bit	<input checked="" type="checkbox"/>	Windows 8 Professional
Windows 7 and 64-bit	<input type="checkbox"/>	Windows 7 Ultimate Service Pack 1
Windows Vista and 64-bit	<input type="checkbox"/>	Vista Ultimate with Service Pack 2
Windows Vista Basic and 64-bit	<input type="checkbox"/>	Vista Basic with Service Pack 2

---

<sup>1</sup> These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

## Onboard Integrated Devices and Driver for Windows 8 64-bit

Technology	OS	Version	Package version
<b>Chipset Update Utility</b> Intel® Chipset Software Utility	Windows 8 64-bit	V9.2.3.1023	INF_allIOS_9.2.3.1023_PV
<b>Graphics</b> Nvidia GeForce GTX 275	Windows 8 64-bit	V9.18.13.1090	310.90-desktop-win8-win7-winvista-64bit-english-whql
<b>Audio</b> Realtek	Windows 8 64-bit	V6.0.1.6804	AUD_allIOS_6.0.1.6804_PV
<b>LAN</b> Intel® 82579LM Gigabit	Windows 8 64-bit	V12.2.45.0	PROWin8_64_v17.3
<b>MEI</b> Intel® Management Engine Interface	Windows 8 64-bit	V8.1.0.1263	MEI_Win8_8.1.10.1286_PV

## Windows Hardware Certification Kit Used (WHCK)

Microsoft website: <http://msdn.microsoft.com/library/windows/hardware/hh833788>

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit
Windows 8 64-bit	WHCK for Windows 8	WHCK for Windows 8

## Errata and Contingencies

Operating System	Falling Test	Expiry Date	ID Number	Type	Error Description
Windows 8 64-bit	Single Computer Display Object test	08/01/2013	884	Erratum	AllInOne desktop computers have the "Computer.AllInOne" form factor. For this form factor, the test should recognize the mouse and keyboard to be external to the main computer machine. Without this filter it expects the mouse/keyboard to be part of the computer which may not be the case. t.
Windows 8 64-bit	UAA Test (System)	7/1/2013	244	Contingency	Section 3.3.14 of the Intel High Definition Audio specification mandates a reset value of 0 for the Interrupt Control register on HD Audio controllers.
Windows 8 64-bit	UAA Test (System)	7/1/2014	354	Contingency	The FIFO size for Input and Output Stream Descriptors should be read only.
Windows 8 64-bit	PCI Hardware Compliance Test For Systems	01/01/2015	13	Contingency	Legacy hardware filter.

## Test Notes

Operating System	Test	Description
Windows 8	BIOS download	Internal: <a href="http://bios.intel.com/downloads/">http://bios.intel.com/downloads/</a> External: <a href="http://www.intel.com/">http://www.intel.com/</a> click on Support and Download
Windows 8	BIOS setup	Please make sure the BIOS setting are as below, otherwise use default settings.  System Date and Time: Current date and time Peripheral Configuration: Enable all onboard component Drive Configuration: Set to AHCI Chipset Configuration: Enable HPET ACPI Suspend State: Set to <S3 State> Boot Device Priority: set <Hard Disk Driver> to first Enhanced Consumer IR (CIR) component: Enable
Windows 8 filter update	WHCK WHQL test	<a href="https://sysdev.microsoft.com/member/SubmissionWizard/LegalExemptions/HCKFilterUpdates.cab">https://sysdev.microsoft.com/member/SubmissionWizard/LegalExemptions/HCKFilterUpdates.cab</a>
Special H/W that use to PASS the test	None	None