
Report of Compliance

Report of Compliance has been accepted.

Report No.:2011022172

Acceptance No.:2011016029

<Contact person's information>

<Member's profile>

Member number:338

Company name:Intel K.K.

Address:茨城県つくば市東光台5-6

<Responsible person>

Department:LNO

Name:Robert Sem

E-mail:robert.k.sem@intel.com

<Contact person>

Address:2111 NE 25th Avenue Hillsboro, OR 97124 Department:LNO Name:Robert Sem

Phone:503 264 4430

FAX:5032640124

E-mail:robert.k.sem@intel.com

<Recipient of certificate of reporting>

Department:LNO

E-mail:robert.k.sem@intel.com

Reporting type:new

Name of ITE:LAN card

Classification of ITE and classification code:Class A / Classification code W1 Product type (Model No.):G58497, 49Y7971, 49Y7972, X540T2 <Brand(1)>

Name of the brand supplier:

Member number of the supplier:

Product type (Model No.) of the branded ITE:

<Brand(2)>

Name of the brand supplier:

Member number of the supplier:

Product type (Model No.) of the branded ITE:

<Brand(3)>

Name of the brand supplier:

Member number of the supplier:

Product type (Model No.) of the branded ITE:

<Brand(4)>

Name of the brand supplier:
Member number of the supplier:
Product type (Model No.) of the branded ITE:
<Brand(5)>

Name of the brand supplier:
Member number of the supplier:
Product type (Model No.) of the branded ITE:
Name of the testing laboratory:Northwest EMC, Inc.
<Measurement facility registration number> Radiated EMI measurement below 1GHz facility:R-2318 (10m) Radiated EMI measurement above 1GHz facility:G-84 (3m) Mains port conducted EMI measurement facility:C-2687 Telecommunication ports conducted EMI measurement facility:T-1658 Date of testing:2012-02-23 2/23; 2/24; 2/27; and 2/28/2012 Serial No. of the test report:INTE5317 Reason for addition/modification:

VCCI comment:

VCCI Council

URL : <http://www.vcci.jp/>

E-mail : aplimg@vcci.jp