

CUSTOMER ADVISORY FLEX 8000 ORDERING CODE CHANGE

Throughout 1995 and 1996, Altera has announced ordering code changes in its Classic, MAX, and FLEX device families. In keeping with this strategy, we are now consolidating selected FLEX 8000 ordering codes. Please note that the substitute ordering codes are functional- and pin-compatible replacements for all affected ordering codes.

Altera will continue to accept orders for the current FLEX ordering codes until March 31, 1997. Final shipments of the existing ordering codes by Altera will occur no later than June 30, 1997.

Should you need additional information or assistance, please contact your local Altera sales representative. Your cooperation is greatly appreciated.

FLEX 8000 Ordering Code Changes

Existing Code	Substitute Code	Existing Code	Substitute Code
EPF81188AGC232-2A	EPF81188AGC232-2	EPF8452AGC160-5	EPF8452AGC160-4
EPF81188AGC232-5	EPF81188AGC232-4	EPF8452AGC160-6	EPF8452AGC160-4
EPF81188AGC232-6	EPF81188AGC232-4	EPF8452ALC84-5	EPF8452ALC84-4
EPF81188AQC208-2A	EPF81188AQC208-2	EPF8452ALC84-6	EPF8452ALC84-4
EPF81188ARC240-2A	EPF81188AQC240-2*	EPF8452AQC160-5	EPF8452AQC160-4
EPF81188ARC240-5	EPF81188AQC240-4*	EPF8452AQC160-6	EPF8452AQC160-4
EPF81188ARC240-6	EPF81188AQC240-4*	EPF8636AGC192-5	EPF8636AGC192-4
EPF81500AGC280-2A	EPF81500AGC280-2	EPF8636ALC84-5	EPF8636ALC84-4
EPF81500ARC240-2A	EPF81500AQC240-2*	EPF8636AQC160-5	EPF8636AQC160-4
EPF81500ARC304-2A	EPF81500ARC304-2	EPF8636ARC208-5	EPF8636AQC208-4
EPF8282ALC84-2A	EPF8282ALC84-2	EPF8820AGC192-2A	EPF8820AGC192-2
EPF8282ATC100-2A	EPF8282ATC100-2	EPF8820AQC160-2A	EPF8820AQC160-2
		EPF8820ARC208-2A	EPF8820AQC208-2

* Available in January 1997