



## **PRODUCT DISCONTINUANCE NOTIFICATION PDN0402 MAX+PLUS II PRINTED MANUAL**

### **Change Description:**

Altera has discontinued the printed version of the MAX+PLUS® II manual.

### **Reason for Change:**

Customer demand for this product has been extremely limited for an extended period of time. The information included in the MAX+PLUS II software version 10.2 online help system is more up-to-date than the printed content.

### **Products Affected**

PL-MANUAL

### **Replacement Products**

For up-to-date information on MAX+PLUS II software operation, refer to the online help system in version 10.2 of the MAX+PLUS II software or the MAX+PLUS II BASELINE software.

### **Contact:**

Please contact your local Altera® sales representative if you require additional information regarding this discontinuance.