

**PRODUCT DISCONTINUANCE NOTICE  
SELECTED FLEX 8000 ORDERING CODES**

In November of 1995, Altera announced in PDN9512 that it would be discontinuing selected FLEX 8000 ordering codes and substituting them with compatible FLEX 8000A alternatives. In keeping with this strategy, we are now adding additional devices as candidates for substitution in the FLEX 8000 family of products.

Altera will be discontinuing FLEX 8000 ordering codes (shown in Table 1) in mid-1996. FLEX 8000A alternatives are currently available and offer the added benefit of lower prices. The schedule for phase-out is:

Date for last order acceptance:        May 31, 1996  
Date for last Altera shipments:        August 30, 1996

**Table 1  
Discontinued FLEX 8000 Ordering Codes  
and Their FLEX 8000A Alternatives**

<b>Discontinued Ordering Code</b>	<b>Compatible Substitute</b>
EPF81188GC232-2	EPF81188AGC232-4
EPF81188GC232-3	EPF81188AGC232-4
EPF81188GI232-3	C.F.
EPF81188RC240-2	EPF81188ARC240-4
EPF81188RC240-3	EPF81188ARC240-4
EPF81188RI240-3	EPF81188ARI240-4
EPF81500GC280-2	EPF81500AGC280-4
EPF81500GC280-3	EPF81500AGC280-4
EPF81500RC304-2	EPF81500ARC304-4
EPF81500RC304-3	EPF81500ARC304-4
EPF8282LC84-2	EPF8282ALC84-4
EPF8282LC84-3	EPF8282ALC84-4
EPF8282LI84-3	EPF8282ALI84-4
EPF8282TC100-2	EPF8282ATC100-4
EPF8282TC100-3	EPF8282ATC100-4

EPF8282VLC84-3	EPF8282AVLC84-4
EPF8282VLC84-4	EPF8282AVLC84-4
EPF8282VTC100-3	EPF8282AVTC100-4
EPF8282VTC100-4	EPF8282AVTC100-4
EPF8452LC84-2	EPF8452ALC84-4
EPF8452LC84-3	EPF8452ALC84-4
EPF8452LI84-3	EPF8452ALI84-4
EPF8452QC160-2	EPF8452AQC160-4
EPF8452QC160-3	EPF8452AQC160-4
EPF8820GI192-3	C.F.
EPF8820RC208-2	EPF8820ARC208-4
EPF8820RC208-3	EPF8820ARC208-4
EPF8820RI208-3	EPF8820ARI208-4

**C.F. - Call Factory**

Please contact your local Altera Sales Representative if you require additional information, or assistance, regarding the changes described in this PDN.